

Network OS

Message Reference

Supporting Network OS v3.0.0

BROCADE

Copyright @ 2010-2012 Brocade Communications Systems, Inc. All Rights Reserved.

Brocade, Brocade Assurance, the B-wing symbol, BigIron, DCX, Fabric OS, FastIron, MLX, NetIron, SAN Health, ServerIron, TurboIron, VCS, and VDX are registered trademarks, and AnylO, Brocade One, CloudPlex, Effortless Networking, ICX, NET Health, OpenScript, and The Effortless Network are trademarks of Brocade Communications Systems, Inc., in the United States and/or in other countries. Other brands, products, or service names mentioned may be trademarks of their respective owners.

Notice: This document is for informational purposes only and does not set forth any warranty, expressed or implied, concerning any equipment, equipment feature, or service offered or to be offered by Brocade. Brocade reserves the right to make changes to this document at any time, without notice, and assumes no responsibility for its use. This informational document describes features that may not be currently available. Contact a Brocade sales office for information on feature and product availability. Export of technical data contained in this document may require an export license from the United States government.

The authors and Brocade Communications Systems, Inc. shall have no liability or responsibility to any person or entity with respect to any loss, cost, liability, or damages arising from the information contained in this book or the computer programs that accompany it.

The product described by this document may contain "open source" software covered by the GNU General Public License or other open source license agreements. To find out which open source software is included in Brocade products, view the licensing terms applicable to the open source software, and obtain a copy of the programming source code, please visit http://www.brocade.com/support/oscd.

Brocade Communications Systems, Incorporated

Corporate and Latin American Headquarters Brocade Communications Systems, Inc. 130 Holger Way

San Jose, CA 95134 Tel: 1-408-333-8000 Fax: 1-408-333-8101 E-mail: info@brocade.com

European Headquarters
Brocade Communications Switzerland Sàrl
Centre Swissair
Tour B - 4ème étage
29, Route de l'Aéroport
Case Postale 105
CH-1215 Genève 15
Switzerland

Tel: +41 22 799 5640 Fax: +41 22 799 5641

E-mail: emea-info@brocade.com

Asia-Pacific Headquarters

Brocade Communications Systems China HK, Ltd.

No. 1 Guanghua Road Chao Yang District Units 2718 and 2818 Beijing 100020, China Tel: +8610 6588 8888 Fax: +8610 6588 9999 E-mail: china-info@brocade.com

Asia-Pacific Headquarters

Brocade Communications Systems Co., Ltd. (Shenzhen WFOE)

Citic Plaza

No. 233 Tian He Road North Unit 1308 - 13th Floor Guangzhou, China Tel: +8620 3891 2000 Fax: +8620 3891 2111

E-mail: china-info@brocade.com

Document History

Title	Publication number	Summary of changes	Date
Network OS Message Reference	53-1002082-01	New document	December 2010
Network OS Message Reference	53-1002341-01	Updated for Network OS v2.1.0: Added new chapters: DCM, DOT1, FW, IGMP, L2SS, L3SS, PHP, PLAT, SS, VC, and VCS. Added new messages: EM, FABR, FCOE, FVCS, HAM, HIL, LOG, MSTP, NSM, ONMD, PORT, RAS, RTWR, SEC, SFLO, SNMP, SSMD, SULB, and ZONE. Deleted messages: CEE CONFIG, EANV, FABR, FVCS, HSL, LACP, MFIC, NSM, PORT, and TOAM.	September 2011

Title	Publication number	Summary of changes	Date
Network OS Message Reference	53-1002489-01	 Updated for Network OS v2.1.1: Added new chapters: AUTH, C2, ELD, RCS, and TS. Added new messages: L2SS, PORT, SEC, and SSMD. Modified messages: L2SS, SEC, and ZONE. 	December 2011
Network OS Message Reference	53-1002559-01	Updated for Network OS v3.0.0: Added new chapters: BL, BLL, C3, CHS, ERCP, ESS, FABS, FCMC, FCPH, FLOD, FSPF, FSS, HASM, HAWK, HLO, KTRC, L2AG, LSDB, MCAST_SS, MPTH, MS, NBFS, NS, OSPF, PDM, RTM, SCN, SLCD, SWCH, UCST, UPTH, VRRP, and WLV. Added new messages: AUTH, C2, DCM, EM, FABR, FVCS, FW, HIL, IPAD, L2SS, MSTP, NSM, ONMD, Modified messages: DOT1, EANV, ELD, FCOE, HSL, IGMP, LOG, MSTP, NSM, ONMD, PHP, PLAT, PORT, RAS, RCS, RTWR, SEC, SFLO, SNMP, SS, SSMD, SULB, TOAM, TRCE, TS, VC, VCS, and ZONE.	September 2012

Contents

About This Document

	How this document is organized	ix
	Supported hardware and software	>
	What's new in this document	>
	Document conventions	xi
	Text formatting	xii
	Command syntax conventions	xiii
	Notes	xiii
	Key terms	xiii
	Notice to the reader	xii
	Additional information	xiv
	Brocade resources	xiv
	Other industry resources	xiv
	Getting technical help	xiv
	Document feedback	X\
Chapter 1	Introduction to RASLog Messages	
	Overview of RASLog messages	1
	RASLog message types	1
	Message severity levels	4
	RASLog message logging	4
	RASLog message logging	
		5
	Configuring the syslog message destinations	5
	Configuring the syslog message destinations	5 5
	Configuring the syslog message destinations. System logging daemon	5 6
	Configuring the syslog message destinations. System logging daemon System console SNMP management station	5 6 7
	Configuring the syslog message destinations. System logging daemon System console SNMP management station Port logs Configuring the SNMP server hosts.	5
	Configuring the syslog message destinations. System logging daemon System console SNMP management station Port logs	5
	Configuring the syslog message destinations. System logging daemon System console SNMP management station Port logs Configuring the SNMP server hosts. Configuring the SNMP (version 1 or version 2c) server host	5 6 7 8 9

	viewing and clearing the RASLog messages	11
	Displaying the RASLog messages	11
	Displaying the messages on an interface module	12
	Clearing the RASLog messages	12
	Viewing and clearing the SYSTEM messages	12
	Viewing and clearing the DCE messages	13
	Displaying the VCS messages	14
	Displaying the FFDC messages	14
	Viewing, clearing, and configuring Audit log messages	14
	Displaying the Audit messages	14
	Clearing the Audit messages	15
	Configuring event auditing	15
	Understanding the RASLog messages	16
	RASLog messages	16
	Audit event messages	17
	Responding to a RASLog message	18
	Looking up a message	18
	Gathering information about the problem	18
	Support	19
	System module descriptions	20
Chapter 2	Log Messages	
Chapter 3	DCE Messages	
Chapter 4	FFDC Messages	
Chapter 5	Audit Messages	
Chapter 6	VCS Messages	
Chapter 7	Network OS Messages	
	AUTH Messages	63
	BL Messages	77
	BLL Messages	91
	C2 Messages	92
	C3 Messages	95
	CHS Messages	98
	DCM Messages	.100

DOT1 Messages	113
EANV Messages	118
ELD Messages	120
EM Messages	121
ERCP Messages	136
ESS Messages	137
FABR Messages	138
FABS Messages	144
FCMC Messages	149
FCOE Messages	150
FCPH Messages	155
FLOD Messages	156
FSPF Messages	158
FSS Messages	161
FVCS Messages	165
FW Messages	171
HASM Messages	198
HAWK Messages	209
HIL Messages	210
HLO Messages	215
HSL Messages	217
IGMP Messages	219
IPAD Messages	221
KTRC Messages	223
L2AG Messages	225
L2SS Messages	228
LOG Messages	232
LSDB Messages	235
MCAST_SS Messages	237
MPTH Messages	244
MS Messages	245
MSTP Messages	246
NBFS Messages	250
NS Messages	252
NSM Messages	253
ONMD Messages	275
OSPF Messages	277

PDM Messages278
PHP Messages
PLAT Messages
PORT Messages
RAS Messages
RCS Messages
RTM Messages
RTWR Messages301
SCN Messages
SEC Messages
SFLO Messages
SLCD Messages
SNMP Messages
SS Messages
SSMD Messages
SULB Messages
SWCH Messages379
TOAM Messages
TRCE Messages
TS Messages
UCST Messages
UPTH Messages
VC Messages
VCS Messages
VRRP Messages
WLV Messages
ZONE Messages

About This Document

In this chapter

How this document is organized
Supported hardware and software
What's new in this document
• Document conventions
• Notice to the reader
• Additional information
• Getting technical help
• Document feedback

How this document is organized

This document supports Brocade Network OS v3.0.0 and documents RASLog messages that can help you diagnose and fix problems with a switch or network. The guide is organized alphabetically by module name. A *module* is a subsystem in the Network OS. Each module generates a set of numbered messages. For each message, this guide provides message text, message type, severity level, probable cause, and recommended action. There may be more than one cause and more than one recommended action for any given message. This guide discusses the most probable cause and typical action recommended.

This document is organized to help you find the information that you want as quickly and easily as possible. The document contains the following components:

- Chapter 1, "Introduction to RASLog Messages" provides basic information on RASLog messages.
- Chapter 2, "Log Messages" includes a lookup list for LOG messages.
- Chapter 3, "DCE Messages" includes a lookup list for DCE messages.
- Chapter 4, "FFDC Messages" includes a lookup list for FFDC messages.
- Chapter 5, "Audit Messages" includes a lookup list for Audit messages.
- Chapter 6, "VCS Messages" includes a lookup list for VCS messages.
- Chapter 7, "Network OS Messages" provide message text, probable cause, recommended action, and severity for each of the messages.

Supported hardware and software

In those instances in which procedures or parts of procedures documented here apply to some switches but not to others, this guide identifies exactly which switches are supported and which are not.

Although many different software and hardware configurations are tested and supported by Brocade Communications Systems, Inc. for Network OS v3.0.0, documenting all possible configurations and scenarios is beyond the scope of this document.

The following hardware platforms are supported by this release of Network OS:

- Brocade VDX 6710-54
- Brocade VDX 6720
 - Brocade VDX 6720-24
 - Brocade VDX 6720-60
- Brocade VDX 6730
 - Brocade VDX 6730-32
 - Brocade VDX 6730-76
- Brocade VDX 8770
 - Brocade VDX 8770-4
 - Brocade VDX 8770-8

What's new in this document

The following changes have been made since this document was last released:

- The lookup lists in Chapter 2 through Chapter 6 provide hyperlinks to messages by type (LOG, DCE, VCS, FFDC, and Audit).
- Information that was added:
 - BL Messages
 - BLL Messages
 - C3 Messages
 - CHS Messages
 - ERCP Messages
 - ESS Messages
 - FABS Messages
 - FCMC Messages
 - FCPH Messages
 - FLOD Messages
 - FSPF Messages
 - FSS Messages
 - HASM Messages

- HAWK Messages
- HLO Messages
- KTRC Messages
- L2AG Messages
- LSDB Messages
- MCAST_SS Messages
- MPTH Messages
- MS Messages
- NBFS Messages
- NS Messages
- OSPF Messages
- PDM Messages
- RTM Messages
- SCN Messages
- SLCD Messages
- SWCH Messages
- UCST Messages
- UPTH Messages
- VRRP Messages
- WLV Messages
- Information that was changed:
 - AUTH Messages
 - C2 Messages
 - DCM Messages
 - DOT1 Messages
 - EANV Messages
 - ELD Messages
 - EM Messages
 - FABR Messages
 - FCOE Messages
 - FVCS Messages
 - FW Messages
 - HIL Messages
 - HSL Messages
 - IGMP Messages
 - IPAD Messages
 - L2SS Messages
 - LOG Messages
 - MSTP Messages

- NSM Messages
- ONMD Messages
- PHP Messages
- PLAT Messages
- PORT Messages
- RAS Messages
- RCS Messages
- RTWR Messages
- SEC Messages
- SFLO Messages
- SNMP Messages
- SS Messages
- SSMD Messages
- SULB Messages
- TOAM Messages
- TRCE Messages
- TS Messages
- VC Messages
- VCS Messages
- ZONE Messages
- Information that was deleted:
 - HAM System Messages
 - L3SS System Messages

Document conventions

This section describes text formatting conventions and important notice formats used in this document.

Text formatting

The narrative-text formatting conventions that are used are as follows:

Identifies the names of user-manipulated GUI elements

Identifies keywords and operands
Identifies text to enter at the GUI or CLI

italic text Provides emphasis

Identifies variables

Identifies paths and Internet addresses

Identifies document titles

Identifies command syntax examples

For readability, command names in the narrative portions of this guide are presented in mixed lettercase; for example, **switchShow**. In actual examples, command lettercase is often all lowercase.

Command syntax conventions

Command syntax in this manual follows these conventions:

commandCommands are printed in bold.variableVariables are printed in italics.

[] Keywords or arguments that appear within square brackets are optional.

{x | y | z } A choice of required keywords appears in braces separated by vertical bars.

You must select one.

screen font Examples of information displayed on the screen.

Non-printing characters, for example, passwords, appear in angle brackets.

NOTE

In standalone mode, interfaces are identified using slot/port notation. In Brocade VCS Fabric technology® mode, interfaces are identified using switch/slot/port notation.

Notes

The following note is used in this manual.

NOTE

A note provides a tip, guidance, or advice, emphasizes important information, or provides a reference to related information.

Key terms

For definitions specific to Brocade and Fibre Channel, see the technical glossaries on MyBrocade. See "Brocade resources" on page xiv for instructions on accessing MyBrocade.

For definitions of SAN-specific terms, visit the Storage Networking Industry Association online dictionary at:

http://www.snia.org/education/dictionary

Notice to the reader

This document may contain references to the trademarks of the following corporations. These trademarks are the properties of their respective companies and corporations.

These references are made for informational purposes only.

Corporation	Referenced trademarks and products
Microsoft Corporation	Windows
Red Hat, Inc.	Red Hat package manager (RPM)

Additional information

This section lists additional Brocade and industry-specific documentation that you might find helpful.

Brocade resources

To get up-to-the-minute information, go to http://my.brocade.com and register at no cost for a user ID and password.

White papers, online demonstrations, and data sheets are available through the Brocade website at:

http://www.brocade.com/products-solutions/products/index.page

For additional Brocade documentation, visit the Brocade website:

http://www.brocade.com

Other industry resources

For additional resource information, visit the Technical Committee T11 website. This website provides interface standards for high-performance and mass storage applications for Fibre Channel, storage management, and other applications:

http://www.t11.org

For information about the Fibre Channel industry, visit the Fibre Channel Industry Association website:

http://www.fibrechannel.org

Getting technical help

Contact your switch support supplier for hardware, firmware, and software support, including product repairs and part ordering. To expedite your call, have the following information available:

- 1. General Information
 - Switch model
 - Switch operating system version
 - Software name and software version, if applicable
 - · Error numbers and messages received
 - copy support command output

- Detailed description of the problem, including the switch or network behavior immediately following the problem, and specific questions
- Description of any troubleshooting steps already performed and the results
- Serial console and Telnet session logs
- syslog message logs

2. Switch Serial Number

The switch serial number and corresponding bar code are provided on the serial number label, as illustrated below.



The serial number label for the Brocade VDX 6710, Brocade VDX 6720, Brocade VDX 6730, and Brocade VDX 8770 is located on the switch ID pull-out tab located on the bottom of the port side of the switch.

Document feedback

Quality is our first concern at Brocade and we have made every effort to ensure the accuracy and completeness of this document. However, if you find an error or an omission, or you think that a topic needs further development, we want to hear from you. Forward your feedback to:

documentation@brocade.com

Provide the title and version number of the document and as much detail as possible about your comment, including the topic heading and page number and your suggestions for improvement.

Introduction to RASLog Messages

In this chapter

Overview of RASLog messages.
• Configuring the syslog message destinations
• Configuring the SNMP server hosts
\bullet Commands for displaying, clearing, and configuring the message logs 10
• Viewing and clearing the RASLog messages
• Viewing, clearing, and configuring Audit log messages
• Understanding the RASLog messages. 16
• Responding to a RASLog message
• System module descriptions

Overview of RASLog messages

RASLog messages log system events related to configuration changes or system error conditions. Messages are reported at various levels of severity ranging informational (INFO) to escalating error levels (WARNING, ERROR, and CRITICAL). Network OS maintains two separate internal message storage repositories, SYSTEM and DCE. Table 1 shows the message types stored in each of the two repositories. A RASLog message can have one or more type attributes. For example, a message can be of type DCE, FFDC, and AUDIT. A message cannot have both LOG and DCE type attributes.

TABLE 1 Message type matrix

Message type	DCE message repository	SYSTEM message repository
LOG	No	Yes
DCE	Yes	No
FFDC	Yes	Yes
VCS	Yes	Yes
AUDIT	Yes	Yes

RASLog message types

Network OS supports five types of RASLog messages. The following sections describe in detail the message types.

System messages

System or LOG messages report significant system-level events or information and are also used to show the status of the high-level user-initiated actions. System messages are stored in a separate nonvolatile storage and are preserved across the firmware upgrade or downgrade. The system messages are forwarded to the console, to the configured syslog servers, and through the SNMP traps or informs to the SNMP management station.

The following is an example of a system message.

```
2011/08/23-22:58:12, [EM-1036], 4,, WARNING, VDX6720-24, Fan 1 is not accessible.
```

For information on displaying and clearing the system messages, refer to "Viewing and clearing the SYSTEM messages" on page 12.

DCE RASLog messages

DCE RASLog messages report error-related events and information in the protocol-based modules such as network service module (NSM), system services manager (SSM), and so on. DCE messages are stored in a separate nonvolatile storage and are preserved across the firmware upgrades. The DCE messages are forwarded to the console, to the configured syslog servers, and through the SNMP traps or informs to the SNMP management station.

NOTE

DCE messages are supported only in Network OS v3.0.0 and later. If you downgrade to an earlier firmware version, the DCE messages will be dropped.

The following is an example of a DCE message.

```
2012/05/30-21:25:55, [ONMD-1002], 59, M1 \mid DCE, INFO, sw0, LLDP global configuration is changed.
```

For information on displaying and clearing the DCE RASLog messages, refer to "Viewing and clearing the DCE messages" on page 13.

VCS RASLog messages

VCS RASLog messages are supported in VCS fabrics only. The VCS RASLog messages are used to indicate events such as node removal and node join from the Brocade VCS fabric. When a switch generates a VCS RASLog message, it is forwarded to the system console, remote syslog, and SNMP management station.

The following is an example of a VCS RASLog message.

```
2011/08/26-12:40:01, [VCS-1003], 7013/3454, VCS, INFO, VDX6720-60, Event: VCS node add, Coordinator IP: 10.17.10.31, VCS ID: 1, Status: rBridge ID 1 (10.17.10.32) added to VCS cluster., VcsFabAddRejoin, line: 1450, comp:dcmd, ltime:2011/06/27-02:47:04:555942.
```

You can display the VCS RASLog messages using the **show logging raslog attribute VCS** command. For information on displaying the VCS RASLog messages, refer to "Displaying the VCS messages" on page 14.

Audit log messages

Event auditing is designed to support post-event audits and problem determination based on high-frequency events of certain types, such as security violations, firmware downloads, and configuration. Audit log messages are saved in the persistent storage. The storage has a limit of 1024 entries and will wrap around if the number of messages exceed the limit. The switch can be configured to stream Audit messages to the specified syslog servers. The Audit log messages are not forwarded to an SNMP management station.

The following is an example of an Audit log message.

```
AUDIT,2011/08/26-07:51:32 (GMT), [DCM-2001], INFO, DCMCFG, root/none/127.0.0.1/rpc/cli,, VDX6720-24, Event: noscli start, Status: success, Info: Successful login attempt through console from 127.0.0.1.
```

For any given event, Audit messages capture the following information:

- User Name The name of the user who triggered the action.
- User Role The access level of the user, such as root or admin.
- Event Name The name of the event that occurred.
- Status The status of the event that occurred: success or failure.
- Event Info Information about the event.

The three event classes described in Table 2 can be audited.

TABLE 2 Event classes of the Audit messages

Event class	Operand	Description
DCMCFG	CONFIGURATION	You can audit all the configuration changes in the Network OS.
FIRMWARE	FIRMWARE	You can audit the events occurring during the firmware download process.
SECURITY	SECURITY	You can audit any user-initiated security event for all management interfaces. For events that have an impact on the entire network, an audit is generated only for the switch from which the event was initiated.

You can enable event auditing by configuring the syslog daemon to send the events to a configured remote host using the **logging syslog-server** command. You can set up filters to screen out particular classes of events using the **logging auditlog class** command (the classes include SECURITY, CONFIGURATION, and FIRMWARE). All the Audit classes are enabled by default. The defined set of Audit messages are sent to the configured remote host in the Audit message format, so that they are easily distinguishable from other syslog events that may occur in the network. For details on how to configure event auditing, refer to "Configuring event auditing" on page 15.

FFDC messages

First Failure Data Capture (FFDC) is used to capture failure-specific data when a problem or failure is first noted and before the switch reloads or the trace and log buffer get wrapped. All subsequent iterations of the same error are ignored. This critical debug information is saved in nonvolatile storage and can be retrieved by executing the **copy support** command. The data are used for debugging purposes. FFDC is intended for use by Brocade technical support.

FFDC is enabled by default. Execute the **support** command to enable or disable FFDC. If FFDC is disabled, the FFDC daemon does not capture any data, even when a message with FFDC attributes is logged.

The following is an example of an FFDC message.

2011/08/26-12:39:02, [HAM-1007], 2, FFDC, CRITICAL, VDX6720-24, Need to reboot the system for recovery, reason: raslog-test-string0123456-raslog.

You can display the FFDC messages using the **show logging raslog attribute FFDC** command. For information on displaying the FFDC RASLog messages, refer to "Displaying the FFDC messages" on page 14.

Message severity levels

There are four levels of severity for messages, ranging from CRITICAL to INFO. In general, the definitions are wide ranging and are to be used as general guidelines for troubleshooting. In all cases, you must look at each specific error message description thoroughly before taking action. Table 3 lists the RASLog message severity levels.

TABLE 3 Severity levels of the RASLog messages

Severity level	Description
CRITICAL	Critical-level messages indicate that the software has detected serious problems that cause a partial or complete failure of a subsystem if not corrected immediately; for example, a power supply failure or rise in temperature must receive immediate attention.
ERROR	Error-level messages represent an error condition that does not affect overall system functionality significantly. For example, error-level messages may indicate time outs on certain operations, failures of certain operations after retries, invalid parameters, or failure to perform a requested operation.
WARNING	Warning-level messages highlight a current operating condition that must be checked or it may lead to a failure in the future. For example, a power supply failure in a redundant system relay a warning that the system is no longer operating in redundant mode unless the failed power supply is replaced or fixed.
INFO	Info-level messages report the current non-error status of the system components; for example, detecting online and offline status of an interface.

RASLog message logging

The RASLog service generates and stores messages related to abnormal or erroneous system behavior. It includes the following features:

- SYSTEM and DCE messages are saved to separate nonvolatile storage repositories.
- SYSTEM and DCE message logs can save a maximum of 4096 messages.
- The message log is implemented as a circular buffer. When more than the maximum entries
 are added to the log file, new entries overwrite the old entries.
- Messages are numbered sequentially from 1 through 2,147,483,647 (0x7ffffff). The sequence
 number continues to increase after the message log wraps around. The message sequence
 numbering is not split for the system and DCE message logs. The sequence number can be
 reset to 1 using the clear logging raslog command. However, the sequence number is not reset
 to 1 if you clear a particular message type, for example: DCE.
- Trace dump, FFDC, and core dump files can be uploaded to the FTP server using the copy support ftp command.
- Brocade recommends that you configure the system logging daemon (syslogd) facility as a management tool for error logs. For more information, refer to "System logging daemon" on page 5.

Configuring the syslog message destinations

You can configure a switch to send the syslog messages to the following output locations: syslog daemon, system console, and SNMP management station.

System logging daemon

The system logging daemon (syslogd) is a process on UNIX, Linux, and some Windows systems that reads and logs messages as specified by the system administrator.

Network OS can be configured to use a UNIX-style syslogd process to forward system events and error messages to log files on a remote host system. The host system can be running UNIX, Linux, or any other operating system that supports the standard syslogd functionality. All the RASLog messages are forwarded to the syslogd. Configuring for syslogd involves configuring the host, enabling syslogd on the Brocade model, and optionally, setting the facility level.

Configuring a syslog server

To configure the switch to forward all RASLog messages to the syslogd of one or more servers, perform the following steps.

1. Execute the configure terminal command to access the global configuration level of the CLI.

```
switch# configure terminal
Entering configuration mode terminal
```

Execute the logging syslog-server IP address command to add a server to which the messages
are forwarded. You can configure a syslog server in both IPv4 or IPv6 format. The following
example is for configuring a syslog server with IPv4 address.

```
switch(config)# logging syslog-server 192.0.2.2
```

You can configure up to four syslog servers to receive the syslog messages.

3. Execute the **show running-config logging syslog-server** command to verify the syslog configuration on the switch.

```
switch# show running-config logging syslog-server
logging syslog-server 192.0.2.2
```

The following example configures a syslog server with an IPv6 address.

```
switch# configure terminal
Entering configuration mode terminal
switch(config)# logging syslog-server 2001:DB8::32
switch(config)# exit
switch# show running-config logging syslog-server
logging syslog-server 2001:db8::32
```

You can remove a configured syslog server using the no logging syslog-server IP address command.

Setting the syslog facility

The syslog facility is a configurable parameter that specifies the log file to which messages are forwarded. You must configure the syslog servers to receive system messages before you can configure the syslog facility.

To set the syslog facility, perform the following steps.

1. Execute the configure terminal command to access the global configuration level of the CLI.

```
switch# configure terminal
Entering configuration mode terminal
```

2. Execute the **logging syslog-facility local** *log_level* command set the syslog facility to a specified log file.

The *log_level* specifies the syslog facility and can be a value from LOG_LOCALO through LOG_LOCAL7. The default syslog level is LOG_LOCAL7. The following example is for setting the syslog facility level to LOG_LOCAL2.

```
switch(config)# logging syslog-facility local LOG_LOCAL2
```

3. Execute the **show running-config logging syslog-facility** command to verify the syslog facility configuration on the switch.

```
switch# show running-config logging syslog-facility
logging syslog-facility local LOG_LOCAL2
```

You can reset the syslog facility to the default (LOG_LOCAL7) using the **no logging syslog-facility local** command.

System console

The system console displays all RASLog messages, Audit messages (if enabled), and panic dump messages. These messages are mirrored to the system console; they are always saved in one of the message logs.

The system console displays messages only through the serial port. If you log in to a switch through the Ethernet port or modem port, you will not receive system console messages.

You can filter messages that display on the system console by severity using the **logging raslog console** command. All messages are still sent to the system message log, syslog (if enabled), and SNMP management station.

Setting the RASLog console severity level

You can limit the types of messages that are logged to the console using the **logging raslog console** command. The RASLog messages displayed on the console are passed up to and above the configured severity level. For example, if you configure the console severity level to ERROR, then only ERROR and CRITICAL messages pass through. You can choose one of the following severity levels: INFO, WARNING, ERROR, or CRITICAL. The default severity level is INFO.

To set the severity levels for the RASLog console, perform the following steps.

1. Execute the configure terminal command to access the global configuration level of the CLI.

```
switch# configure terminal
Entering configuration mode terminal
```

2. Execute the **logging rbridge-id** *rbridge-id* **raslog console** severity level command to set the RASLog console severity level.

The severity level can be one of the following: WARNING, ERROR, or CRITICAL. The severity level values are case-sensitive. For example, to set the console severity level to ERROR on switch 1, enter the following command.

switch(config)# logging rbridge-id 1 raslog console ERROR

3. Execute the copy running-config startup-config command to save the configuration changes.

You can reset the console severity level to the default (INFO) using the **no logging rbridge-id** *rbridge-id* **raslog console** command.

SNMP management station

When an unusual event, error, or a status change occurs on the device, an event notification is sent to the SNMP management station. Network OS v3.0.0 supports two types of event notifications: traps (in SNMPv1, SNMPv2c, and SNMPv3) and informs (in SNMPv3).

SNMP traps

An unsolicited message that comes to the management station from the SNMP agent on the device is called a *trap*. When an event occurs and if the event severity level is at or below the set severity level, the SNMP trap, swEventTrap, is sent to the configured trap recipients. The VarBind in the Trap Data Unit contains the corresponding instance of the event index, time information, event severity level, the repeat count, and description. The possible severity levels are as follows:

- Critical
- Debug
- Error
- Info
- None
- Warning

By default, the severity level is set to None, implying all traps are filtered and therefore no event traps are received. When the severity level is set to Info, all traps with the severity level of Info, Warning, Error, and Critical are received.

NOTE

The Audit log messages are not converted into swEventTrap.

The SNMP traps are unreliable because the trap recipient does not send any acknowledgment when it receives a trap. Therefore, the SNMP agent cannot determine if the trap was received.

Brocade switches send traps out on UDP port 162. To receive traps, the management station IP address must be configured on the switch. You can configure the SNMPv1, SNMPv2c, and SNMPv3 hosts to receive the traps. For more information, refer to "Configuring the SNMP (version 1 or version 2c) server host" on page 9.

SNMP informs

An SNMP inform is similar to the SNMP trap except that the management station that receives an SNMP inform acknowledges the system message with an SNMP response PDU. If the sender does not receive the SNMP response, the SNMP inform request can be sent again. An SNMP inform request is saved in the switch memory until a response is received or the request times out. The SNMP informs are more reliable and they consume more resources in the device and in the network. Use SNMP informs only if it is important that the management station receives all event notifications. Otherwise, use the SNMP traps.

Brocade devices support SNMPv3 informs. For more information, refer to "Configuring the SNMPv3 server" on page 9.

Port logs

The Network OS maintains an internal log of all port activity. Each switch maintains a log file for each port. Port logs are circular buffers that can save up to 8,000 entries per switch. When the log is full, the newest log entries overwrite the oldest log entries. Port logs capture switch-to-device, device-to-switch, switch-to-switch, some device A-to-device B, and control information. Port logs are not persistent and are lost across power cycles and reboots.

Port log functionality is completely separate from the system message log. Port logs are typically used to troubleshoot device connections.

Configuring the SNMP server hosts

Network OS v3.0.0 supports SNMP version 1, version 2c, and version 3. Use the commands listed in Table 4 to configure the SNMPv1, SNMPv2c, and SNMPv3 hosts and their configurations.

TABLE 4 Commands for configuring SNMP server hosts

Command	Description
[no] snmp-server host {ipv4 host ipv6-host dns} community-string [severity-level [None	This command sets the destination IP addresses, version, community string (for version 1 and version 2c), and destination port for the traps.
Debug Info Warning Error Critical] [udp-port port_number] [version [1 2c]	The severity-level option is used to filter the traps based on severity. The no form of the command changes the SNMP server host configurations to the default value.
[no] snmp-server v3host {ipv4-host ipv6-host dns} username [notifytype {traps informs}] engineid engine-id severity-level [None Debug Info Warning Error Critical] udp-port port_number	This command specifies the recipient of the SNMP version 3 notification option. The severity-level option is used to filter the traps or informs based on severity. Use the no form of the command to remove the specified host.

Configuring the SNMP (version 1 or version 2c) server host

To set the trap destination IP addresses, version (1 or 2c), community string for SNMP version 1 and version 2c, and the destination port for the SNMP traps, perform the following steps.

1. Execute the configure terminal command to access the global configuration level of the CLI.

```
switch# configure terminal
Entering configuration mode terminal
```

2. Execute the following command to set the trap recipient with IP address 192.0.2.2, which receives all traps with the severity levels of Critical, Error, Info, and Warning.

```
switch(config)# snmp-server host 192.0.2.2 public severity-level Info udp-port
162 version 1
```

NOTE

To receive the traps, the management station IP address must be configured on the switch.

3. Execute the do show running-config snmp-server command to verify the configuration.

```
switch(config)# do show running-config snmp-server snmp-server contact "Field Support." snmp-server location "End User Premise." snmp-server sys-descr "Brocade VDX Switch." snmp-server community ConvergedNetwork snmp-server community OrigEquipMfr rw snmp-server community "Secret COde" rw snmp-server community common snmp-server community private rw snmp-server community public snmp-server host 192.0.2.2 public udp-port 162 severity-level Info
```

Configuring the SNMPv3 server

Use the **snmp-server v3-host** command to specify the recipient of SNMP version 3 notifications: traps or informs. The following example explains the procedure to configure the recipient of the SNMPv3 informs.

To configure the SNMPv3 host to receive the inform, perform the following steps.

1. Execute the configure terminal command to access the global configuration level of the CLI.

```
switch# configure terminal
Entering configuration mode terminal
```

2. Execute the following command to set the inform recipient with IP address 192.0.2.2, which receives all traps with the severity levels of Critical, Error, Info, and Warning.

```
switch(config)# snmp-server v3host 192.0.2.2 snmpadmin1 notifytype informs
engineid 80:00:05:23:01:AC:1A:01:79 severity-level Info udp-port 4425
```

NOTE

To receive the SNMP informs, the username, the authentication protocol, the privacy protocol, the UDP port number, and the engine ID must match between the switch and the management station.

3. Execute the **show running-config snmp-server** command to verify the configuration.

```
switch# show running-config snmp-server
snmp-server contact "Field Support."
snmp-server location "End User Premise."
snmp-server sys-descr "Brocade VDX Switch."
snmp-server community ConvergedNetwork
snmp-server community OrigEquipMfr rw
snmp-server community "Secret COde" rw
snmp-server community common
snmp-server community private rw
snmp-server community public
snmp-server user snmpadmin1 groupname snmpadmin auth md5 auth-password * priv
DES priv-password *
snmp-server user snmpadmin2 groupname snmpadmin auth-password * priv-password
snmp-server user snmpadmin3 groupname snmpadmin auth-password * priv-password
snmp-server user snmpuser1 auth-password * priv-password *
snmp-server user snmpuser2 auth-password * priv-password *
snmp-server user snmpuser3 auth-password * priv-password *
snmp-server v3host 192.0.2.2 snmpadmin1
udp-port 4425
notifytype informs
engineid 80:00:05:23:01:AC:1A:01:79
severity-level Info
```

Commands for displaying, clearing, and configuring the message logs

Table 5 describes commands that you can use to view or configure various message logs. Most commands require the admin access level. For detailed information on required access levels and commands, refer to the *Network OS Command Reference*.

TABLE 5 Commands for viewing or configuring the message logs

Command	Description
clear logging auditlog	This command clears the Audit log messages from the local switch or the specified switches.
clear logging raslog	This command clears the error log messages from the local switch or the specified switches.
logging auditlog class	This command sets the event classes for Audit log messages.
logging raslog console	This command sets a filter based on the severity level for the messages to be displayed on the system console.
logging syslog-facility local	This command sets the syslog facility.
logging syslog-server	This command configures a syslog server to which the switch can forward the messages.
show logging auditlog	This command displays the Audit log messages on the local switch or the specified switches.
show logging raslog	This command displays the error log message on the local switch, the specified switch, or interface module. The command includes options to filter the messages based on the message attribute and the severity level, and also to set the count of messages to display, and to display messages in reverse order.

TABLE 5	Commands for viewing or configuring the message logs (Continued)	

Command	Description
show running-config logging	This command is used to display the logging settings on the local switch.
show running-config logging auditlog class	This command displays the event class configured for the audit log.
show running-config logging raslog	This command displays the RASLog console severity level on the local switch or the specified switch.
show running-config logging syslog-facility	This command displays the syslog facility level.

Viewing and clearing the RASLog messages

You can display system messages using the **show logging raslog** command. This command provides options to filter the messages by attribute, message type, severity, or message count. You can also specify to display messages for a single module by using the **blade** option. Use the **clear logging raslog** command to delete the system messages.

Displaying the RASLog messages

To display the saved RASLog messages, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the **show logging raslog** command at the command line.

```
switch# show logging raslog
NOS: v3.0.0
2012/06/04-22:57:00, [HASM-1108], 94,, INFO, VDX6720-24, All service instances
become active.
2012/06/04-22:57:03, [DCM-1002], 96,, INFO, VDX6720-24, PostBoot processing on
global config has started.
2012/06/04-22:57:05, [BL-1000], 100,, INFO, VDX6720-24, Initializing ports...
2012/06/13-05:10:22, [NSM-1004], 4428, DCE, INFO, sw0, Interface Vlan 1 is
created.
2012/06/13-05:10:24, [DOT1-1013], 4435, DCE, INFO, sw0, DOT1X test timeout
value is set to 10.
2012/06/13-05:10:24, [ONMD-1002], 4437, DCE, INFO, sw0, LLDP global
configuration is changed.
2012/06/13-05:10:28, [RAS-2001], 4438,, INFO, sw0, Audit message log is
enabled.
[...]
```

Displaying the messages on an interface module

To display the saved messages for a specific interface module, line card (LC), or management module, perform the following steps.

- 1. Log in to the switch as admin.
- Enter the show logging raslog blade command at the command line. You can filter messages
 based on the severity leve using the severity option. The following example filters messages by
 the severity level of info.

```
switch# show logging raslog blade LC2 severity info
NOS: 3.0.0
2012/05/29-11:43:06, [HASM-1004], 6919, L2, INFO, VDX8770-4, Processor
rebooted - Reset.
2012/05/29-11:43:06, [HASM-1104], 6920, L2, INFO, VDX8770-4, Heartbeat to M2
up.
2012/05/29-11:43:10, [HASM-1004], 6921, L2, INFO, VDX8770-4, Processor
rebooted - Reset.
2012/05/29-11:43:10, [HASM-1104], 6922, L2, INFO, VDX8770-4, Heartbeat to M2
up.
[...]
```

Clearing the RASLog messages

To clear the RASLog messages for a particular switch instance, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Execute the **clear logging rasiog** command to clear all messages from the switch.

Viewing and clearing the SYSTEM messages

This section provides information on viewing and clearing the SYSTEM messages saved on the switch memory.

Displaying the SYSTEM messages

To display the messages saved in the SYSTEM storage repository, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the **show logging raslog message-type SYSTEM** command at the command line.

```
switch# show logging raslog message-type SYSTEM
NOS: v3.0.0

2011/09/14-04:52:05, [LOG-1003], 1,, INFO, VDX6720-60, SYSTEM error log has been cleared.

2011/09/14-04:56:18, [DCM-1101], 2,, INFO, VDX6720-60, Copy running-config to startup-config operation successful on this node.

2011/09/14-05:05:21, [RAS-1007], 5,, INFO, VDX6720-60, System is about to reboot.
[...]
```

Clearing the SYSTEM messages

To clear the messages saved in the SYSTEM storage repository, perform the following steps.

- 1. Log in to the switch as admin.
- Execute the clear logging raslog message-type SYSTEM command to clear all system messages from the local switch.

Viewing and clearing the DCE messages

This section provides information on viewing and clearing the DCE messages saved on the switch memory.

Displaying the DCE messages

To display the saved DCE messages, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the show logging raslog message-type DCE command at the command line.

```
switch# show logging raslog message-type DCE
NOS: 3.0.0
2012/05/30-21:25:34, [NSM-1004], 41, M1 | DCE, INFO, switch, Interface Vlan
4093 is created.
2012/05/30-21:25:34, [NSM-1019], 42, M1 | DCE, INFO, switch, Interface Vlan
4093 is administratively up.
2012/05/30-21:25:52, [DOT1-1013], 50, M1 | DCE, INFO, switch, DOT1X test
timeout has set to 10.
2012/05/30-21:25:52, [ONMD-1002], 59, M1 | DCE, INFO, switch, LLDP global
configuration is changed.
2012/05/30-21:25:53, [SSMD-1602], 63, M1 | DCE, INFO, switch, Class map
default is created.
2012/05/30-21:25:55, [NSM-1004], 58, M1 | DCE, INFO, switch, Interface Vlan
1002 is created.
2012/05/30-21:25:55, [ONMD-1002], 59, M1 | DCE, INFO, switch, LLDP global
configuration is changed.
2012/05/30-21:25:59, [SSMD-1602], 63, M1 | DCE, INFO, switch, Class map
default is created
[...]
```

Clearing the DCE messages

To clear the DCE messages for a particular switch instance, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Execute the **clear logging raslog message-type DCE** command to clear all DCE messages from the local switch.

Displaying the VCS messages

This section provides information on viewing the VCS messages saved on the switch memory.

To display the saved DCE messages, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the show logging raslog attribute VCS command at the command line.

```
switch# show logging raslog attribute VCS
NOS: 3.0.0
2012/06/05-03:00:18:101601, [VCS-1009], 8002/3929, VCS, INFO, VDX6720-60,
Event: VCS node disconnect, Coordinator IP: 192.0.2.15, VCS Id: 1, Status:
Rbridge-id 3 (192.0.2.2) disconnected from VCS cluster.

2012/06/05-03:04:11:621996, [VCS-1005], 8051/3935, VCS, INFO, VDX6720-60,
Event: VCS node rejoin, Coordinator IP: 192.0.2.15, VCS Id: 1, Status:
Rbridge-id 3 (192.0.2.2) rejoined VCS cluster.

[...]
```

Displaying the FFDC messages

This section provides information on viewing the FFDC messages saved on the switch memory. To display the saved DCE messages, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the **show logging raslog attribute FFDC** command at the command line.

```
switch# show logging raslog attribute FFDC
NOS: 3.0.0
2012/06/15-10:39:02, [LOG-1002], 4496, FFDC, WARNING, VDX6720-24, A log
message was not recorded.

2012/06/15-10:39:18, [RAS-1001], 4496, FFDC, WARNING, VDX6720-24, First
failure data capture (FFDC) event occurred.
[...]
```

Viewing, clearing, and configuring Audit log messages

This section provides information on viewing, clearing, and configuring the Audit log messages.

Displaying the Audit messages

To display the saved Audit messages, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Enter the **show logging auditlog** command at the command line.

You can also display messages in revere order using the reverse option.

```
switch# show logging auditlog

0 AUDIT,2011/08/26-07:51:29 (GMT), [RAS-2001], INFO, SYSTEM,
NONE/root/NONE/None/CLI,, switch, Audit message log is enabled.
```

```
1 AUDIT,2011/08/26-07:51:29 (GMT), [RAS-2003], INFO, SYSTEM,
NONE/root/NONE/None/CLI,, switch, Audit message class configuration has been changed to 2,6,4..

2 AUDIT,2011/08/26-07:51:32 (GMT), [DCM-2001], INFO, DCMCFG,
root/none/127.0.0.1/rpc/cli,, VDX6720-24, Event: noscli start, Status:
success, Info: Successful login attempt through console from 127.0.0.1.

3 AUDIT,2011/08/26-07:51:34 (GMT), [DCM-2001], INFO, DCMCFG,
admin/admin/127.0.0.1/rpc/cli,, VDX6720-24, Event: noscli start, Status:
success, Info: Successful login attempt through console from 127.0.0.1.

4 AUDIT,2011/08/26-07:51:36 (GMT), [DCM-2002], INFO, DCMCFG,
admin/admin/127.0.0.1/rpc/cli,, VDX6720-24, Event: noscli exit, Status:
success, Info: Successful logout by user [admin].
[...]
```

Clearing the Audit messages

To clear the Audit log messages for a particular switch instance, perform the following steps.

- 1. Log in to the switch as admin.
- 2. Execute the clear logging auditlog command to clear all messages on the switch memory.

Configuring event auditing

The Audit log classes SECURITY, CONFIGURATION, and FIRMWARE are enabled by default. You can enable or disable auditing of these classes using the **logging auditlog class** class command.

To configure and verify the event auditing, perform the following steps.

1. Execute the configure terminal command to access the global configuration level of the CLI.

```
switch# configure terminal
Entering configuration mode terminal
```

2. Configure the event classes you want to audit. For example, to audit the CONFIGURATON class, execute the following command.

You can choose one of the following event classes: CONFIGURATION, FIRMWARE, or SECURITY.

```
switch(config)# logging auditlog class CONFIGURATION
```

3. Execute the show running-config logging auditlog class command to verify the configuration.

```
switch# show running-config logging auditlog class
logging auditlog class CONFIGURATION
```

Understanding the RASLog messages

This section provides information about reading the RASLog messages.

RASLog messages

The following example shows the format of a RASLog message.

<Timestamp>, [<Event ID>], <Sequence Number>, <Flags>,<Severity>,<Switch name>, <Event-specific information>

The following example shows the sample messages from the error log.

2011/08/23-22:58:10, [IPAD-1000], 2,, INFO, VDX6720-24, SW/0 Ether/0 IPv4 DHCP 10.24.95.252/20 DHCP On.

2012/05/30-21:26:00, [FCOE-1035], 67, M1 | DCE, INFO, sw0, Virtual FCoE port 1/1/4 is online.

2011/08/26-12:39:02, [HAM-1007], 2, FFDC, CRITICAL, VDX6720-24, Need to reboot the system for recovery, reason: raslog-test-string0123456-raslog.

2011/08/26-12:40:01, [VCS-1003], 7013/3454, VCS, INFO, VDX6720-60, Event: VCS node add, Coordinator IP: 10.17.10.31, VCS ID: 1, Status: rBridge ID 1 (10.17.10.32) added to VCS cluster., VcsFabAddRejoin, line: 1450, comp:dcmd, ltime:2011/06/27-02:47:04:555942.

The fields in the error message are described in Table 6.

TABLE 6 RAS message field description

Variable name	Description
Timestamp	The system time (UTC) when the message was generated on the switch. The RASLog subsystem supports an internationalized time stamp format base on the "LOCAL" setting.
Event ID	The Event ID is the message module and number. These values uniquely identify each message in the Network OS and reference the cause and actions recommended in this manual. Note that not all message numbers are used; there can be gaps in the numeric message sequence.
Sequence Number	The error message position in the log. When a new message is added to the log, this number is incremented by 1. The message sequence number starts at 1 after a firmware download and increases up to a value of 2,147,483,647 (0x7ffffff). The sequence number continues to increase after the message log wraps around; that is, the oldest message in the log is deleted when a new message is added. The message sequence numbering is not split for the system and DCE message logs. The sequence number can be reset to 1 using the clear logging raslog command. However, the sequence number is not reset if you clear a particular message type, for example: DCE. The sequence number is persistent across power cycles and switch reboots.
Flags	For most messages, this field contains a space character (null value) indicating that the message is neither a DCE, FFDC, or VCS message. Messages may contain the following values: DCE-Indicates a message generated by the protocol-based modules. FFDC-Indicates that additional first failure data capture information has also been generated for this event.

VCS-Indicates a VCS message generated by a switch in Brocade VCS fabric.

TABLE 6 RAS message field description (Continued)

Variable name	Description	
Severity	The severity level of the message, which can be one of the following: CRITICAL ERROR WARNING INFO	
Switch name	The defined switch name or the chassis name of the switch. This value is truncated if it exceeds 16 characters in length.	
Event-specific information	A text string explaining the error encountered and provides the parameters supplied by the software at runtime.	

Audit event messages

Compared to Log error messages, messages flagged as AUDIT provide additional user and system-related information of interest for post-event auditing and problem determination.

The following example shows the format of the Audit event message.

<Sequence Number> AUDIT, <Timestamp>, [<Event ID>], <Severity>, <Event Class>,
<User ID>/<Role>/<IP address>/<Interface>/<app name>, <Reserved field for future
expansion>, <Switch name>, <Event-specific information>

The following is a sample Audit event message.

0 AUDIT,2011/08/26-07:51:32 (GMT), [DCM-2001], INFO, DCMCFG, root/none/127.0.0.1/rpc/cli,, VDX6720-24, Event: noscli start, Status: success, Info: Successful login attempt through console from 127.0.0.1.

The fields in the Audit event message are described in Table 7.

TABLE 7 Audit message field description

Variable name	Description
Sequence Number	The error message position in the log.
AUDIT	Identifies the message as an Audit message.
Timestamp	The system time (UTC) when the message was generated on the switch. The RASLog subsystem supports an internationalized time stamp format base on the "LOCAL" setting.
Event ID	The Event ID is the message module and number. These values uniquely identify each message in the Network OS and reference the cause and actions recommended in this manual. Note that not all message numbers are used; there can be gaps in the numeric message sequence.
Severity	The severity level of the message, which can be one of the following: CRITICAL ERROR WARNING INFO
Event Class	The event class, which can be one of the following: DCMCFG FIRMWARE SECURITY

TABLE 7 Audit message field description (Continued)

Variable name	Description
User ID	The user ID.
Role	The role of the user.
IP Address	The IP address.
Interface	The interface being used.
Application Name	The application name being used on the interface.
Reserved field for future expansion	This field is reserved for future use and contains a space character (null value).
Switch name	The defined switch name or the chassis name of the switch. This value is truncated if it is over 16 characters in length.
Event-specific information	A text string explaining the error encountered and provides the parameters supplied by the software at runtime.

Responding to a RASLog message

This section provides procedures on gathering information on RASLog messages.

Looking up a message

Messages in this manual are arranged alphabetically by Module ID, and then numerically within a given module. To look up a message, copy down the module (see Table 8 on page 20) and the error code and compare this with the Table of Contents or look up lists to determine the location of the information for that message.

The following information is provided for each message:

- Module and code name for the error
- Message text
- Message Type
- Class (for Audit messages only)
- Message Severity
- Probable Cause
- Recommended Action

Gathering information about the problem

The following are the common steps and questions to ask yourself when troubleshooting a system message:

- What is the current Network OS version?
- What is the switch hardware version?
- Is the switch operational?

- Assess impact and urgency:
 - Is the switch down?
 - Is it a standalone switch?
 - How large is the fabric?
 - Is the fabric redundant?
- Execute the show logging raslog command on each switch.
- Execute the **copy support** command.
- Document the sequence of events by answering the following questions:
 - What happened just before the problem?
 - Is the problem repeatable?
 - If so, what are the steps to produce the problem?
 - What configuration was in place when the problem occurred?
- Did a failover occur?
- Was Power-On Self-Test (POST) enabled?
- Are serial port (console) logs available?
- What and when were the last actions or changes made to the system?

Support

Network OS creates several files that can help support personnel troubleshoot and diagnose a problem. This section describes those files and how to access and save the information for support personnel.

Panic dump, core dump, and FFDC data files

The Network OS creates panic dump files, core files, and FFDC data files when there are problems in the Network OS kernel. You can view files using the **show support** command. These files can build up in the persistent storage and may need to be periodically deleted or downloaded using the **copy support** command.

The software watchdog (SWD) process is responsible for monitoring daemons critical to the function of a healthy switch. The SWD holds a list of critical daemons that ping the SWD periodically at a predetermined interval defined for each daemon.

If a daemon fails to ping the SWD within the defined interval, or if the daemon terminates unexpectedly, then the SWD dumps information to the panic dump files, which helps to diagnose the root cause of the unexpected failure.

Execute the **show support** command to view these files or the **copy support ftp** command to send them to a host workstation using FTP. The panic dump files, core files, and FFDC data files are intended for support personnel use only.

Trace dumps

The Network OS produces trace dumps when problems are encountered within Network OS modules. The Network OS trace dump files are intended for support personnel use only. You can use the **copy support** command to collect trace dump files to a specified remote location to provide support when requested.

Using the copy support command

The **copy support** command is used to send the output of the RASLog messages, the trace files, and the output of the **copy support** command to an off-switch storage location through FTP. You can upload supportsave data from the local switch to an external host or you can save the data on an attached USB device. The **copy support** command runs a large number of dump and show commands to provide a global output of the status of the switch. Refer to the *Network OS Command Reference* for more information on the **copy support** command.

System module descriptions

Table 8 provides a summary of the system modules for which messages are documented in this reference guide; A module is a subsystem in the Network OS. Each module generates a set of numbered messages.

TABLE 8	System module descriptions
System module	Description
AUTH	AUTH messages indicate problems with the authentication module of the Network OS.
BL	BL messages are a result of faulty hardware, transient out-of-memory conditions, ASIC errors, or inconsistencies in the software state between an interface module and the environment monitor (EM) module.
BLL	Bloom is the name of the ASIC used as the building block for third-generation hardware platforms.
C2	Condor2 error messages indicate problems with the Condor2 ASIC driver module of the Network OS.
C3	Condor3 error messages indicate problems with the Condor2 ASIC driver module of the Network OS.
CHS	CHS messages report the problems in the management of the interface modules in the different slots of the chassis.
DCM	Distributed Configuration Manager (DCM) messages indicate major switch bootup events, user login or logout, and the configuration operations.
DOT1	DOT1 messages indicate problems with the 802.1x authentication module of the Network OS.
EANV	EANV messages indicate any issues associated with eAnvil ASIC operation and eAnvil ASIC driver operations.
ELD	End Loop Detection (ELD) messages notify a loop in the Layer 2 network and the status of the port on which the loop is detected.
EM	The environmental monitor (EM) manages and monitors the various field-replaceable units (FRUs), including the port cards, blower assemblies, power supplies, and World Wide Name (WWN) cards. EM controls the state of the FRUs during system startup, hot-plug sequences, and fault recovery. EM provides access to and monitors the sensor and status data from the FRUs and maintains the integrity of the system using the environmental and power policies. EM reflects system status by way of CLI commands, system light emitting diodes (LEDs), and status and alarm messages. EM also manages some component-related data.
FABR	FABR (network of Fibre Channel switches) messages come from the fabric daemon. The fabric daemon follows the FC-SW-3 standard for the fabric initialization process, such as determining the E_Ports, assigning unique domain IDs to switches, creating a spanning tree, throttling the trunking process, and distributing the domain and alias lists to all switches in the fabric.
FABS	FABS messages indicate problems in the fabric system driver module.

TABLE 8	System module descriptions (Continued)					
System module	Description					
FCMC	Fibre Channel miscellaneous messages relate to problems with the physical layer used to send Fibre Channel traffic to and from the switch.					
FCOE	FCOE error messages indicate problems with the Fibre Channel over Ethernet (FCoE) module of the Network OS.					
FCPH	The Fibre Channel Physical Layer is used to send Fibre Channel traffic to and from the switch.					
FLOD	FLOD is a part of the fabric shortest path first (FSPF) protocol that handles synchronization of the link state database (LSDB) and propagation of the link state records (LSRs).					
FSPF	Fabric shortest path first (FSPF) is a link state routing protocol that is used to determine how frames should be routed. FSPF messages are about protocol errors.					
FSS	The fabric state synchronization framework provides facilities by which the active management module can synchronize with the standby management module, enabling the standby management module to take control of the switch nondisruptively during failures and software upgrades. These facilities include version negotiation, state information transfer, and internal synchronization functions, enabling the transition from standby to active operation. FSS is defined both as a component and a service. A component is a module in the Network OS, implementing a related set of functionality. A service is a collection of components grouped together to achieve a modular software architecture.					
FVCS	The Fabric Services VCS (FVCS) daemon provides fabric distribution services for VCS and Virtual Link Aggregation Group (vLAG).					
FW	FW messages indicate the warnings when the temperature, voltage, fan speed, and switch status threshold exceed for the switch subsystems.					
HASM	HASM is the infrastructure for the High Availability System Management, which has the functionality to maintain the cluster of high availability switch platforms, deploy and start multiple service instances with active and standby redundancy in distributed clustering environment, manage the state synchronizations, and the non-disruptive failovers between active and standby management modules, host the non-disruptive firmware upgrade context, and support the software watchdog and daemon restart.					
HAWK	HAWK is a component that connects the fabric ASIC.					
HIL	HIL messages indicate any issues associated with the Hardware Independent Layer (HIL) for general platform components, such as Environmental Monitoring (EM), fan and power supply unit (PSU) subsystems, and other platform FRUs.					
HLO	HLO is a part of the fabric shortest path first (FSPF) protocol that handles the HELLO protocol between adjacent switches. The HELLO protocol is used to establish connectivity with a neighbor switch, to establish the identity of the neighbor switch, and to exchange FSPF parameters and capabilities.					
HSL	HSL messages indicate problems with the Hardware Subsystem Layer (HSL) of the Network OS.					
IGMP	IGMP messages indicate any issue associated with the Internet Group Management Protocol (IGMP) snooping feature.					
IPAD	IPAD messages are generated by the IP admin demon.					
KTRC	KTRC message indicate any problem associate with RAS-TRACE facility which provide Brocade internal information to diagnostic a failure.					
L2AG	L2AG messages indicate problems with the Layer 2 system agent module. L2SS and L2AG together control the Layer 2 forwarding engine and are responsible for MAC learning, aging, and forwarding functionality.					

System module	Description
L2SS	L2SS messages indicate problems with the Layer 2 system manager module. L2SS and L2AG together control the Layer 2 forwarding engine and are responsible for MAC learning, aging, an forwarding functionality.
L3SS	L3SS messages indicate any issues associated with IP forwarding, ARP, and IP routes.
LOG	LOG messages describe events and problems associated with the RASLog and Audit log faciliti
LSDB	The link state database is a part of the FSPF protocol that maintains records on the status of p links. This database is used to route frames.
MCAST_SS	MCAST_SS messages indicate any problems associated with the Layer 2 and Layer 3.
MPTH	Multicast path uses the shortest path first (SPF) algorithm to dynamically compute a broadcast tree.
MS	The Management Service (MS) enables the user to obtain information about the Fibre Channe fabric topology and attributes by providing a single management access point.
MSTP	MSTP messages indicate problems with Multiple Spanning Tree Protocol (MSTP) modules of th Network OS.
NBFS	NBFSM is a part of the fabric shortest path first (FSPF) protocol that handles a neighboring or adjacent switch's finite state machine (FSM). Input to the FSM changes the local switch from one state to another, based on specific events. example, when two switches are connected to each other using an interswitch link (ISL) cable, t are in the Init state. After both switches receive HELLO messages, they move to the Database Exchange state, and so on.
NS	NS messages indicate problems with the simple Name Server module.
NSM	NSM messages indicate problems with the interface management and VLAN management module of the Network OS.
ONMD	ONMD error messages indicate problems with the Operation, Administration and Maintenance module of the Network OS.
OSPF	OSPF messages indicate information or problems with the OSPF module of the Network OS.
PDM	Parity data manager (PDM) is a user-space daemon responsible for the replication of persisten configuration files from the primary partition to the secondary partition and from the active management module to the standby management module.
PHP	PHP messages indicate any important information associated with the discovery and creation, deletion, and updating of the port profiles.
PLAT	PLAT messages indicate hardware problems.
PORT	PORT messages refer to the front-end user ports on the switch. Front-end user ports are direct accessible by users to connect end devices or connect to other switches.
RAS	RAS messages notify when first failure data capture (FFDC) events are logged to the FFDC log, a size or roll-over warnings.
RCS	The reliable commit service (RCS) daemon generates log entries when it receives a request fro the zoning or security server for passing data messages to switches. RCS then requests reliabl transport write and read (RTWR) to deliver the message. RCS also acts as a gatekeeper, limitin the number of outstanding requests for the Zoning or Security modules.
RTM	Route Manager (RTM) messages indicate status or errors while updating or maintaining the rot and next-hop database.

TABLE 8	System module descriptions (Continued)					
System module	Description					
RTWR	The reliable transport write (RTWR) and read daemon helps deliver data messages either to specific switches in the fabric or to all the switches in the fabric. For example, if some of the switches are not reachable or are offline, RTWR returns an "unreachable" message to the caller, allowing the caller to take the appropriate action. If a switch is not responding, RTWR retries 100 times.					
SCN	The internal state change notification daemon is used for state change notifications from the kernel to the daemons within Network OS.					
SEC	SEC messages indicate security errors, warnings, or information during security-related data management or fabric merge operations. Administrators must watch for these messages to distinguish between internal switch and fabric operation errors and external attack.					
SFLO	sFlow is a standards-based sampling technology embedded within switches and routers, which is used to monitor high speed network traffic. sFlow uses two types of sampling:					
	Statistical packet-based sampling of switched or routed packet flows. Time based correlling of interface payments.					
	 Time-based sampling of interface counters. SFLO messages indicate errors or information related to the sflow daemon. 					
SLCD	SLCD messages provide wear level statistics of western digital (WD) SiliconDrive 2 compact flash.					
SNMP	Simple Network Management Protocol (SNMP) is an universally supported low-level protocol that allows simple get, get next, and set requests to go to the switch (acting as an SNMP agent). It also allows the switch to send traps to the defined and configured management station. Brocade switches support four management entities that can be configured to receive these traps or informs. SNMP messages indicate problems in the SNMP operations.					
SS	SS messages indicate problems during the execution of the copy support command.					
SSMD	SSMD messages indicate problems with the System Services Module (SSM) of the Network OS.					
SULB	The software upgrade library provides the firmware download command capability, which enables firmware upgrades as well as nondisruptive code load to the switches. SULB messages may display if there are any problems during the firmware download procedure.					
SWCH	SWCH messages are generated by the switch driver module that manages a Fibre Channel switch instance.					
TOAM	TRILL OAM (TOAM) messages indicate problems with the I2traceroute family of commands that help in VCS cluster data path troubleshooting.					
TRCE	TRCE messages describe events and problems associated with the tracedump facility.					
TS	Time Service (TS) provides switch time-synchronization by synchronizing all clocks in the network. The TS messages indicate information or errors during the switch time-synchronization.					
UCST	UCST is a part of the fabric shortest path first (FSPF) protocol that manages the unicast routing table.					
UPTH	UPATH is a part of the FSPF protocol that uses the SPF algorithm to dynamically compute a unicast tree.					
VC	VC messages indicates any important information related to the vCenter CLI and its plugins.					
VCS	VCS messages indicate major events related to VCS cluster formation and node operations.					
VRRP	VRRP messages indicate information or problems with the VRRP module of the Network OS.					

TABLE 8	System module descriptions (Continued)			
System module	Description			
WLV	Wolverine (WLV) ASIC is a component that connects the front-end port. WLV messages indicate failures in the front-end port.			
ZONE	ZONE messages indicate any problems associated with the zoning features, including commands associated with aliases, zones, and configurations.			

Log Messages

AUTH Messages

AUTH-1001
AUTH-1002
AUTH-1003
AUTH-1004
AUTH-1006
AUTH-1007
AUTH-1010
AUTH-1012
AUTH-1013
AUTH-1014
AUTH-1017
AUTH-1018
AUTH-1020
AUTH-1022
AUTH-1025
AUTH-1026
AUTH-1027
AUTH-1028
AUTH-1029
AUTH-1030
AUTH-1031
AUTH-1032
AUTH-1033
AUTH-1034
AUTH-1035
AUTH-1036
AUTH-1037
AUTH-1039
AUTH-1040
AUTH-1041
AUTH-1042

AUTH-1044

BL Messages

- BL-1000
- BL-1001
- BL-1002
- BL-1003
- BL-1004
- BL-1006
- BL-1007
- BL-1008
- BL-1009
- BL-1010
- BL-1011
- BL-1012
- BL-1013
- BL-1014
- BL-1015
- BL-1016
- BL-1017 BL-1018
- BL-1019
- BL-1020
- BL-1021
- BL-1022 BL-1023
- DL 1020
- BL-1024 BL-1026
- BL-1027
- BL-1028 BL-1029
- BL-1031
- DE 1001
- BL-1032 BL-1033
- BL-1034
- BL-1037
- __
- BL-1038 BL-1039
- BL-1045
- BL-1046
- BL-1047

BLL Messages

BLL-1000

C2 Messages

C2-1004 C2-1006 C2-1007 C2-1008 C2-1009 C2-1010 C2-1011

C2-1012

C3 Messages

C3-1004 C3-1006 C3-1010 C3-1011 C3-1012 C3-1014 C3-1017 C3-1019 C3-1020

CHS Messages

CHS-1002 CHS-1003 CHS-1004 CHS-1005

DCM Messages

DCM-1001 DCM-1002 DCM-1003 DCM-1004 DCM-1005

D	CI	M	-1	10	0	7

DCM-1008

DCM-1009

DCM-1010

DCM-1011

DCM-1012

DCM-1101

DCM-1102

DCM-1103

DCM-1104

DCM-1105

DCM-1106

DCM-1107

DCM-1108

DCM-1109

DCM-1201

DCM-1202

DCM-1203

DCM-1204

DCM-1205

DCM-1206

DCM-1207

DCM-1208

DCM-1209

DCM-1210

DCM-1211

DCM-1212

DCM-3005

DCM-3051

DCM-3052

DCM-4001

DCM-4002

EANV Messages

EANV-1001

EANV-1002

EANV-1003

EANV-1004

EANV-1005

EANV-1006

EM Messages

EM-1001

EM-1002

EM-1003

EM-1004

EM-1005

EM-1006

EM-1008

EM-1009

EM-1010

EM-1011

EM-1012

EM-1013

EM-1014

EM-1015

EM-1016

EM-1020

EM-1021

EM-1022

EM-1023

EM-1024

EM-1028

EM-1029

EM-1031

EM-1033

EM-1034

EM-1036

EM-1037

EM-1042

EM-1043

EM-1045

EM-1046

EM-1047

EM-1048

EM-1049

EM-1050

EM-1051

EM-1059 EM-1064

EM-1068

EM-1069

EM-1070

EM-2003

ERCP Messages

ERCP-1000

ESS Messages

ESS-1008

ESS-1009

ESS-1010

FABR Messages

FABR-1001

FABR-1003

FABR-1004

FABR-1005

FABR-1006

FABR-1007

FABR-1008

FABR-1009

FABR-1010

FABR-1012

.....

FABR-1013

FABR-1014

FABR-1019

FABR-1029

FABR-1030 FABR-1039

E4.DD 4044

FABR-1041

FABR-1055

FABS Messages

FABS-1001

FABS-1002
FABS-1004
FABS-1005
FABS-1007
FABS-1008
FABS-1009
FABS-1010
FABS-1011
FABS-1013
FABS-1014
FABS-1015

FCMC Messages

FCMC-1001

FCPH Messages

FCPH-1001

FLOD Messages

FLOD-1001 FLOD-1003 FLOD-1004 FLOD-1005 FLOD-1006

FSPF Messages

FSPF-1001 FSPF-1002 FSPF-1005 FSPF-1006 FSPF-1007 FSPF-1008

FSS Messages

FSS-1001

FSS-1002

FSS-1003

FSS-1004

FSS-1005

FSS-1006

FSS-1007

FSS-1008

FSS-1009

FSS-1010

FSS-1011

FVCS Messages

FVCS-1003

FVCS-2001

FVCS-2002

FVCS-2003

FVCS-2004

FVCS-2005

FVCS-2006

FVCS-3001

FVCS-3002

FVCS-3003

FVCS-3004

FVCS-3005

FVCS-3006

FVCS-3007

FVCS-3008

FVCS-3009

FW Messages

FW-1001

FW-1002

FW-1003

FW-1004

FW-1005

- FW-1006
- FW-1007
- FW-1008
- FW-1009
- FW-1010
- FW-1012
- FW-1034
- FW-1035
- FW-1036
- FW-1038
- FW-1039
- FW-1040
- FW-1042
- FW-1043
- FW-1044
- FW-1046
- FW-1047
- FW-1048
- FW-1050
- FW-1051
- FW-1052
- FW-1297
- FW-1298
- FW-1299
- FW-1341
- FW-1342
- FW-1343
- FW-1403
- FW-1404
- FW-1405
- FW-1406
- FW-1407
- FW-1408
- FW-1424
- FW-1425
- FW-1426
- FW-1427
- FW-1428
- FW-1429

F	W	-1	143	0

FW-1431

FW-1432

FW-1433

FW-1434

FW-1435

FW-1439

FW-1440

FW-1441

FW-1442

FW-1443

FW-1444

FW-1447

FW-1500

FW-1501

FW-1510

FW-3101

FW-3102

FW-3103

FW-3104

FW-3105

FW-3107

FW-3108

FW-3109

FW-3110

FW-3111

FW-3113

FW-3114

FW-3115

FW-3116

FW-3117

FW-3119

1 11 0110

FW-3120 FW-3121

FW-3122

FW-3123

HASM Messages

HASM-1000

HASM-1001
HASM-1002
HASM-1003
HASM-1004
HASM-1013
HASM-1014
HASM-1019
HASM-1020
HASM-1021
HASM-1022
HASM-1023
HASM-1024
HASM-1025
HASM-1026
HASM-1100
HASM-1101
HASM-1102
HASM-1103
HASM-1104
HASM-1105
HASM-1106
HASM-1107
HASM-1108
HASM-1109
HASM-1110
HASM-1111
HASM-1120
HASM-1121
HASM-1130
HASM-1131
HASM-1200

HAWK Messages

HAWK-1002

HASM-1201

HIL Messages

HIL-1202

HIL-1301
HIL-1302
HIL-1404
HIL-1505
HIL-1506
HIL-1510
HIL-1511
HIL-1512
HIL-1521
HIL-1522
HIL-1523
HIL-1605

HLO Messages

HLO-1001 HLO-1002 HLO-1003

HSL Messages

HSL-1000 HSL-1001 HSL-1004 HSL-1006 HSL-1009

IPAD Messages

IPAD-1000 IPAD-1001 IPAD-1002 IPAD-1003 IPAD-1004 IPAD-1005

KTRC Messages

KTRC-1001 KTRC-1002 KTRC-1003 KTRC-1004 KTRC-1005

LOG Messages

LOG-1000 LOG-1001 LOG-1002 LOG-1003 LOG-1004 LOG-1005 LOG-1006

LSDB Messages

LSDB-1001 LSDB-1002 LSDB-1003 LSDB-1004

MPTH Messages

MPTH-1001 MPTH-1002 MPTH-1003

MS Messages

MS-1021

NBFS Messages

NBFS-1001 NBFS-1002 NBFS-1003

NS Messages

NS-1006 NS-1009 NS-1012

PDM Messages

PDM-1001
PDM-1003
PDM-1004
PDM-1006
PDM-1007
PDM-1009
PDM-1010
PDM-1011
PDM-1012
PDM-1013
PDM-1014
PDM-1017
PDM-1019
PDM-1021

PHP Messages

PHP-1001 PHP-1002 PHP-1003 PHP-1004

PLAT Messages

PLAT-1000 PLAT-1001 PLAT-1002 PLAT-1004 PLAT-1005 PLAT-1006 PLAT-1007 PLAT-1008 PLAT-1009

PORT Messages

PORT-1003 PORT-1004 PORT-1011 PORT-1012

PORT-1013

RAS Messages

RAS-1001

RAS-1002

RAS-1004

RAS-1005

RAS-1006

RAS-1007

RAS-2001

RAS-2002

RAS-2003

RAS-3001

RAS-3002

RAS-3003

RAS-3004

RAS-3005

RCS Messages

RCS-1003

RCS-1005

RCS-1006

RCS-1007

RCS-1008

RCS-1010

RCS-1011

RTWR Messages

RTWR-1001

RTWR-1002

RTWR-1003

SCN Messages

SCN-1001

SEC Messages

- SEC-1033
- SEC-1034
- SEC-1036
- SEC-1037
- SEC-1038
- SEC-1044
- SEC-1071
- SEC-1180
- SEC-1181
- SEC-1184
- SEC-1185
- SEC-1187
- SEC-1189
- SEC-1190
- SEC-1191
- SEC-1192
- SEC-1193
- SEC-1197
- SEC-1199
- SEC-1203
- SEC-1307
- SEC-1308
- SEC-1312
- SEC-1313
- SEC-1325
- SEC-1329
- SEC-1334
- SEC-1335
- SEC-1336
- SEC-1337
- SEC-3035
- SEC-3036
- SEC-3037
- SEC-3038
- SEC-3039
- SEC-3051
- SEC-3061
- SEC-3062

SEC-3501

SLCD Messages

SLCD-1001

SLCD-1002

SLCD-1003

SLCD-1004

SLCD-1005

SLCD-1006

SLCD-1007

SLCD-1008

SLCD-1009

SLCD-1010

SLCD-1011

SNMP Messages

SNMP-1001

SNMP-1002

SNMP-1003

SNMP-1004

SNMP-1005

SS Messages

SS-1000

SS-1001

SS-1002

SS-1003

SS-1004

SSMD Messages

SSMD-1537

SULB Messages

SULB-1100

SULB-1101

SULB-1102

SULB-1103 SULB-1104 SULB-1105 SULB-1106 SULB-1107 SULB-1108 SULB-1109

SWCH Messages

SWCH-1001 SWCH-1002 SWCH-1003 SWCH-1004 SWCH-1005 SWCH-1007 SWCH-1021

TRCE Messages

TRCE-1002 TRCE-1003 TRCE-1005 TRCE-1006 TRCE-1007 TRCE-1009 TRCE-1010 TRCE-1011 TRCE-1011

TS Messages

TS-1002 TS-1008

UCST Messages

UCST-1003

UPTH Messages

UPTH-1001

VC Messages

VC-1000

VC-1001

VC-1002

VC-1003

VC-1004

VC-1005

VC-1006

VCS Messages

VCS-1001

VCS-1002

VCS-1003

VCS-1004

VCS-1005

VCS-1006

VCS-1007

VCS-1008

VCS-1009

WLV Messages

WLV-1001

WLV-1002

WLV-1003

ZONE Messages

ZONE-1010

ZONE-1014

ZONE-1015

ZONE-1019

ZONE-1022

ZONE-1023

ZONE-1024

- **ZONE-1027**
- **ZONE-1028**
- **ZONE-1029**
- **ZONE-1032**
- **ZONE-1033**
- **ZONE-1034**
- ZONE-1035
- **ZONE-1036**
- **ZONE-1037**
- **ZONE-1038**
- **ZONE-1039**
- ZONE-1040
- ZONE-1041
- ZONE-1042
- ZONE-1043
- ZONE-1044
- **ZONE-1045**
- **ZONE-1046**

Chapter

DCE Messages 3

DOT1 Messages

DOT1-1001
DOT1-1002
DOT1-1003
DOT1-1004
DOT1-1005
DOT1-1007
DOT1-1008
DOT1-1009
DOT1-1010
DOT1-1011
DOT1-1012
DOT1-1013

ELD Messages

ELD-1001 ELD-1002

FCOE Messages

FCOE-1001 FCOE-1019 FCOE-1020 FCOE-1022 FCOE-1023 FCOE-1024 FCOE-1030 FCOE-1030 FCOE-1032 FCOE-1034 FCOE-1035

FCOE-1036

IGMP Messages

IGMP-1001

IGMP-1002

IGMP-1003

IGMP-1004

L2AG Messages

L2AG-1001

L2AG-1002

L2AG-1003

L2AG-1004

L2AG-1005

L2AG-1006

L2AG-1007

L2SS Messages

L2SS-1001

L2SS-1002

L2SS-1003

L2SS-1004

L2SS-1005

L2SS-1006

L2SS-1007

L2SS-1008

L2SS-1009

L2SS-1010

LOG Messages

LOG-1007

MCAST_SS Messages

MCAST_SS-1001

MCAST_SS-1002

MCAST_SS-1003

MCAST_SS-1004 MCAST_SS-1005 MCAST_SS-1006 MCAST_SS-1007 MCAST_SS-1008 MCAST_SS-1009 MCAST_SS-1010 MCAST_SS-1011 MCAST_SS-1012 MCAST_SS-1013 MCAST_SS-1014 MCAST_SS-1015 MCAST_SS-1016 MCAST_SS-1017 MCAST_SS-1018 MCAST_SS-1019 MCAST_SS-1020

MSTP Messages

MSTP-1001 MSTP-1002 MSTP-1003 MSTP-1004 MSTP-2001 MSTP-2002 MSTP-2003 MSTP-2004 MSTP-2005 MSTP-2006

NSM Messages

NSM-1001 NSM-1002 NSM-1003 NSM-1004 NSM-1007 NSM-1009 NSM-1010

- NSM-1011
- NSM-1012
- NSM-1013
- NSM-1014
- NSM-1015
- NSM-1016
- NSM-1017
- NSM-1018
- NSM-1019
- NSM-1020
- NSM-1021
- NSM-1022
- NSM-1023
- NSM-1024
- NSM-1025
- NSM-1026
- NSM-1027
- NSM-1028
- NSM-1029
- NSM-1030
- NSM-1031
- NSM-1032
- NSM-1033
- NSM-1034
- NSM-1035
- NSM-1036
- NSM-1037
- NSM-1038
- NSM-2000
- NSM-2001
- NSM-2002
- NSM-2003
- NSM-2004
- NSM-2005
- NSM-2006
- NSM-2007
- NSM-2008
- NSM-2010
- NSM-2011

١	N	C	١./	I-2	n.	10
	IN	O	ıv	1-2	u	12

NSM-2013

NSM-2014

NSM-2015

NSM-2016

NSM-2017

NSM-2018

NSM-2019

NSM-2020

NSM-2021

NSM-2022

NSM-2023

NSM-2024

NSM-2025

NSM-2026

NSM-2027

NSM-2028

NSM-2029

NSM-2030

NSM-2031

NSM-2032

NSM-2033

NSM-2034

NSM-2035

NSM-2036

ONMD Messages

ONMD-1000

ONMD-1001

ONMD-1002

ONMD-1003

ONMD-1004

ONMD-1005

OSPF Messages

OSPF-1001

OSPF-1002

OSPF-1003

RTM Messages

RTM-1001

RTM-1002

RTM-1003

RTM-1005

RTM-1021

RTM-1022

RTM-1023

SFLO Messages

SFLO-1001

SFLO-1002

SFLO-1003

SFLO-1004

SFLO-1005

SFLO-1006

SFLO-1007

SFLO-1008

SFLO-1009

SSMD Messages

SSMD-1001

SSMD-1002

SSMD-1003

SSMD-1004

SSMD-1005

SSMD-1006

SSMD-1007 SSMD-1200

SSMD-1201

SSMD-1202

SSMD-1203

SSMD-1204

SSMD-1205

SSMD-1206

SSMD-1207

SSMD-1208

- SSMD-1209
- SSMD-1210
- SSMD-1211
- SSMD-1212
- SSMD-1213
- SSMD-1214
- SSMD-1215
- SSMD-1216
- SSMD-1217
- SSMD-1218
- SSMD-1219
- SSMD-1220
- SSMD-1221
- SSMD-1222
- SSMD-1223
- OOMD 1220
- SSMD-1224
- SSMD-1225
- SSMD-1300
- SSMD-1301
- SSMD-1302
- SSMD-1303
- SSMD-1304
- SSMD-1305
- SSMD-1306
- SSMD-1307
- SSMD-1308
- SSMD-1309
- ____
- SSMD-1312 SSMD-1313
- SSMD-1314
- SSMD-1315
- SSMD-1400
- SSMD-1401
- SSMD-1402
- SSMD-1403
- SSMD-1404
- SSMD-1405
- SSMD-1406
- SSMD-1407

- SSMD-1408
- SSMD-1436
- SSMD-1437
- SSMD-1438
- SSMD-1439
- SSMD-1500
- SSMD-1536
- SSMD-1571
- SSMD-1600
- SSMD-1601
- SSMD-1602
- SSMD-1603
- SSMD-1604
- SSMD-1605
- SSMD-1606
- SSMD-1607
- SSMD-1609
- SSMD-1610
- SSMD-1611
- SSMD-1612
- SSMD-1613
- SSMD-1614
- SSMD-1615
- SSMD-1618
- SSMD-1619
- SSMD-1620
- SSMD-1621
- SSMD-1622
- SSMD-1650
- SSMD-1651
- SSMD-1652
- SSMD-1653
- SSMD-1654
- SSMD-1655
- SSMD-1656
- SSMD-1657
- SSMD-1658
- SSMD-1659
- SSMD-1660

SSMD-1700	
SSMD-1701	
SSMD-1702	
SSMD-1703	
SSMD-1704	
SSMD-1705	
SSMD-1706	
SSMD-1707	
SSMD-1708	
SSMD-1900	
SSMD-1901	
SSMD-1902	
SSMD-1903	
SSMD-1904	
SSMD-1905	
SSMD-1906	
SSMD-1907	
SSMD-1908	
SSMD-1909	
SSMD-1910	
SSMD-1911	
SSMD-1912	
SSMD-1913	
SSMD-1914	
SSMD-1915	
SSMD-1916	

TOAM Messages

TOAM-1000

TOAM-1003

VRRP Messages

VRRP-1001

VRRP-1501

VRRP-2001

VRRP Messages

FFDC Messages

AUTH Messages

AUTH-1014 AUTH-1044

BL Messages

BL-1002 BL-1003 BL-1004 BL-1008 BL-1009 BL-1011 BL-1016 BL-1020

BLL Messages

BLL-1000

CHS Messages

CHS-1002

EANV Messages

EANV-1002

EM Messages

EM-1001 EM-1002 EM-1003 EM-1004 EM-1005 EM-1006

EM-1008

EM-1009

EM-1010

EM-1011

EM-1012

EM-1028

EM-1068

ERCP Messages

ERCP-1000

FABR Messages

FABR-1013

FABR-1019

FABS Messages

FABS-1001

FCMC Messages

FCMC-1001

FCPH Messages

FCPH-1001

FLOD Messages

FLOD-1004

HASM Messages

HASM-1105

HASM-1200

HASM-1201

HAWK Messages

HAWK-1002

HIL Messages

HIL-1506

HIL-1522

HIL-1523

HLO Messages

HLO-1001

HLO-1002

IPAD Messages

IPAD-1003

LOG Messages

LOG-1001

LOG-1002

LSDB Messages

LSDB-1003

MPTH Messages

MPTH-1001

MPTH-1002

NBFS Messages

NBFS-1002

PDM Messages

PDM-1017

PLAT Messages

PLAT-1000

PLAT-1004

PLAT-1005

RAS Messages

RAS Messages

RAS-1004

RAS-1005

SCN Messages

SCN-1001

SNMP Messages

SNMP-1004

TRCE Messages

TRCE-1008

WLV Messages

WLV-1002

Chapter

5

Audit Messages

AUTH Messages

AUTH-3001 AUTH-3002 AUTH-3004

AUTH-3005

AUTH-3006

AUTH-3007

AUTH-3008

DCM Messages

DCM-1006

DCM-2001

DCM-2002

SEC Messages

SEC-3014

SEC-3016

SEC-3017

SEC-3018

SEC-3019

SEC-3020

SEC-3021

SEC-3022

SEC-3023

SEC-3024

SEC-3025

SEC-3026

SEC-3027

SEC-3028

SEC-3030

SEC-3034

SEC-3035

SEC-3036

SEC-3037

SEC-3038

SEC-3039

SEC-3045

SEC-3046

SEC-3049

SEC-3051

SEC-3061

SEC-3062

SEC-3501

SULB Messages

SULB-1100

SULB-1101

SULB-1102

SULB-1103

SULB-1104

SULB-1105

SULB-1106

Chapter

6

VCS Messages

VCS Messages

VCS-1001

VCS-1002

VCS-1003

VCS-1004

VCS-1005

VCS-1006

VCS-1007

VCS-1008

VCS-1009

6 VCS Messages

Network OS Messages

AUTH Messages

AUTH-1001

Message <Operation type> has been successfully completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the secret database has been updated using the fcsp auth-secret or no fcsp auth-secret

command. The values for Operation type can be "set" or "remove".

Recommended

Action

No action is required.

AUTH-1002

Message <Operation type> has failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified action to update the secret database using the fcsp auth-secret or no fcsp

auth-secret command has failed. The values for Operation type can be "set" or "remove".

Recommended Execute the fcsp auth-secret or no fcsp auth-secret command again.

Action Execute the **copy support** command and contact your switch service provider.

AUTH-1003

Message <data type> type has been successfully set to <setting value>.

Message Type LOG

Severity INFO

Probable Cause Indicates that an authentication configuration parameter was set to a specified value. The data type can

be either authentication type, DH group type, or policy type.

Recommended

No action is required.

Action

AUTH-1004

Message Failed to set <data type> type to <setting value>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the fcsp auth command has failed to set the authentication configuration value. The data

type can be either authentication type, DH group type, hash type, or policy type.

Recommended Execute the fcsp auth command.

Action Execute the **copy support** command and contact your switch service provider.

AUTH-1006

Message Failed to open authentication configuration file.

Message Type LOG

Severity WARNING

Probable Cause Indicates an internal problem with the security policy.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

If the message persists, execute the copy support command and contact your switch service provider.

AUTH-1007

Message The proposed authentication protocol(s) are not supported: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the proposed authentication protocol types are not supported by the local port.

Recommended Execute the **fcsp auth** command to make sure the local switch supports the following protocols: Fibre

Action Channel Authentication Protocol (FCAP) or Diffie-Hellman Challenge Handshake Authentication Protocol

(DH-CHAP).

Message Failed to initialize security policy: switch <switch number>, error <error code>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates an internal problem with the security policy.

Recommended Reload or power cycle the switch.

> Action If the message persists, execute the copy support command and contact your switch service provider.

AUTH-1012

Message Authentication <code> is rejected: port <port number> explain <explain code>

reason <reason code>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates that the specified authentication is rejected because the remote entity does not support

authentication.

Recommended

Action

Make sure the entity at the other end of the link supports authentication.

AUTH-1013

Cannot perform authentication request message: port <port number>, message code Message

<message code>.

Message Type LOG

Action

Severity **WARNING**

Probable Cause Indicates that the system is running low on resources when receiving an authentication request. Usually

this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

and chassis enable commands.

AUTH-1014

Message Invalid port value to <operation>: port <port number>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates an internal problem with the security policy.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

If the message persists, execute the **copy support** command and contact your switch service provider.

AUTH-1017

Message Invalid value to start authentication request: port port number>, operation code

<operation code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal problem with the security policy.

Recommended Reinitialize authentication using the **shutdown** and **no shutdown** commands or the **chassis disable**

Action and chassis enable commands.

If the message persists, execute the **copy support** command and contact your switch service provider.

AUTH-1018

Message Invalid value to check protocol type: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal problem with the security policy.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

Message Failed to create timer for authentication: port <port number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that an authentication message timer was not created.

Usually this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

If the message persists, execute the **copy support** command and contact your switch service provider.

AUTH-1022

Message Failed to extract <data type> from <message> payload: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed to extract a particular value from the receiving payload.

Usually this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

If the message persists, execute the copy support command and contact your switch service provider.

AUTH-1025

Message Failed to get <data type> during <authentication phase>: port <port number>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the authentication process failed to get expected information during the specified

authentication phase. Usually this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

and chassis enable commands.

AUTH-1026

Message Failed to <Device information> during negotiation phase: port <port number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the authentication failed to get device or host bus adapter (HBA) information due to an

internal failure. Usually this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

If the message persists, execute the copy support command and contact your switch service provider.

AUTH-1027

Message Failed to select <authentication value> during <authentication phase>: value

<value> port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed to select an authentication value (for example, DH group,

hash value, or protocol type) from a receiving payload during the specified authentication phase. This

error occurred because the local switch does not support the specified authentication value.

Recommended

Action

Check the authentication configuration and reset the supported value if needed using the fcsp auth

command.

Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

and chassis enable commands.

If the message persists, execute the copy support command and contact your switch service provider.

AUTH-1028

Message Failed to allocate <data type> for <operation phase>: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed because the system is low on memory. Usually this

problem is transient. The authentication may fail.

The data type is a payload or structure that failed to get memory. The operation phase specifies which

operation of a particular authentication phase failed.

Recommended Action

Reinitialize authentication using the **shutdown** and **no shutdown** commands or the **chassis disable**

and chassis enable commands.

If the message persists, execute the copy support command and contact your switch service provider.

AUTH-1029

Message Failed to get <data type> for <message phase> message: port <port number>, retval

<error code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed to get a particular authentication value at certain phase.

Usually this problem is transient. The authentication may fail.

The data type is a payload or structure that failed to get memory.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

If the message persists, execute the **copy support** command and contact your switch service provider.

AUTH-1030

Message Invalid message code for <message phase> message: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the receiving payload does not have a valid message code during the specified

authentication phase. Usually this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

If the message persists, execute the copy support command and contact your switch service provider.

AUTH-1031

Message Failed to retrieve secret value: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the secret value was not set properly for the authenticated entity.

Recommended Reset the secret value using the **fcsp auth-secret** command.

Action Reinitialize authentication using the **shutdown** and **no shutdown** commands or the **chassis disable**

and chassis enable commands.

AUTH-1032

Message Failed to generate <data type> for <message payload> payload: length <data

length>, error code <error code>, port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the authentication process failed to generate specific data (for example, challenge, nonce,

or response data) for an authentication payload. This usually relates to an internal failure. A nonce is a single-use, usually random value used in authentication protocols to prevent replay attacks. Usually this

problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

If the message persists, execute the **copy support** command and contact your switch service provider.

AUTH-1033

Message Disable port <port number> due to unauthorized switch <switch WWN value>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that an entity, which was not configured in the switch connection control (SCC) policy tried to

connect to the port.

Recommended Add the entity World Wide Name (WWN) to the SCC policy using the **secpolicy defined-policy**

command, then reinitialize authentication using the **shutdown** and **no shutdown** commands or the

chassis disable and chassis enable commands.

AUTH-1034

Message Failed to validate name <entity name> in <authentication message>: port <port

number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the entity name in the payload is not in the correct format.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis enable commands.

AUTH-1035

Message Invalid <data type> length in <message phase> message: length <data length>, port

<port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a particular data field in the authentication message has an invalid length field. This error

usually relates to an internal failure.

Usually this problem is transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis disable commands.

If the message persists, execute the **copy support** command and contact your switch service provider.

AUTH-1036

Message Invalid state <state value> for <authentication phase>: port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the switch received an unexpected authentication message. Usually this problem is

transient. The authentication may fail.

Recommended Reinitialize authentication using the shutdown and no shutdown commands or the chassis disable

Action and chassis disable commands.

If the message persists, execute the **copy support** command and contact your switch service provider.

AUTH-1037

Message Failed to <operation type> response for <authentication message>: init_len <data

length>, resp_len <data length>, port <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a Diffie-Hellman Challenge Handshake Authentication Protocol (DH-CHAP) authentication

operation failed on the specified port due to mismatched response values between two entities. The error

may indicate that an invalid entity tried to connect to the switch.

Recommended Check the connection port for a possible security attack.

Action Reinitialize authentication using the **shutdown** and **no shutdown** commands or the **chassis disable**

and chassis disable commands.

AUTH-1039

Message Neighboring switch has conflicting authentication policy: Port <Port Number>

disabled.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the neighboring switch has a conflicting authentication policy enabled. The E_Port has

been disabled because the neighboring switch has rejected the authentication negotiation and the local

switch has a strict switch authentication policy.

Recommended Correct the switch policy configuration on either of the switches using the fcsp auth command, and then

enable the port using the no shutdown command.

AUTH-1040

Message Reject authentication on port <Port Number>, because switch authentication policy

is set to OFF.

LOG Message Type

Action

Severity INFO

Probable Cause Indicates that the local switch has rejected the authentication because the switch policy is turned off. If

the neighboring switch has a strict (ON) switch policy, the port will be disabled due to conflicting

configuration settings. Otherwise, the E_Port will form without authentication.

Recommended If the port is disabled, correct the switch policy configuration on either of the switches using the fcsp auth

command, and then enable the port on neighboring switch using the no shutdown command. If the Action

E Port has formed, no action is required.

AUTH-1041

Message Port <port number> has been disabled, because an authentication-reject was

received with code '<Reason String>' and explanation '<Explanation String>'.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the specified port has been disabled because it received an authentication-reject response

from the connected switch or device. The error may indicate that an invalid entity tried to connect to the

switch.

Recommended Check the connection port for a possible security attack.

Action

Check the shared secrets using the **show fcsp auth-secret dh-chap** command and reinitialize authentication using the shutdown and no shutdown commands or the chassis disable and chassis

disable commands.

AUTH-1042

Message Port <port number> has been disabled, because authentication failed with code

'<Reason String>' and explanation '<Explanation String>'.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified port has been disabled because the connecting switch or device failed to

authenticate. The error may indicate that an invalid entity attempted to connect to the switch.

Recommended Check the connection port for a possible security attack.

Action Check the shared secrets using the show fcsp auth-secret dh-chap command and reinitialize

authentication using the shutdown and no shutdown commands or the chassis disable and chassis

disable commands.

If the message persists, execute the copy support command and contact your switch service provider.

AUTH-1044

Message Authentication <Reason for disabling the port >. Disabling the port <port number>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the authentication has timed out after multiple retries and as a result, the specified port has

been disabled. This problem may be transient due to the system CPU load. In addition, a defective small

form-factor pluggable (SFP) or faulty cable may have caused the failure.

Recommended Check the SFP and the cable. Then try to enable the port using the **no shutdown** command.

Action

AUTH-3001

Message Event: <Event Name>, Status: success, Info: <Data type> type has been changed from

[<Old value>] to [<New value>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that a authentication configuration parameter was set to a specified value. The data type can

be either authentication type, DH group type, hash type, or policy type.

Recommended No action is required.

Action

AUTH-3002

Message Event: <Event Name>, Status: success, Info: <Event Related Info>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the secret database has been updated using the fcsp auth-secret command.

Recommended No action is required.

Action

AUTH-3004

Message Event: <Event Name>, Status: failed, Info: Neighboring switch has a conflicting

authentication policy; Port <Port Number> disabled.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified E_Port was disabled because the neighboring switch rejected the

authentication negotiation and the local switch has a strict switch authentication policy.

Recommended

Action

Correct the switch policy configuration on either of the switches using the fcsp auth command, and then

enable the port using **no shutdown** command.

AUTH-3005

Message Event: <Event Name>, Status: failed, Info: Rejecting authentication request on

port <Port Number> because switch policy is turned OFF.

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates that the local switch has rejected the authentication request because the switch policy is turned

off. If the neighboring switch has a strict (ON) switch policy, the port will be disabled due to conflicting

configuration settings. Otherwise, the E_Port will form without authentication.

Recommended If the specified port is disabled, correct the switch policy configuration on either of the switches using the

fcsp auth command, and then enable the port on the neighboring switch using no shutdown command.

If the E_Port formed, no action is required.

AUTH-3006

Message Event: <Event Name>, Status: failed, Info: Authentication failed on port <port

number> due to mismatch of DH-CHAP shared secrets.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that a Diffie-Hellman Challenge Handshake Authentication Protocol (DH-CHAP) authentication

operation failed on the specified port due to mismatched response values between two entities. The error

may indicate that an invalid entity tried to connect to the switch.

Recommended Check the connection port for a possible security attack.

Action Check the shared secrets using the **show fcsp auth-secret dh-chap** command and reinitialize

authentication using the shutdown and no shutdown commands or the chassis disable and chassis

enable commands.

If the message persists, execute the copy support command and contact your switch service provider.

AUTH-3007

Message Event: <Event Name>, Status: failed, Info: Port <port number> disabled, because an

authentication-reject was received with code '<Reason String>' and Explanation

'<Explanation String>'.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified port was disabled because it received an authentication-reject response from

the connected switch or device. The error may indicate that an invalid entity tried to connect to the

switch.

Recommended Check the connection port for a possible security attack.

Action Check the chared correct using about four parts all a

Check the shared secrets using **show fcsp auth-secret dh-chap** and reinitialize authentication using the **shutdown** and **no shutdown** commands or the **chassis disable** and **chassis enable** commands.

AUTH-3008

Message Event: <Event Name>, Status: failed, Info: Port <port number> has been disabled

due to authentication failure with code '<Reason String>' and explanation

'<Explanation String>'.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified port has been disabled because the connecting switch or device failed to

authenticate. The error may indicate that an invalid entity tried to connect to the switch.

Recommended Check the connection port for a possible security attack.

Action Check the shared secrets using **show fcsp auth-secret dh-chap** and reinitialize authentication using

the shutdown and no shutdown commands or the chassis disable and chassis enable commands.

BL Messages

BL-1000

Message Initializing ports...

Message Type

Severity INFO

Probable Cause Indicates that the switch has started initializing the ports.

Recommended No action is required.

Action

BL-1001

Message Port initialization completed.

Message Type LOG

> Severity INFO

Probable Cause Indicates that the switch has completed initializing the ports.

Recommended No action is required.

Action

BL-1002

Message Init Failed: <slot string> DISABLED because internal ports were not ONLINE, <list

of internal port number not ONLINE>.

Message Type FFDC | LOG

> **CRITICAL** Severity

Probable Cause Indicates that the interface module initiation failed because one or more of the internal ports were not

online. The interface module is faulted.

Recommended Make sure that the interface module is seated correctly. If the interface module is seated correctly, reload Action

or power cycle the interface module using the **power-off** and **power-on** commands.

Execute the diag systemverification command to verify that the interface module does not have

hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

Additional interface module fault messages precede and follow this error, providing more information.

Refer to other error messages for the recommended action.

If the message persists, replace the interface module.

BL-1003

Message Faulty interface module in <slot string>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates a faulty interface module in the specified slot.

Recommended Make sure that the interface module is seated correctly. If the interface module is seated correctly, reload

Action or power cycle the interface module using the power-off and power-on commands.

Execute the diag systemverification command to verify that the interface module does not have

hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If the message persists, replace the interface module.

BL-1004

Message Suppressing interface module fault in <slot string>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified interface module experienced a failure but was not faulted due to a user

setting.

Recommended Reload or power cycle the interface module using the **power-off** and **power-on** commands.

Action

Execute the diag systemverification command to verify that the interface module does not have

hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If the message persists, replace the interface module.

BL-1006

Message Interface module <slot number> NOT faulted. Peer interface module <slot number>

experienced abrupt failure.

Message Type LOG

Severity INFO

Probable Cause Indicates that the errors (mostly synchronization errors) on this interface module are harmless. Probably,

the standby management module connected to the active management module has experienced

transitory problems.

Recommended Action

Execute the **show ha** command to verify that the standby management module is healthy. If the problem persists, remove and reinstall the faulty interface module.

If the standby management module was removed or faulted by user intervention, no action is required.

BL-1007

Message

interface module #<interface module number>: interface module state is
inconsistent with EM. bl_cflags 0x<interface module control flags>, slot_on
<slot_on flag>, slot_off <slot_off flag>, faulty <faulty flag>, status <interface
module status>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a failover occurred while a interface module was initializing on the previously active

management module.

Recommended

Action

No action is required. The interface module is re-initialized. Because re-initializing a interface module is a disruptive operation and can stop I/O traffic, you must stop and restart the traffic during this process.

BL-1008

Message <slot string> control-plane failure. Expected value: 0x<value 1>, Actual: 0x<value

2>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the interface module has experienced a hardware failure or was removed without following

the recommended removal procedure.

Recommended

Action

Make sure that the interface module is seated correctly. If the interface module is seated correctly, reload or power cycle the interface module using the **power-off** and **power-on** commands.

Execute the diag systemverification command to verify that the interface module does not have

hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If the message persists, replace the interface module.

BL-1009

Message Interface module in slot <slot number> timed out initializing the chips.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the interface module has failed to initialize the application-specific integrated circuit (ASIC)

chips.

Recommended Make sure that the interface module is seated correctly. If the interface module is seated correctly, reload

Action or power cycle the interface module using the **power-off** and **power-on** commands.

Execute the diag systemverification command to verify that the interface module does not have

hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If the message persists, replace the interface module.

BL-1010

Message Interface module in <slot string> is inconsistent with the hardware settings.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that a failover occurred while some hardware changes (such as changing the domain ID) were

being made on the previously active management module.

Recommended No action is required. This interface module has been re-initialized. Because re-initializing a interface

module is a disruptive operation and can stop I/O traffic, you must stop and restart the traffic during this

process.

BL-1011

Message Busy with emb-port int for chip <chip number> in minis <mini-switch number> on

interface module <slot number>, chip int is disabled. Interrupt

status=0x<interrupt status>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that too many interrupts in the embedded port caused the specified chip to be disabled. The

probable cause is too many abnormal frames; the chip is disabled to prevent the management module

from becoming too busy.

Recommended Action

Make sure to capture the console output during this process.

Check for a faulty cable, small form-factor pluggable (SFP) transceiver, or device attached to the specified port.

Execute the **diag systemverification** command to verify that the interface module or switch does not have hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface module.

For a compact switch, reload or power cycle the switch.

If the message persists, replace the interface module or the switch.

BL-1012

Message

bport <interface module port number> port int is disabled. Status=0x<interrupt
status>; Port <port number> will be re-enabled in a minute.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the port generated an excessive number of interrupts that may prove unrecoverable to the switch operation. The port is disabled to prevent the management module from becoming too busy. The interface module port number displayed in the message may not correspond to a user port number.

Recommended

Action

Make sure to capture the console output during this process.

Check for a faulty cable, small form-factor pluggable (SFP) transceiver, or device attached to the specified port.

For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface module

For a compact switch, reload or power cycle the switch.

If the message persists, replace the interface module or the switch.

BL-1013

Message

bport <interface module port number> port is faulted. Status=0x<interrupt status>;
Port <port number> will be re-enabled in a minute.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the port generated an excessive number of interrupts that may prove fatal to the switch operation. The port is disabled to prevent the management module from becoming too busy. The interface module port number displayed in the message may not correspond to the user port number.

Recommended Action

Make sure to capture the console output during this process.

Check for a faulty cable, small form-factor pluggable (SFP) transceiver, or device attached to the specified port.

For a modular switch, execute the power-off and power-on commands to power cycle the interface module.

For a compact switch, reload or power cycle the switch.

If the message persists, replace the interface module or the switch.

BL-1014

Message

bport <interface module port number> port int is disabled. Status=0x<interrupt status>.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the port generated an excessive number of interrupts that may prove fatal to the switch operation. The port is disabled to prevent the management module from becoming too busy. The interface module port number displayed in the message may not correspond to the user port number.

Recommended Action Make sure to capture the console output during this process.

For a modular switch, execute the power-off and power-on commands to power cycle the interface

module.

For a compact switch, execute the **reload** command to reload the switch.

Execute the diag systemverification command to determine if there is a hardware error.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If there is a hardware error, the **power-off** or **power-on** command fails on the modular switch, or the errors are encountered again, replace the interface module or the switch.

BL-1015

Message

bport <interface module port number> port is faulted. status=0x<interrupt status>.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the port generated an excessive number of interrupts that may prove fatal to the switch operation. The port is disabled to prevent the management module from becoming too busy. The interface module port number displayed in the message may not correspond to the user port number.

Recommended Action

Make sure to capture the console output during this process.

For a modular switch, execute the power-off and power-on commands to power cycle the interface

module.

For a compact switch, execute the **reload** command to reload the switch.

Execute the diag systemverification command to determine if there is a hardware error.

Execute the diag post command to ensure that Power-On Self-Test (POST) is enabled.

If there is a hardware error, the power-off or power-on command fails on the modular switch, or the

errors are encountered again, replace the interface module or the switch.

BL-1016

Message Interface module port <port number> in <slot string> failed to enable.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified interface module port could not be enabled.

Recommended

Action

Make sure that the interface module is seated correctly. If the interface module is seated correctly, reload

or power cycle the interface module using the ${\bf power-off}$ and ${\bf power-on}$ commands.

Execute the diag systemverification command to verify that the interface module does not have

hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If the message persists, replace the interface module.

BL-1017

Message <slot string> Initializing.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified slot has started initializing the ports.

Recommended

No action is required.

Action

BL-1018

Message <slot string> Initialization completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified slot has completed initializing the ports.

Recommended No action is required.

Action

BL-1019

Message <Slot string>, retry <Retry Number>, internal port retry initialization, <List of

internal ports retrying initialization>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified slot had internal ports that are not online. Initiated a retry on ports that failed

to go online.

Recommended No action is required.

Action

BL-1020

Message Switch timed out initializing the chips.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that the switch has failed to initialize the application-specific integrated circuit (ASIC) chips.

Recommended Reload power cycle the switch.

Execute the diag systemverification command to verify that the switch does not have hardware

problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If the message persists, replace the switch.

Message Retry <Retry Number>, internal port retry initialization, <List of internal ports

retrying initialization>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch had internal ports that are not online. Initiated a retry on ports that failed to go

online.

Recommended

No action is required.

Action

BL-1022

Message Init Failed: Switch DISABLED because internal ports were not ONLINE, st of

internal port number not ONLINE>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the switch initiation failed because one or more of the internal ports were not online. The

switch is faulted.

Recommended Reload or power cycle the switch.

Action

Execute the diag systemverification command to verify that the switch does not have hardware

problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

Additional fault messages precede and follow this error providing more information. Refer to other error

messages for recommended action.

If the message persists, replace the switch.

BL-1023

Message Interface module in <slot string> was reset before initialization completed. As a

result the interface module is faulted.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the interface module was reset before the initialization completed.

Recommended Reload or power cycle the interface module using the power-off and power-on commands. If the

Action message persists, replace the interface module.

BL-1024

Message All ports on the interface module in <slot string> will be reset as part of the

firmware upgrade.

Message Type LOG

Severity INFO

Probable Cause Indicates that a recent firmware upgrade caused the interface module firmware to be upgraded and

resulted in a cold upgrade. As part of the upgrade, all data path elements were reset.

Recommended

Action

No action is required.

BL-1026

Message Internal port offline during warm recovery, state <port state> (0x<port ID>).

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that an internal port went offline during warm recovery of the switch. The switch will reboot and

start a cold recovery.

Recommended Execute the **copy support** command and reload the switch.

Action Execute the diag post command to make sure Power-On Self-Test (POST) is enabled.

If the problem persists, replace the switch.

BL-1027

Message Interface module in <slot string> faulted, boot failed; status 0x<boot status>

0x<1250 0 boot status> 0x<1250 1 boot status>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the interface module failed to boot properly.

Recommended Reload or power cycle the interface module using the **power-off** and **power-on** commands. If the

Action message persists, replace the interface module.

Message Switch faulted; internal processor was reset before switch init completed.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the switch internal processor was reset before the initialization completed.

Recommended Reload or power cycle the switch. If the message persists, replace the switch.

Action

BL-1029

Message All ports on the switch will be reset as part of the firmware upgrade.

Message Type LOG

Severity INFO

Probable Cause Indicates that a recent firmware upgrade caused the switch internal processor firmware to be upgraded

and resulted in a cold upgrade. As part of the upgrade, all data path elements were reset.

Recommended No action is required.

Action

BL-1031

Message Link timeout in internal port (slot <slot number>, port <port number>) resulted in

interface module fault. Use power-off/power-on commands to recover the interface

module.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that link time out occurred in one of the back-end internal ports.

Recommended Power cycle the interface module using the **power-off** and **power-on** commands.

Action

BL-1032

Message (<slot string>,bitmap 0x<object control flags(bitmap)>) ports never came up ONLINE

(reason <reason for port disable>, state <status of the interface module>).

Disabling slot.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the back-end (non-user) ports have not come online within the time limit.

Recommended Reload or power cycle the interface module using the **power-off** and **power-on** commands.

Action Execute the diag systemverification command to verify that the interface module does not have

hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If the message persists, replace the interface module.

BL-1033

Message (<slot string>,bitmap 0x<object control flags(bitmap)>) No disable acknowledgment

from ports (state <status of the interface module>). Disabling slot.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the system has timed out waiting for the disable acknowledgment messages from the user

ports.

Recommended Reload or power cycle the interface module using the **power-off** and **power-on** commands.

Action Execute the diag systemverification command to verify that the interface module does not have

hardware problems.

Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

If the message persists, replace the interface module.

BL-1034

Message <slot string> CEE initialization completed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified slot has completed initializing the Converged Enhanced Ethernet (CEE)

ports.

Recommended No action is required.

Action

Message Faulting chip in <slot string>, miniS = <mini-switch number>,port = <port number>

due to BE/BI port fault.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that all ports on the chip have been disabled due to a fault on the chip.

Recommended Execute the **diag systemverification** command to determine if there is a hardware error.

Action Execute the diag post command to make sure that Power-On Self-Test (POST) is enabled.

BL-1038

Message Inconsistent FPGA image version detected, reload the switch for recovery.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the field-programmable gate array (FPGA) image version is incompatible with the software

version.

Recommended Reload the switch. If the message persists, replace the switch.

Action

BL-1039

Message Inconsistent FPGA image version detected, faulting the interface module in <slot

string>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the field-programmable gate array (FPGA) image version is incompatible with the software

version.

Recommended Power cycle the interface module using the **power-off** and **power-on** commands. If the message

Action persists, replace the interface module.

7 ві

BL-1045

BL-1045

Message

mini SFP+ (SN: <mini SFP+ serial number>) is only supported in certain high port count interface modules, not interface module in slot <slot number of interface module that has the mini SFP+> with ID <Interface module ID of interface module that has the mini SFP+ that does not support it>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the mini (form factor) enhanced small form-factor pluggable (SFP+) transceiver is

supported only by a certain type of interface module, but it can be inserted in other interface modules.

Recommended Action

Replace the mini SFP+ transceiver with an SFP or SFP+ transceiver.

BL-1046

Message

<Slot number of interface module that has the SFP> error on SFP in Slot <Port
number into which the SFP is inserted>/Port <The type of error 'checksum' or 'data
access' for general problems accessing the i2c accessible data> (<A detailed error
code>). Reseat or replace the SFP.

Message Type LOG

Severity ERROR

Probable Cause Indicates that checksum in an area on the small form-factor pluggable (SFP) transceiver does not match

with the computed value or there is problem accessing the data.

Recommended

Action

Reseat the SFP transceiver. If the problem persists, replace the SFP transceiver.

BL-1047

Message Buffer optimized mode is turned <buffer optimized mode> for slot <slot number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the buffer optimized mode is changed for the specified slot.

Recommended No action is required.

Action

BLL Messages

BLL-1000

Message

ASIC driver detected <slot string> port <port number> as faulty (reason: <reason code>).

Message Type

FFDC | LOG

Severity

CRITICAL

Probable Cause

Indicates that an interface module regulation problem was reported on the specified slot. The interface module is faulted.

The reason codes are as follows:

- 1 = Available buffer overflow
- 2 = Backend port buffer timeout
- 3 = Backend port got shut down
- 4 = Embedded port buffer timeout
- 5 = Excessive busy mini buffer
- 6 = Excessive RCC VC on E Port
- 7 = Excessive RCC VC on FL_Port
- 8 = Fail detection buffer tag error
- 9 = Fail detection TX parity error
- 10 = EPI CMEM interrupt error
- 11 = Checkpoint Middleware Interface (CMI) interrupt error
- 12 = Interrupt overrun
- 13 = FDET interrupt
- 14 = Interrupt suspended
- 15 = Filter LISTD error
- 16 = Unknown filter LIST error
- 17 = Wait for LPC open state
- 18 = Wait for Old port state
- 19 = Wait for Open init state
- 20 = TX parity error
- 21 = RAM parity error
- 22 = Built in Self Repair (BISR) or RAMINIT error

Recommended Action

Make sure the interface module is seated correctly. If the interface module is seated correctly, reload or power cycle the interface module using the **power-off** and **power-on** commands.

Execute the **diag systemverification** command to verify that the interface module does not have hardware problems.

If the message persists, replace the interface module.

C2 Messages

C2-1004

Message S<slot number>,C<chip index>: Invalid DMA ch pointer, chan:<channel number>,

good_addr:0x<good address> bad_addr:0x<bad address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal error in the application-specific integrated circuit (ASIC) hardware that may degrade

the data traffic.

Recommended Restart the system at the next maintenance window. If the problem persists, replace the interface

Action module.

C2-1006

Message S<slot number>,C<chip index>: Internal link errors have been reported, no hardware

faults identified, continuing to monitor for errors: fault1:<fault1_count>,

fault2:<fault2_count>, thresh1:0x<threshold_used>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some internal link errors have been detected. These errors can be normal in an active

running system.

The system automatically starts a more detailed monitoring of the errors reported in the internal hardware. There is no action required by the user at this time. If any actual hardware failures are

detected, the C2-1010 message will be generated identifying the failing field-replaceable unit (FRU).

Recommended

Action

No action is required.

C2-1007

Message S<slot number>,P<port number> (<interface module port number>): At next port state

change, best effort QoS will be turned off automatically as it is no longer

supported under this configuration.

Message Type LOG

Severity WARNING

Probable Cause Indicates that quality of service (QoS) will be turned off automatically at next port state change because

best effort is no longer supported on 4 Gbps or 8 Gbps platform long distance ports.

Recommended

No action is required.

Action

C2-1008

Message S<slot number>,P<port number> (<interface module port number>): QoS overwrites

vc-link-init idle. ARB will be used on the link.

Message Type LOG

Severity WARNING

Probable Cause Indicates that quality of service (QoS) overwrites the fill word IDLE used in the long distance links.

Arbitrated loop (ARB) will be used on the link.

Recommended No a

Action

No action is required.

C2-1009

Message S<slot number>,P<port number> (<interface module port number>): vc-link-init arb

overwrites fill word IDLE. ARB will be used on the link.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the vc-link-init arb command has overwritten the fill word IDLE. Arbitrated loop (ARB) will

be used on the link.

Recommended

Action

No action is required.

C2-1010

Message S<slot number>,C<chip index>: Internal monitoring of faults has identified suspect

hardware, interface module may need to be reset or replaced:

fault1:<fault1_count>, fault2:<fault2_count>, thresh2:0x<threshold_used>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that above normal errors were observed in hardware that may or may not impact the data

traffic.

Recommended Whenever the error is observed persistently, power cycle the specified interface module using the

Action power-off and power-on commands. If the problem persists, replace the interface module.

7 c2-1011

C2-1011

Message S<slot number>,P<port number> (<interface port number>): Primitive received with

Encoding errors, do AL_RESET.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates encoding errors on the internal links. This error can cause cyclic redundancy check (CRC)

errors or frame loss.

Recommended Whenever the error is observed persistently, power cycle the specified interface module using the

power-off and power-on commands. If the problem persists, check the backplane or replace the

interface module.

C2-1012

Message S<slot number>,P<port number> (<interface module port number>): Link Timeout on

internal port ftx=<frame transmitted> tov=<real timeout value> (><expected

timeout value>), interface module may need to be reset or replaced.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that above normal errors were observed in hardware that may or may not impact the data

traffic.

Recommended Whenever the error is observed persistently, power cycle the specified interface module using the

power-off and **power-on** commands. If the problem persists, replace the interface module.

C3 Messages

C3-1004

Message <slot string>,C<chip index>: Invalid DMA ch pointer, chan:<channel number>,

good_addr:0x<good address> bad_addr:0x<bad address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal error in the application-specific integrated circuit (ASIC) hardware that may degrade

the data traffic.

Recommended Reload the system at the next maintenance window. If the problem persists, replace the interface

Action module.

C3-1006

Message <slot string>,C<chip index>: Various non-critical hardware errors were observed:

fault1:0x<fault1_count>, fault2:0x<fault2_count>, thresh1:0x<threshold used>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some errors were found in hardware that may or may not impact the data traffic.

Recommended No action is required.

Action

C3-1010

Message <slot string>,C<chip index>: Above normal hardware errors were observed:

fault1:<fault1_count>, fault2:<fault2_count>, thresh2:0x<threshold used>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that above normal errors were observed in hardware that may or may not impact the data

traffic.

Recommended Whenever this error is observed persistently, power cycle the specified interface module using the

Action power-off and power-on commands. If the problem persists, replace the interface module.

7 c3-1011

C3-1011

Message Detected a complete loss of credit on internal back-end VC: Slot <slot string>,

Port <port number>(<interface module port number>) vc_no=<vc number>

crd(s)lost=<credit(s)lost>.

Message Type LOG

Severity INFO

Probable Cause Indicates that all credits have been lost on the specified virtual channel (VC) and port.

Recommended No action is required. The link will be reset to recover the credits.

Action

C3-1012

Message <slot string>,P<port number>(<interface module port number>): Link Timeout on

internal port ftx=<frame transmitted> tov=<real timeout value> (><expected

timeout value>) vc_no=<vc number> crd(s)lost=<credit(s) lost>

complete_loss:<complete credit loss>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that above normal errors were observed in hardware that may or may not impact the data

traffic.

Recommended Whenever this error is observed persistently, power cycle the specified interface module using the

power-off and **power-on** commands. If the problem persists, replace the interface module.

C3-1014

Message Link Reset on internal Port <slot string>,P<port number>(<interface module port

number>) vc_no=<vc number> crd(s)lost=<credit(s) lost>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that one or more credits were lost and the link is reset.

Recommended Whenever this error is observed persistently, power cycle the specified interface module using the

Action power-off and **power-on** commands. If the problem persists, replace the interface module.

C3-1017

Message Interface module in Slot-<slot string> failed due to unavailability of ports in

the internal trunk.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the specified interface module failed due to unavailability of ports in the internal trunk.

Recommended Whenever this error is observed persistently, power cycle the specified interface module using the

power-off and **power-on** commands. If the problem persists, replace the interface module.

C3-1019

Message <slot string>,C<chip index>: HW ASIC Chip TXQ FID parity error threshold reached

type = 0x<chip error type>.

Message Type LOG

Severity WARNING

Probable Cause Indicates an internal error in the application-specific integrated circuit (ASIC) hardware that may degrade

the data traffic.

Recommended Reload the system at the next maintenance window.

Action

C3-1020

Message <slot string>,P<port number>(<interface module port number>): Some non-critical

CRC with good EOF errors were observed: current:0x<last_crc_good_eof_cnt>,

last:0x<total_crc_good_eof_cnt>, thresh1:0x<threshold_used>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that some non-critical errors were detected in the hardware.

Recommended No action is required.

CHS Messages

CHS-1002

Message ki_gd_register_action failed with rc = <return value>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates an internal error.

Recommended Reload or power cycle the switch.

Action

CHS-1003

Message Slot ENABLED but Not Ready during recovery, disabling slot = <slot number>, rval =

<return value>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the slot state has been detected as inconsistent during failover or recovery.

Recommended For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface

Action module.

For a compact switch, reload or power cycle the switch.

CHS-1004

Message Interface module attach failed during recovery, disabling slot = <slot number>,

rval = <return value>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified interface module has failed during failover or recovery.

Recommended For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface

Action module.

For a compact switch, reload or power cycle the switch.

CHS-1005

Message Diag attach failed during recovery, disabling slot = <slot number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the diagnostic interface module attach operation has failed during failover or recovery.

Recommended For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface

Action module

For a compact switch, reload or power cycle the switch.

DCM Messages

DCM-1001

Message VCS ID is changed from <Previous Vcs Id> to <New Vcs Id>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the VCS ID has been changed.

Recommended No action is required.

Action

DCM-1002

Message PostBoot processing on <Configuration name> has started.

Message Type LOG

Severity INFO

Probable Cause Indicates that the PostBoot processing on specified configuration group has started.

Recommended No action is required.

Action

DCM-1003

Message PostBoot processing on <Configuration name> is complete.

Message Type LOG

Severity INFO

Probable Cause Indicates that the PostBoot processing on specified configuration group has been completed.

Recommended No action is required.

DCM-1004

Message Configuration File Replay has started.

Message Type LOG

Severity INFO

Probable Cause Indicates that the configuration replay has started.

Recommended No action is required.

Action

DCM-1005

Message Configuration Replay is complete.

Message Type LOG

Severity INFO

Probable Cause Indicates that the configuration replay has been completed.

Recommended No action is required.

Action

DCM-1006

Message Event: <Event Name>, Status: <Command status>, User command: <ConfD hpath string>.

Message Type AUDIT

Class DCMCFG

Severity INFO

Probable Cause Indicates that the user command has been executed successfully.

Recommended No action is required.

DCM-1007

Message No Configuration File Replay.

Message Type LOG

Severity INFO

Probable Cause Indicates that configuration file replay will not happen on this system boot up.

Recommended No action is required.

Action

DCM-1008

Message Configuration has been reset to default due to changes in configuration metadata.

Message Type LOG

Severity INFO

Probable Cause Indicates that the configuration schema has changed and therefore the old configuration cannot be

retained

Recommended Replay the saved configuration manually.

Action

DCM-1009

Message RBridge ID is set to <Rbridge-id>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the RBridge ID has changed to the specified value.

Recommended No action is required.

Action

DCM-1010

Message Operation of setting RBridge ID to <Rbridge-id> failed.

Message Type LOG

Severity INFO

Probable Cause Indicates a failure while changing the RBridge ID.

Recommended

No action is required.

Action

DCM-1011

Message VCS enabled: VCS ID is set to <New Vcs Id>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the VCS mode has been enabled.

Recommended No action is required.

Action

DCM-1012

Message VCS disabled: VCS ID is set to <New Vcs Id>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the VCS mode has been disabled.

Recommended No action is required.

Action

DCM-1101

Message Copy running-config to startup-config operation successful on this node.

Message Type LOG

Severity INFO

Probable Cause Indicates that the running configuration has been copied to the startup configuration on the node.

Recommended No action is required.

7 D

DCM-1102

Message Copy running-config to startup-config operation failed on this node.

Message Type LOG

Severity INFO

Probable Cause Indicates failure to copy the running configuration to the startup configuration on the node.

Recommended No action is required.

Action

DCM-1103

Message Copy default-config to startup-config operation successful on this node.

Message Type LOG

Severity INFO

Probable Cause Indicates that the default configuration has been copied to the startup configuration on the node.

Recommended No action is required.

Action

DCM-1104

Message Copy default-config to startup-config operation failed on this node.

Message Type LOG

Severity INFO

Probable Cause Indicates failure to copy the default configuration to the startup configuration on the node.

Recommended No action is required.

Action

DCM-1105

Message Copy of the downloaded config file to the current running-config has completed

successfully on this node.

Message Type LOG

Severity INFO

Probable Cause Indicates that the downloaded configuration file has been copied to the current running configuration.

Recommended

No action is required.

Action

DCM-1106

Message Copy of the downloaded config file to the current startup-config has completed

successfully on this node.

Message Type LOG

Severity INFO

Probable Cause Indicates that the downloaded configuration file has been copied to the current startup configuration.

Recommended No action is required.

Action

DCM-1107

Message Startup configuration file has been uploaded successfully to the remote location.

Message Type LOG

Severity INFO

Probable Cause Indicates that the startup configuration file has been uploaded successfully.

Recommended No action is required.

Action

DCM-1108

Message Running configuration file has been uploaded successfully to the remote location.

Message Type LOG

Severity INFO

Probable Cause Indicates that the running configuration file has been uploaded successfully.

Recommended No action is required.

DCM-1109

Message Error (<error string>) encountered while copying configuration to flash/USB.

Message Type LOG

Severity INFO

Probable Cause Indicates a failure to copy configuration file to flash.

Recommended No action is required.

Action

DCM-1201

Message FIPS Zeroize operation request received.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Federal Information Protection Standard (FIPS) Zeroize operation request has been

received.

Recommended No action is required.

Action

DCM-1202

Message FIPS Zeroize operation: failed as VCS is enabled for this node.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Federal Information Protection Standard (FIPS) Zeroize operation has failed because

VCS is enabled on the node.

Recommended Execute the **no vcs enable** command to disable the VCS mode and then perform the Zeroize operation.

DCM-1203

Message FIPS Zeroize operation: confirmed that VCS is not enabled for this node.

Message Type LOG

Severity INFO

Probable Cause Indicates that VCS is not enabled on the node and therefore the Federal Information Protection Standard

(FIPS) Zeroize operation will proceed.

Recommended N

Action

No action is required.

DCM-1204

Message FIPS Zeroize operation: all client sessions are notified that Zeroize in progress.

Message Type LOG

Severity INFO

Probable Cause Indicates that all client sessions are notified about the Federal Information Protection Standard (FIPS)

Zeroize operation in progress and the commands cannot be executed.

Recommended

Action

No action is required.

DCM-1205

Message FIPS Zeroize operation: starting with cleanup for Zeroize.

Message Type LOG

Severity INFO

Probable Cause Indicates that the configuration files cleanup for Federal Information Protection Standard (FIPS) Zeroize

has started.

Recommended

Action

No action is required.

DCM-1206

Message FIPS Zeroize operation: starting prepare phase for Zeroize.

Message Type LOG

Severity INFO

Probable Cause Indicates that the prepare phase for Federal Information Protection Standard (FIPS) Zeroize has started,

during which all the services will be shut down.

Recommended

Action

No action is required.

DCM-1207

Message FIPS Zeroize operation: failed in prepare phase step for Zeroize.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Federal Information Protection Standard (FIPS) Zeroize operation has failed during the

prepare phase.

Recommended

Action

No action is required.

DCM-1208

Message FIPS Zeroize operation: Running Zeroize for secure deletion of the user

configuration data.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Federal Information Protection Standard (FIPS) Zeroize operation is running for secure

deletion of the user configuration data.

Recommended

No action is required.

DCM-1209

Message FIPS Zeroize operation: failed during secure deletion of the user configuration

data.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Federal Information Protection Standard (FIPS) Zeroize operation has failed during

secure deletion of the user configuration data.

Recommended Refer to the reason code indicated in the **fips zeroize** command output for possible action.

Action

DCM-1210

Message FIPS Zeroize operation failed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Federal Information Protection Standard (FIPS) Zeroize operation has failed.

Recommended No action is required.

Action

DCM-1211

Message FIPS Zeroize operation executed successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Federal Information Protection Standard (FIPS) Zeroize operation has been executed

successfully.

Recommended No action is required.

DCM-1212

Message FIPS Zeroize operation failed. Node zeroizing or already zeroized.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Federal Information Protection Standard (FIPS) Zeroize operation has failed because

the node is zeroizing or it was already zeroized.

Recommended No action is required.

Action

DCM-2001

Message Event: <Event Name>, Status: success, Info: Successful login attempt through

<connection method and IP Address>.

Message Type AUDIT

Class DCMCFG

Severity INFO

Probable Cause Indicates that the log in was successful. An IP address is displayed when the login occurs over a remote

connection.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

DCM-2002

Message Event: <Event Name>, Status: success, Info: Successful logout by user [<User>].

Message Type AUDIT

Class DCMCFG

Severity INFO

Probable Cause Indicates that the specified user has successfully logged out.

Recommended No action is required.

DCM-3005

Message DCM ASSERT Service:<message>

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal failure in the distributed configuration manager (DCM).

Recommended Execute the **copy support** command and contact your switch service provider.

Action

DCM-3051

Message Encountered Database Corruption. System going down for auto-recovery.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the database operation failed because of database corruption. The system reloads for

auto-recovery of the database.

Recommended No action is required.

Action

DCM-3052

Message Database Corruption was detected. Therefore, system was rebooted for recovery and

may have taken longer than usual.

Message Type LOG

Severity INFO

Probable Cause Indicates that the last system reload was for auto-recovery of database because the database corruption

was detected.

Recommended No action is required.

DCM-4001

Message Database schema conversion succeeded.

Message Type LOG

Severity INFO

Probable Cause Indicates that after a firmware download, the database schema was successfully converted to the

schema supported by the firmware.

Recommended No action is required.

Action

DCM-4002

Message Database schema conversion failed.

Message Type LOG

Severity INFO

Probable Cause Indicates that after a firmware download, a failure was encountered in converting the database schema

to the schema supported by the firmware.

Recommended

Action

No action is required.

DOT1 Messages

DOT1-1001

Message 802.1% is enabled globally.

Message Type DCE

Severity INFO

Probable Cause Indicates that 802.1X is enabled globally.

Recommended No action is required.

Action

DOT1-1002

Message 802.1% is disabled globally.

Message Type DCE

Severity INFO

Probable Cause Indicates that 802.1X is disabled globally.

Recommended No action is required.

Action

DOT1-1003

Message 802.1% is enabled for port <port_name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that 802.1X is enabled on the specified port.

Recommended No action is required.

DOT1-1004

Message Port <port_name> is forcefully unauthorized.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified port has been unauthorized forcefully using the dot1x port-control

force-unauthorized command.

Recommended No action is required.

Action

DOT1-1005

Message 802.1% authentication is successful on port <port_name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that authentication has succeeded on the specified port.

Recommended No action is required.

Action

DOT1-1006

Message 802.1X authentication has failed on port <port_name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that authentication has failed on the specified port due to incorrect credentials or the remote

authentication dial-in user service (RADIUS) server is not functioning properly.

Recommended Check the credentials configured with the supplicant and RADIUS server. You can reconfigure the

Action attributes on the RADIUS server using the radius-server command.

DOT1-1007

Message No RADIUS server available for authentication.

Message Type DCE

Severity CRITICAL

Probable Cause Indicates that there is no remote authentication dial-in user service (RADIUS) server available for

authentication.

Recommended Check whether the configured RADIUS servers are reachable and are functioning.

Action

DOT1-1008

Message Port <port_name> is forcefully authorized.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified port has been authorized forcefully using the dot1x port-control

forced-authorized command.

Recommended No action is required.

Action

DOT1-1009

Message 802.1X is disabled for port <port_name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that 802.1X is disabled on the specified port.

Recommended No action is required.

7 DOT1-1010

DOT1-1010

Message Port <port_name> is set in auto mode.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified port is set to auto mode.

Recommended No action is required.

Action

DOT1-1011

Message DOT1X_PORT_EAPOL_CAPABLE: Peer with MAC <mac1><mac2>.<mac3><mac4>.<mac5><mac6>

connected to port <port_name> is EAPOL Capable.

Message Type DCE

Severity INFO

Probable Cause Indicates that the peer connected to the specified port is DOT1X-capable.

Recommended No action is required.

Action

DOT1-1012

Message DOT1X_PORT_EAPOL_CAPABLE: Peer connected to port port_name> is NOT EAPOL capable.

Message Type DCE

Severity INFO

Probable Cause Indicates that the peer connected to the specified port is not DOT1X-capable.

Recommended No action is required.

Action

DOT1-1013

Message DOT1X test timeout value is set to <Updated test timeout value>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the DOT1X test timeout value has been changed to the specified value.

Recommended No Action

No action is required.

EANV Messages

EANV-1001

Message Port <port number> port fault. Change the SFP transceiver or check the cable.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates a deteriorated small form-factor pluggable (SFP) transceiver, an incompatible SFP transceiver

pair, or a faulty cable between the peer ports.

Recommended Verify that compatible SFP transceivers are used on the peer ports, the SFP transceivers have not

deteriorated, and the Fibre Channel cable is not faulty. Replace the SFP transceivers or the cable if

necessary.

EANV-1002

Message Port <port number> chip faulted due to an internal error.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates an internal error. All the ports on this chip will be disabled.

Recommended Reload the system at the next maintenance window.

Action

EANV-1003

Message C<chip index>: HW ASIC Chip error. Type = 0x<chip error type>, Error = <chip error

string>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates an internal error in the application-specific integrated circuit (ASIC) hardware that may degrade

the data traffic.

Recommended Reload the system at the next maintenance window.

EANV-1004

Message C<chip index>: Invalid DMA ch pointer, chan:<Channel number>, good_addr:0x<Good

address> bad_addr:0x<Bad address>.

Message Type LOG

Severity ERROR

Probable Cause Indicates an internal error in the application-specific integrated circuit (ASIC) hardware that may degrade

the data traffic.

Recommended No action is required. The software will recover from the error.

Action

EANV-1005

Message C<chip index>,A<eanvil id>: Memory allocation failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates memory allocation failure in the software.

Recommended Reload the system at the next maintenance window. If the problem persists, replace the switch or contact

Action your switch service provider.

EANV-1006

Message C<chip index>: HW ASIC Chip fault. Type = 0x<chip error type>, Error = <chip error

string>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates an internal error in the application-specific integrated circuit (ASIC) hardware that renders the

chip not operational.

Recommended Reload the system at the next maintenance window. If the problem persists, replace the switch or contact

Action your switch service provider.

ELD Messages

ELD-1001

Message Interface <InterfaceName> is shut down by edge loop detection (ELD) for loop in

VLAN <VLAN ID>.

Message Type DCE

Severity INFO

Probable Cause Indicates that a loop has been detected by the edge loop detection (ELD) protocol on the specified

interface. The interface has been shut down.

Recommended Identify and fix the Layer 2 bridging loop and then re-enable the interface using the clear

Action edge-loop-detection command.

ELD-1002

Message Interface <InterfaceName> is auto-enabled by edge loop detection (ELD).

Message Type DCE

Severity INFO

Probable Cause Indicates that the interface on which a loop was detected has been auto-enabled based on the

configured shutdown time.

Recommended No action is required.

EM Messages

EM-1001

Message <FRU ID> is overheating: Shutting down.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that a field replaceable unit (FRU) is shutting down due to overheating. Overheating is mainly

due to a faulty fan and can also be caused by the switch environment.

Recommended Verify that the location temperature is within the operational range of the switch.

Action Execute the **show environment fan** command to verify that all fans are running at normal speeds.

Replace fans that are missing or not performing at high enough speeds.

EM-1002

Message System fan(s) status <fan FRU>.

Message Type LOG | FFDC

Severity INFO

Probable Cause Indicates that a compact system has overheated and may shut down. All the fan speeds are dumped to

the console.

Recommended Verify that the location temperature is within the operational range of the switch.

Action Execute the **show environment fan** command to verify that all fans are running at normal speeds.

Replace fans that are missing or not performing at high enough speeds.

EM-1003

Message <FRU ID> has unknown hardware identifier: FRU faulted.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that a field-replaceable unit (FRU) header cannot be read or is invalid. The FRU is faulted.

Recommended Reload or power cycle the switch.

Action Execute the diag systemverification command to verify that the switch does not have hardware

problems.

EM-1004

Message <FRU ID> failed to power on.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified field-replaceable unit (FRU) failed to power on and is not being used. The

FRU ID value is composed of a FRU type string and an optional number to identify the unit, slot, or port.

Recommended Reseat the FRU. If the problem persists, replace the FRU.

Action

EM-1005

Message <FRU Id> has faulted. Sensor(s) above maximum limits.

Message Type FFDC | LOG

Action

Severity CRITICAL

Probable Cause Indicates that an interface module in the specified slot or the switch (for compact switches) is being shut

down for environmental reasons; its temperature or voltage is out of range.

Recommended Check the environment and make sure the room temperature is within the operational range of the

switch. Execute the **show environment fan** command to verify fans are operating properly. Make sure there are no blockages of the airflow around the chassis. If the temperature problem is isolated to the

interface module itself, replace the interface module.

Voltage problems on a interface module are likely a hardware problem on the interface module itself;

replace the interface module.

EM-1006

Message <FRU Id> has faulted. Sensor(s) below minimum limits.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the sensors show the voltage is below minimum limits. The switch or specified interface

module is being shut down for environmental reasons; the voltage is too low.

Recommended If this problem occurs on an interface module, it usually indicates a hardware problem on the interface

Action module; replace the interface module.

If this problem occurs on a switch, it usually indicates a hardware problem on the main board; replace the

switch.

EM-1008

Message Unit in <Slot number or Switch> with ID <FRU Id> is faulted, it is incompatible

with the <type of incompatibility> configuration, check firmware version as a

possible cause.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that an interface module inserted in the specified slot or the switch (for compact switches) is not

compatible with the platform configuration (includes the firmware version). The interface module is

faulted.

Recommended

Action

If the interface module is not compatible, upgrade the firmware or replace the interface module and make sure the replacement interface module is compatible with your management module type and firmware.

EM-1009

Message <FRU Id> powered down unexpectedly.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the environmental monitor (EM) received an unexpected power-down notification from the

specified field-replaceable unit (FRU). This may indicate a hardware malfunction in the FRU.

Recommended

Action

Reseat the FRU. If the problem persists, replace the FRU.

EM-1010

Message Received unexpected power down for <FRU Id> but <FRU Id> still has power.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the environmental monitor (EM) received an unexpected power-down notification from the

specified field-replaceable unit (FRU). However, the specified FRU still appears to be powered up after 4

seconds.

Recommended Action

ed Reseat the interface module. If the problem persists, replace the interface module.

EM-1011

Message Received unexpected power down for <FRU Id>, but cannot determine if it has power.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the environmental monitor (EM) received an unexpected power-down notification from the

specified field-replaceable unit (FRU). However, after 4 seconds it could not be determined if it has

powered down or not.

Recommended

Action

Reseat the interface module. If the problem persists, replace the interface module.

EM-1012

Message <FRU Id> failed <state> state transition, unit faulted.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that a switch interface module or compact switch failed to transition from one state to another. It

is faulted. The specific failed target state is displayed in the message. There are serious internal Network

OS configuration or hardware problems on the switch.

Recommended Reload or power cycle the switch.

Action Execute the diag system verifies

Execute the diag systemverification command to verify that the switch does not have hardware

problems.

If the problem persists, replace the FRU.

EM-1013

Message Failed to update FRU information for <FRU Id>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the environmental monitor (EM) was unable to update the time alive or original equipment

manufacturer (OEM) data in the memory of an field-replaceable unit (FRU).

Recommended The update is automatically attempted again. If it continues to fail, reseat the FRU.

Action If the problem persists, replace the FRU.

EM-1014

Message Unable to read sensor on <FRU Id> (<Return code>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the environmental monitor (EM) was unable to access the sensors on the specified

field-replaceable unit (FRU).

Recommended Reseat the FRU. If the problem persists, replace the FRU.

Action

EM-1015

Message Warm recovery failed (<Return code>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that a problem was discovered when performing consistency checks during a warm boot.

Recommended Monitor the switch. If the problem persists, reload or power cycle the switch.

Action

EM-1016

Message Cold recovery failed (<Return code>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that a problem was discovered when performing consistency checks during a cold boot.

Recommended Monitor the switch. If the message persists, execute the **copy support** command and contact your

Action switch service provider.

EM-1020

Message A problem was found on one or both CID cards (<The return code is for internal use

only.>), run the CIDrecov tool to get more information and recovery options.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a problem was found either accessing one (or both) of the CID cards or with the content of

the data stored there. The content problem could be a corrupted data set or a mismatch between the two

CID cards.

Recommended

Action

Execute the **CIDrecov** command to get details of the problems found and how to recover.

EM-1021

Message A CID card has been inserted, a CID verification audit will be run to detect any

mismatches or other problems.

Message Type LOG

Severity INFO

Probable Cause Indicates that the second CID card was enabled. Because the data may not match, the CID verification

audit will be run.

Recommended If an EM-1020 follows, execute the CIDrecov command to get details of the problems found and how to

Action recover. If not, no action is required.

FM-1022

Message A CID card access problem has been encountered, please run the CIDrecov tool to

get more information and recovery options.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a problem was encountered while accessing one (or both) of the 2 CID cards or with the

content of the data stored there.

Recommended Execute the **CIDrecov** command to get details of the problems found and how to recover.

EM-1023

Message Chassis fan airflow-direction <fan-direction> change is failed.

Message Type LOG

> Severity INFO

Probable Cause Indicates failure to change the fan airflow direction.

Recommended No action is required.

Action

EM-1024

Message Platform is not supported for changing the fan-airflow direction.

Message Type LOG

> Severity **INFO**

Probable Cause Indicates that the platform is not supported for changing the configuration.

Recommended No action is required.

Action

EM-1028

Message HIL Error: <function> failed to access history log for FRU: <FRU Id> (rc=<return

code>).

Message Type FFDC | LOG

> Severity WARNING

Probable Cause Indicates a problem accessing the data on the Chassis ID (CID) card field-replaceable unit (FRU) or the

World Wide Name (WWN) card storage area on the main logic board.

The problems were encountered when the software attempted to write to the history log storage to record an event for the specified FRU. This error can indicate a significant hardware problem.

The FRU ID value is composed of a FRU type string and an optional number to identify the unit, slot, or

port. The return code is for internal use only.

Recommended If the problem persists, reload or power cycle the switch. **Action**

If the problem still persists, perform one of the following actions:

- For compact switches, replace the switch.
- For CID cards, run the CIDrecov tool to get more information.

EM-1029

Message <FRU Id>, a problem occurred accessing a device on the I2C bus (<error code>).

Operational status (<state of the FRU when the error occurred>) not changed,

access is being retried.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the inter-integrated circuit (I2C) bus had problems and a timeout occurred.

Recommended This is often a transient error.

Action Watch for the EM-1048 message, which indicates that the problem has been resolved.

If the error persists, check for loose or dirty connections. Remove all dust and debris prior to reseating

the field-replaceable unit (FRU). Replace the FRU if it continues to fail.

EM-1031

Message <FRU Id> ejector not closed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the environmental monitor (EM) has found a switch interface module that is inserted, but

the optical ejector switch is not latched. The interface module in the specified slot is treated as not

inserted.

Recommended Close the ejector switch (completely screw in the optical (middle) thumbscrew on the switch fabric

module (SFM)) if the field-replaceable unit (FRU) is intended for use. Refer to the appropriate Hardware

Reference Manual for instructions on inserting the switch interface modules.

EM-1033

Message MM in <FRU Id> set to faulty because MM ERROR asserted.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the standby management module has been detected as faulty. The high availability (HA)

feature will not be available. This message occurs every time the other management module reloads, even as part of a clean warm failover. In most situations, this message is followed by the EM-1047 message, and no action is required for the management module; however, find the reason for failover.

Recommended

Action

If the standby management module was just reloaded, wait for the error to clear (execute the **show slots** command to determine if the errors are cleared). Watch for the EM-1047 message to verify that this error has cleared.

If the standby management module continues to be faulty or if it was not intentionally reloaded, check the error logs on the other management module (using the **show logging raslog** command) to determine

the cause of the error state.

Reseat the field-replaceable unit (FRU). If the problem persists, replace the FRU.

EM-1034

Message <FRU Id> is set to faulty, rc=<return code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified field-replaceable unit (FRU) has been marked as faulty for the specified

reason.

Recommended Reseat the FRU.

Action

Execute the diag systemverification command to verify that the switch does not have hardware

problems.

If the problem persists, replace the FRU.

EM-1036

Message <FRU Id> is not accessible.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified field-replaceable unit (FRU) is not present on the switch.

If the FRU is a Chassis ID (CID) card, then the default WWN and IP addresses are used for the switch.

Recommended Reseat the FRU card.

Action

If the problem persists, reload or power cycle the switch.

Execute the diag systemverification command to verify that the switch does not have hardware

problems.

If the problem still persists, replace the FRU.

EM-1037

Message <FRU Id> is no longer faulted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified power supply is no longer marked faulty; probably because its AC power

supply has been turned on.

Recommended

Action

No action is required.

EM-1042

Message Important FRU header data for <FRU Id> is invalid.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified field-replaceable unit (FRU) has an incorrect number of sensors in its FRU

header-derived information. This could mean that the FRU header was corrupted or read incorrectly, or it

is corrupted in the object database, which contains information about all the FRUs.

Recommended

Action

Reseat the FRU. If the problem persists, replace the FRU.

EM-1043

Message Cannot power <FRU Id> <state (on or off)>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified field-replaceable unit (FRU) could not be powered on or off. The FRU is not

responding to commands.

Recommended

Reseat or replace the FRU.

EM-1045

Message <FRU Id> is being powered <new state>.

Message Type LOG

Severity WARNING

Probable Cause

Indicates that an automatic power adjustment is being made because of the (predicted) failure of a power supply or the insertion or removal of a port interface module.

The new state can be one of the following:

- On A port interface module is being powered on because more power is available (either a power supply was inserted or a port interface module was removed or powered down).
- Off A port interface module has been powered down because of a (predicted) failure of the power supply.
- Down A newly inserted port interface module was not powered on because there was not enough power available.

Recommended Action

Refer to the *Hardware Reference Manual* of your switch for the number of power supplies required for redundancy.

EM-1046

Message

Error status received for interface module ID <id value> for <FRU Id>, <interface module incompatibility type: platform>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified interface module is incompatible.

Recommended

Action

If the interface module ID listed is incorrect, the field-replaceable unit (FRU) header for the interface module is corrupted and the interface module must be replaced.

If the error is due to platform, the interface module ID listed is not supported for that platform (management module) type. Remove the interface module from the chassis.

EM-1047

Message <FRU Id> not faulty, MM ERROR deasserted.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the specified management module is no longer faulted. This message usually follows the EM-1033 message. The new standby management module is in the process of reloading and has turned off the MM_ERR signal.

7 EM-1048

Recommended

No action is required.

Action

EM-1048

Message <FRU Id> I2C access recovered: state <current state>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the inter-integrated circuit (I2C) bus problems have been resolved and the specified

field-replaceable unit (FRU) is accessible on the I2C bus.

Recommended No action is required. This message is displayed when the EM-1029 error is resolved.

Action

EM-1049

Message FRU <FRU Id> insertion detected.

Message Type LOG

Severity INFO

Probable Cause Indicates that the field-replaceable unit (FRU) of the specified type and location was inserted into the

chassis.

Recommended

Action

No action is required.

EM-1050

Message FRU <FRU Id> removal detected.

Message Type LOG

Severity INFO

Probable Cause Indicates that the field-replaceable unit (FRU) of the specified type and location was removed from the

chassis

Recommended Verify that the FRU was intended to be removed. Replace the FRU as soon as possible.

EM-1051

Message <FRU Id>: Inconsistency detected, FRU re-initialized.

Message Type LOG

Severity INFO

Probable Cause Indicates that an inconsistent state was found in the specified field-replaceable unit (FRU). This event

occurs when the state of the FRU was changing during a failover. The FRU is reinitialized and traffic may

have been disrupted.

Recommended

Action

No action is required.

EM-1059

Message <FRU Id or Switch name> with ID <Interface module Id> may not be supported on this

platform, check firmware version as a possible cause.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the interface module inserted in the specified slot or the switch (for compact switches) is

not compatible with the switch configuration software. The interface module will not be completely

usable.

The interface module may only be supported by a later (or earlier) version of the firmware.

Recommended

Action

Change the management module firmware or replace the interface module. Make sure the replacement

is compatible with your switch type and firmware.

EM-1064

Message <FRU Id> is being powered off (based on user configuration) upon receiving a HW

ASIC ERROR, reason: < Fault reason > .

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the interface module has been powered off because a hardware application-specific

integrated circuit (ASIC) error was detected, and you have selected to power off the problem interface

module when such a condition occurred.

Recommended

Action

Execute the **copy support** command and contact your switch service provider.

EM-1068

Message High Availability Service Management subsystem failed to respond. A required

component is not operating.

Message Type FFDC | LOG

Severity ERROR

Probable Cause Indicates that the high availability (HA) subsystem has not returned a response within 4 minutes of

receiving a request from the environmental monitor (EM). This event usually indicates that some component has not started properly or has terminated. The specific component that has failed may be indicated in other messages or debug data. There are serious internal Network OS configuration or

hardware problems on the switch.

Recommended Reload or power cycle the switch.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

EM-1069

Message <FRU slot identifier> is being powered off.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified interface module has been intentionally powered off.

Recommended

Action

No action is required.

EM-1070

Message <FRU slot identifier> is being powered on.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified interface module has been intentionally powered on.

Recommended

Action

No action is required.

EM-2003

Message

<FRU Id or switch for compact switches> has failed the POST tests. FRU is being faulted.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the specified field-replaceable unit (FRU) has failed the Power-On Self-Test (POST). Refer to the /tmp/post[1/2].slot#.log file for more information on the faults. To view this log file you must be logged in at the root level. The login ID is switch name for compact systems.

Recommended Action On modular systems, reseat the specified FRU.

On compact switches, reload or power cycle the switch.

If the problem persists:

- Execute the diag systemverification command to verify that the switch does not have hardware
- On modular systems, replace the specified FRU; For compact switch, replace the switch.

ERCP Messages

ERCP-1000

Message Multiple ECC errors are detected and the system will reload automatically.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that error checking and correction (ECC) errors occurred due to multi-bit corruption.

Recommended No action is required. The system will reload automatically to recover from the error.

ESS Messages

ESS-1008

Message Fabric Name - <fabric_name> configured (received from domain <domain ID>).

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified fabric name has been configured or renamed.

Recommended No action is required.

Action

ESS-1009

Message Fabric Name Mismatch - local (<fabric_name>) remote (<r_fabric_name> - received

from domain <domain ID>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified fabric name is not unique for this fabric.

Recommended Select an appropriate fabric name and set it again from any switch in the fabric.

Action

ESS-1010

Message Duplicate Fabric Name - <fabric_name> matching with FID <Fabric ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the configured fabric name is already used for another partition.

Recommended Select a different fabric name and reconfigure.

FABR Messages

FABR-1001

Message port <port number>, <segmentation reason>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the specified switch port is isolated because of a segmentation resulting from mismatched

configuration parameters.

Recommended Based on the segmentation reason displayed in the message, look for a possible mismatch of relevant

parameters in the switches at both ends of the link.

FABR-1003

Message port <port number>: ILS <command> bad size <payload size>, wanted <expected

payload size>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an internal link service (ILS) information unit of invalid size has been received. The

neighbor switch has sent a payload with an invalid size.

Recommended Investigate the neighbor switch for problems. Execute the show logging raslog command on the

Action neighbor switch to view the error log for additional messages.

Check for a faulty cable or deteriorated small form-factor pluggable (SFP) transceiver. Replace the cable

or SFP transceiver if necessary.

If the message persists, execute the copy support command and contact your switch service provider.

FABR-1004

Message port: <port number>, req iu: 0x<address of IU request sent>, state: 0x<command

sent>, resp iu: 0x<address of response IU received>, state 0x<response IU state>,

<additional description>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the information unit (IU) response was invalid for the specified command sent. The fabric

received an unknown response. This message is rare and usually indicates a problem with the Network

OS kernel.

Recommended Action

If this message is due to a one time event because of the incoming data, the system will discard the

16 41- ----

If the message persists, execute the copy support command and contact your switch service provider.

FABR-1005

Message <command sent>: port <port number>: status 0x<reason for failure> (<description of</pre>

failure reason>) xid = 0x<exchange ID of command>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the application failed to send an async command for the specified port. The message

provides additional details regarding the reason for the failure and the exchange ID of the command. This

can happen if a port is about to go down.

Recommended No action is required. This message is often transitory.

Action If the manage paraiete execute the convicument command and control

If the message persists, execute the copy support command and contact your switch service provider.

FABR-1006

Message Node free error, caller: <error description>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Network OS is trying to free or deallocate memory space that has already been

deallocated. This message is rare and usually indicates a problem with the Network OS.

Recommended

Action

If the message persists, execute the copy support command and contact your switch service provider.

FABR-1007

Message IU free error, caller: <function attempting to de-allocate IU>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a failure occurred when deallocating an information unit (IU). This message is rare and

usually indicates a problem with the Network OS.

Recommended If the message persists, execute the **copy support** command and contact your switch service provider.

FABR-1008

Message <error description>.

Message Type LOG

Severity WARNING

Probable Cause

Indicates that errors occurred during the request RBridge ID state; the information unit (IU) cannot be allocated or sent. If this message occurs with FABR-1005, the problem is usually transitory. Otherwise, this message is rare and usually indicates a problem with the Network OS. The error descriptions are as follows:

FAB RDI: cannot allocate IU
 FAB RDI: cannot send IU

Recommended Action

No action is required if the message appears with the FABR-1005 message.

If the message persists, execute the copy support command and contact your switch service provider.

FABR-1009

Message <error description>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that errors were reported during the exchange fabric parameter (EFP) state; cannot allocate

RBridge IDs list due to a faulty EFP type. This message is rare and usually indicates a problem with the

Network OS.

Recommended

The fabric daemon will discard the EFP. The system will recover through the EFP retrial process.

Action

If the manage projects available projects are projects as a project of the manage projects are projects as a project of the manage projects are projects.

If the message persists, execute the copy support command and contact your switch service provider.

FABR-1010

Message <error description>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that errors occurred while cleaning up the request RBridge ID (RDI). The error description

provides further details. This message is rare and usually indicates a problem with the Network OS.

Recommended

Action

If the message persists, execute the copy support command and contact your switch service provider.

FABR-1012

Message <function stream>: no such type, <invalid type>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric is not in the appropriate state for the specified process. This message is rare and

usually indicates a problem with the Network OS.

Recommended The fabric daemon will take proper action to recover from the error.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

FABR-1013

Message No Memory: pid=<fabric process id> file=<source file name> line=<line number

within the source file>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that there is not enough memory in the switch for the fabric module to allocate. This message is

rare and usually indicates a problem with the Network OS.

Recommended The system will recover by failing over to the standby management module.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

FABR-1014

Message Port <port number> Disabled: RBridge IDs overlap. Insistent RBridge ID <RBridge

ID> could not be obtained. Principal is trying to assign RBridge ID <RBridge ID>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the switch received an RBridge ID other than the one it requested. The port was disabled

because the requested insistent RBridge ID could not be obtained.

Recommended Change the RBridge ID of the local node (if applicable) using the vcs rbridge-id command. You can

toggle the disabled port using the fabric isl enable and no fabric isl enable commands after the

RBridge ID change.

FABR-1019

Message

Critical fabric size (<current RBridges>) exceeds supported configuration (<supported RBridges>).

Message Type

FFDC | LOG

Severity

CRITICAL

Probable Cause

Indicates that this switch is a value-line switch and has exceeded the configured fabric size: that is, a specified limit to the number of RBridges. This limit is defined by your specific value-line license key. The fabric size has exceeded this specified limit and the grace period counter has started.

Recommended

Action

Bring the fabric size within the licensed limits. Either a full fabric license must be added or the size of the fabric must be changed to within the licensed limit. Contact your switch provider to obtain a full fabric license.

FABR-1029

Message

Port port number> negotiated <flow control mode description> (mode = <received flow control mode>).

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that a different flow control mode, as described in the message, is negotiated with the port at the other end of the link. The flow control is a mechanism of throttling the transmitter port to avoid buffer overrun at the receiving port. There are three types of flow control modes:

- VC_RDY mode: Virtual-channel flow control mode. This is a proprietary protocol.
- R_RDY mode: Receiver-ready flow control mode. This is the Fibre Channel standard protocol, that uses R_RDY primitive for flow control.
- DUAL_CR mode: Dual-credit flow control mode. In both of the previous modes, the buffer credits are
 fixed, based on the port configuration information. In this mode, the buffer credits are negotiated as
 part of exchange link parameter (ELP) exchange. This mode also uses R_RDY primitive for flow
 control.

Recommended

Action

No action is required.

FABR-1030

Message

fabric: RBridge ID <new RBridge ID> (was <old RBridge ID>).

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that the RBridge ID has changed.

Recommended

No action is required.

Action

FABR-1039

Message Invalid RBridge ID zero received from principal switch (RBridge ID = <Principal

RBridge id>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that an invalid RBridge ID zero has been received.

Recommended Check the reason for the principal switch to assign an invalid RBridge ID zero.

Action

FABR-1041

Message Port <Port that is being disabled > is disabled due to trunk protocol error.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a link reset was received before the completion of the trunking protocol on the port.

Recommended Toggle the port using the **no fabric isl enable** and **fabric isl enable** commands.

Action

The port may recover by re-initialization of the link.

If the message persists, execute the **copy support** command and contact your switch service provider.

FABR-1055

Message Switch <Switchname> will be taken offline and back online for RBridge Id auto

configuration to take effect.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified switch has been bounced for the RBridge ID auto configuration to take effect

on the unconfigured VCS switch.

Recommended No action is required.

FABS Messages

FABS-1001

Message <Function name> <Description of memory need>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the system is low on memory and cannot allocate more memory for new operations. This is

usually an internal Network OS problem or file corruption. The Description of memory need variable

specifies the memory size that was being requested. The value could be any whole number.

Recommended Action

Reload or power cycle the switch.

FABS-1002

Message <Function name> <Description of problem>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an internal problem has been detected by the software. This is usually an internal Network

OS problem or file corruption.

Recommended Reload or power cycle the switch.

Action If the message persists, execute the **firmware download** command to update the firmware.

FABS-1004

Message <Function name and description of problem> process <Process ID number> (<Current

command name>) <Pending signal number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an operation has been interrupted by a signal. This is usually an internal Network OS

problem or file corruption.

Recommended Reload or power cycle the switch.

FABS-1005

Message <Function name and description of problem> (<ID type>= <ID number>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that an unsupported operation has been requested. This is usually an internal Network OS

problem or file corruption. The following is the possible value for the function name and description of

problem variable:

fabsys_write: Unsupported write operation: process xxx

where xxx is the process ID (PID), which could be any whole number.

Recommended Reload or power cycle the active management module (for modular systems) or the switch (for compact

Action systems).

If the message persists, execute the **firmware download** command to update the firmware.

FABS-1006

Message <Function name and description of problem>: object <object type id> unit <slot>.

Message Type LOG

Severity WARNING

Probable Cause

Indicates that there is no device in the slot with the specified object type ID in the system module record. This could indicate a serious Network OS data problem on the switch. The following are the possible values for *function name and description of problem* variable:

- setSoftState: bad object
- setSoftState: invalid type or unit
- media_sync: Media oid mapping failed
- fabsys_media_i2c_op: Media oid mapping failed
- fabsys_media_i2c_op: obj is not media type
- media_class_hndlr: failed sending media state to blade driver

Recommended Action

If the message is isolated, monitor the error messages on the switch. If the error is repetitive or if the fabric failed, fail over or reload the switch.

If the message persists, execute the firmware download command to update the firmware.

FABS-1007

Message <Function name>: Media state is invalid - status=<Status value>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Network OS has detected an invalid value in an object status field. This is usually an

internal Network OS problem or file corruption.

Recommended Reload or power cycle the switch.

Action If the message persists, execute the **firmware download** command to update the firmware.

FABS-1008

Message <Function name>: Media OID mapping failed.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Network OS was unable to locate a necessary object handle. This is usually an internal

Network OS problem or file corruption.

Recommended Reload or pe

Action

Reload or power cycle the switch.

FABS-1009

Message <function name>: type is not media.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Network OS was unable to locate an appropriate object handle. This is usually an

internal Network OS problem or file corruption.

Recommended Reload or power cycle the switch.

FABS-1010

Message <Function name>: Wrong media_event <Event number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Network OS detected an unknown event type. This is usually an internal Network OS

problem or file corruption.

Recommended Reload or power cycle the switch.

Action If the message persists, execute the **firmware download** command to update the firmware.

FABS-1011

Message <Method name>[<Method tag number>]:Invalid input state 0x<Input state code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an unrecognized state code was used in an internal Network OS message for a

field-replaceable unit (FRU).

Recommended Reload or power cycle the management module or switch.

Action If the message persists, execute the **firmware download** command to update the firmware.

FABS-1013

Message <Method name>[<Method tag number>]:Unknown interface module type 0x<Interface

module type>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an unrecognized type of interface module has been discovered in the system.

This error can be caused by one of the following reasons: an incorrect field-replaceable unit (FRU) header, inability to read the FRU header, or the interface module may not be supported by this platform

or Network OS version.

Recommended Verify that the interface module is valid for use in this system and this version of Network OS.

Action Reseat the interface module.

If this is a valid interface module and reseating does not solve the problem, replace the interface module.

FABS-1014

Message <Method name>[<Method tag number>]:Unknown FRU type 0x<FRU Object type>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an unrecognized type of field-replaceable unit (FRU) has been discovered in the system.

This error can be caused by one of the following reasons: an incorrect FRU header, inability to read the

FRU header, or the FRU may not be supported by this platform or Network OS version.

Recommended Verify that the FRU is valid for use in this system and this version of Network OS.

Action Reseat the FRU.

If this is a valid FRU and reseating does not solve the problem, replace the FRU.

FABS-1015

Message <Method name>[<Method tag number>]:Request to enable FRU type 0x<FRU Object type>,

unit <Unit number> failed. err code <Error code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified field-replaceable unit (FRU) could not be enabled. This is usually an internal

Network OS problem.

Recommended Remove and reinsert the FRU.

Action Reload or power cycle the management module or switch.

If the message persists, execute the **firmware download** command to update the firmware.

FCMC Messages

FCMC-1001

Message System is low on memory and has failed to allocate new memory.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the switch is low on memory and therefore failed to allocate new memory for an information

unit (IU).

Recommended A compact switch will automatically reload.

Action For a modular switch, the active management module will automatically fail over and the standby

management module become the active management module.

FCOE Messages

FCOE-1001

Message calloc failed for <object>.

Message Type DCE

Severity ERROR

Probable Cause Indicates a memory failure.

Action

FCOE-1010

Recommended

Message Clean up of login failed for port:<port number>.

Check the switch memory status using the show process memory command.

Execute the copy support command and restart the system. Contact your switch service provider.

Message Type DCE

Severity ERROR

Probable Cause Indicates an invalid port number.

•

Action

FCOE-1019

Recommended

Message FLOGI ignored as FCMAP not configured on FCoE VLAN.

Message Type DCE

Severity WARNING

Probable Cause Indicates that FCMAP is not configured on the Fibre Channel over Ethernet (FCoE) VLAN.

Recommended Configure FCMAP using the **fcmap** command.

FCOE-1020

Message Login rejected by FC stack.

Message Type DCE

Severity INFO

Probable Cause Indicates that the login was rejected by the Fibre Channel (FC) stack.

Recommended No action is required. The device will try to login again.

Action

FCOE-1022

Message Max FCoE device login limit reached.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the switch has reached its maximum allowed Fibre Channel over Ethernet (FCoE) device

limit

Recommended Do not add any more FCoE devices to the switch.

Action

FC0E-1023

Message Too many logins on FCoE controller, max allowed = <MAX_DEVS_PER_CTLR>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the controller has reached its maximum allowed Fibre Channel over Ethernet (FCoE) login

limit.

Recommended Log out some of the logged-in devices using one of the following commands: no fcoeport default,

Action shutdown, and clear fcoe login, and then log in the new device.

You can view the list of logged-in devices using the show fcoe login command.

FCOE-1024

Message FDISC received from Enode without prior FLOGI.

Message Type DCE

Severity WARNING

Probable Cause Indicates that a fabric discovery (FDISC) frame is received from the end node that has not logged in. The

end node must send a fabric login (FLOGI) before it can send an FDISC.

Recommended No action is required.

Action

FCOE-1029

Message Version mismatch between FIP FDISC and root VN port.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the FCoE initialization protocol (FIP) version does not match between the fabric login

(FLOGI) and fabric discovery (FDISC) frames.

Recommended Make sure that the device that is trying to log in conforms to the FC-BB-5 standard.

Action

FCOE-1030

Message Version mismatch between FIP LOGO and root VN port.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the switch received an FCoE initialization protocol (FIP) logout (LOGO) request but the

device logged in with a different FIP version.

Recommended Make sure that the device that is trying to log in conforms to the FC-BB-5 standard.

FC0E-1032

Message The chassis is in WARM RECOVERING state.

Message Type DCE

Severity INFO

Probable Cause Indicates that the chassis is in a warm recovering state and therefore cannot perform the

protocol-specific actions for the time being.

Recommended Wait until the chassis has fully recovered before you perform any operations.

Action

FCOE-1034

Message FIP/FCoE frame on priority <pkt_ctrlp->pri_in> for <Name of the following string>

<MAC address or WWN of the source device> on interface <Rbridge-id>/<Slot>/<Port>

discarded because PFC/FCoE not enabled on this priority.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the specified priority is not priority-based flow control (PFC) or Fibre Channel over Ethernet

(FCoE) enabled.

Recommended Change the CEE map assigned to the FCoE map to accommodate the PFC for the specified FCoE

priority or change the FCoE priority using the fabric-map default command under the FCoE

configuration mode.

FCOE-1035

Message Virtual FCoE port <port number> is online.

Message Type DCE

Action

Severity INFO

Probable Cause Indicates an administrative action on the Fibre Channel over Ethernet (FCoE) port.

Recommended No action is required.

FCOE-1036

Message Virtual FCoE port <port number> is offline.

Message Type DCE

Severity INFO

Probable Cause Indicates an administrative action on the Fibre Channel over Ethernet (FCoE) port.

Recommended No action is required.

FCPH Messages

FCPH-1001

Message <function>: <failed function call> failed, out of memory condition.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the switch is low on memory and therefore failed to allocate new memory for a Fibre

Channel driver instance.

The function can only be fc_create. This function creates a Fibre Channel driver instance.

The failed function call can only be kmalloc_wrapper, which has failed. This function call is for kernel

memory allocation.

Recommended A compact switch will automatically reload.

Action For a modular switch, the active management module will automatically fail over and the standby

management module become the active management module.

FLOD Messages

FLOD-1001

Message Unknown LSR type: port <port number>, type <LSR header type>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the link state record (LSR) type is unknown. The following are the known LSR header

types: 1 - Unicast and 3 - Multicast.

Recommended No action is required; the record is discarded.

Action

FLOD-1003

Message Link count exceeded in received LSR, value = link count number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the acceptable link count received was exceeded in the link state record (LSR).

Recommended No action is required; the record is discarded.

Action

FLOD-1004

Message Excessive LSU length = <LSU length>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the link state update (LSU) size exceeds the value that the system can support.

Recommended Reduce the number of switches in the fabric or reduce the number of redundant inter-switch links (ISLs)

Action between two switches.

FLOD-1005

Message Invalid received RBridge ID: <RBridge number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the received link state record (LSR) contained an invalid RBridge number.

Recommended No action is required; the LSR is discarded.

Action

FLOD-1006

Message Transmitting invalid RBridge ID: <RBridge number>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the transmit link state record (LSR) contained an invalid RBridge number.

Recommended No action is required; the LSR is discarded.

FSPF Messages

FSPF-1001

Message Input Port <port number> out of range.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the specified input port number is out of range because it does not exist on the switch.

Recommended No action is required. This is a temporary kernel error that does not affect your system. If the problem

persists, execute copy support command and contact your service provider.

FSPF-1002

Message Wrong neighbor ID (<RBridge ID>) in Hello message from port <port number>,

expected ID = <RBridge ID>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch has received a wrong RBridge ID in the Hello message from its neighbor switch.

This may happen when the RBridge ID for a switch has been changed.

Recommended No action is required.

Action

FSPF-1003

Message Remote RBridge ID <RBridge number> out of range, input port = <port number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified remote RBridge ID is out of range.

Recommended No action is required. The frame is discarded.

FSPF-1005

Message Wrong Section Id <section number>, should be <section number>, input port = <port

number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an incorrect section ID was reported from the specified input port. The section ID is part of

the fabric shortest path first (FSPF) protocol and is used to identify a set of switches that share an

identical topology database.

Recommended This switch does not support a non-zero section ID. Any connected switch from another manufacturer

with a section ID other than 0 is incompatible in a fabric of Brocade switches. Disconnect the

incompatible switch.

FSPF-1006

Message FSPF Version <FSFP version> not supported, input port = <port number>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the fabric shortest path first (FSPF) version is not supported on the specified input port.

Recommended Update the FSPF version by running the firmware download command. All current versions of the

Action Network OS supports FSPF version 2.

FSPF-1007

Message ICL triangular topology is broken between the neighboring RBridges: <RBridge

number> and <RBridge number>. Please fix it ASAP.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the inter-chassis link (ICL) triangular topology is broken and becomes linear. It may cause

frame drop or performance slowdown.

Recommended Investigate the ICLs and reconnect the switches to form a triangular topology.

FSPF-1008

Message ICL triangular topology is formed among the RBridges: <RBridge number> (self),

<RBridge number>, and <RBridge number>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the inter-chassis link (ICL) triangular topology is formed.

Recommended No action is required.

FSS Messages

FSS-1001

Message Component (<component name>) dropping HA data update (<update ID>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that an application has dropped a high availability (HA) data update.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

FSS-1002

Message Component (<component name>) sending too many concurrent HA data update

transactions (<dropped update transaction ID>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that an application has sent too many concurrent high availability (HA) data updates.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

FSS-1003

Message Component (<component name>) misused the update transaction (<transaction ID>)

without marking the transaction begining.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric synchronization service (FSS) has dropped the update because an application

has not set the transaction flag correctly.

Recommended Execute the **copy support** command and contact your switch service provider.

FSS-1004

Message Memory shortage.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the system ran out of memory.

Recommended Check memory usage on the switch using the **show process memory** command.

Action Execute the **copy support** command and contact your switch service provider.

FSS-1005

Message FSS read failure.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the read system call to the fabric synchronization service (FSS) device has failed.

Recommended If the message persists, execute the **copy support** command and contact your switch service provider.

Action

FSS-1006

Message No FSS message available.

Message Type LOG

Severity WARNING

Probable Cause Indicates that data is not available on the fabric synchronization service (FSS) device.

Recommended If the message persists, execute the **copy support** command and contact your switch service provider.

FSS-1007

Message <component name>: Faulty Ethernet connection.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the Ethernet connection between the active and standby management modules is not

healthy. The error occurs when the standby management module does not respond to a request from the active management module within 5 seconds. This usually indicates a problem with the internal Ethernet

connection and a disruption of the synchronization process.

Recommended

Action

Execute the **copy support** command and contact your switch service provider.

FSS-1008

Message FSS Error on service component [<service name><service instance><component

name>]: <Error Message>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that a fabric synchronization service (FSS) error has occurred.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

FSS-1009

Message FSS Error on service instance [<service name><service instance>]: <Error Message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that a fabric synchronization service (FSS) error has occurred.

Recommended Execute the **copy support** command and contact your switch service provider.

FSS-1010

Message FSS Warning: <Warning Message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a fabric synchronization service (FSS) error may have occurred.

Recommended No action required.

Action

FSS-1011

Message FSS Info: <Info Message>.

Message Type LOG

Severity INFO

Probable Cause Indicates a fabric synchronization service (FSS) related informational message.

Recommended No action required.

FVCS Messages

FVCS-1003

Message Possible vLAG Split Detected vLAG - ifindex (<vLAG ifindex>), split RBridge(<split

RBridge >).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the RBridge has left the cluster.

Recommended If the RBridge was not disabled on purpose, check if it is still connected to the cluster using the show

Action fabric isl command.

FVCS-2001

Message FCS Primary Update Send attempt Failed - reason (<Failure Reason>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the remote switch has rejected the update. Refer to the failure reason for more details.

Recommended Execute the **show fabric isl** command to check the cluster connection status.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

FVCS-2002

Message Link State Update sent to Remote RBridge Failed - reason (<Failure Reason Code>).

Message Type LOG

Severity WARNING

Probable Cause Indicates a possible cluster infrastructure problem.

Recommended Execute the **show fabric isl** command to check the cluster connection status.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

FVCS-2003

Message Lag Configureation Update sent to Remote RBridge Failed - reason (<Failure Reason

Code>).

Message Type LOG

Severity WARNING

Probable Cause Indicates a possible cluster infrastructure problem.

Recommended Execute the **show fabric isl** command to check the cluster connection status.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

FVCS-2004

Message FCS Commit stage Failed - cfg type <Configuration Type>, cfg tag <Configuration

Tag>, domain <Source Domain>, reason (<Failure Reason Code>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric configuration server (FCS) commit stage has failed. The failure reason can be

one of the following:

7 - Memory allocation error

• 14 - Reliable Transport Write and Read (RTWR) send failure

Recommended

Action

Check the status of the virtual link aggregation group (vLAG) identified by the configuration tag.

If the message persists, execute the **copy support** command on both this RBridge and the remote RBridge specified by the domain field and contact your switch service provider.

FVCS-2005

Message FCS Cancel stage Failed - cfg type <Configuration Type>, cfg tag <Configuration

Tag>, domain <Source Domain>, reason (<Failure Reason Code>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the fabric configuration server (FCS) cancel stage has failed. The failure reason can be

one of the following:

• 7 - Memory allocation error

• 14 - Reliable Transport Write and Read (RTWR) send failure

Recommended

Action

Check the status of the virtual link aggregation group (vLAG) identified by the configuration tag.

If the message persists, execute the copy support command on both this RBridge and the remote

RBridge specified by the domain field and contact your switch service provider.

FVCS-2006

Message FCS Transaction Hung - cfg type <Configuration Type>, cfg tag <Configuration Tag>,

trans state<Trans State>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the update cannot be completed for an unknown reason.

Recommended Check the status of the virtual link aggregation group (vLAG) identified by the configuration tag.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

FVCS-3001

Message Eth_ns Message Queue Overflow. Failed to send Update. MAC or MCAST database may be

out of sync. Drop count = (<Drop Count>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Eth_ns (component of FVCS) that kept the MCAST and L2 databases in sync, cannot

send an update to the remote RBridges because its internal message queue is full. This error is due to a

temporary congestion issue on the local RBridge.

Recommended The RBridge must leave and rejoin the fabric for synchronization of the MCAST and L2 databases.

Action

FVCS-3002

Message Eth_ns Message Queue Overflow. Failed to add recieved Update. MAC or MCAST

database may be out of sync. Drop count = (<Drop Count>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the Eth_ns (component of FVCS) that kept the MCAST and L2 databases in sync, cannot

process an update received from the remote RBridge because its internal message queue is full. This

error is due to a temporary congestion issue on the local RBridge.

Recommended No action is required. The L2 and MCAST databases will synchronize with the fabric after the local

Action congestion issue is resolved.

FVCS-3003

Message Local VRID config attempt failed. Existing VLAN_ID mismatch. VRID <VRID>, VRB_ID

<VRB_ID>, New VLAN_ID <New VLAN_ID>, Existing VLAN_ID <Existing VLAN_ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates virtual router ID (VRID) configuration conflict.

Recommended Check existing VRID configurations.

Action

FVCS-3004

Message Local VRID config attempt failed. Existing VMAC mismatch. VRID <VRID>, VRB_ID

<VRB_ID>, New VMAC <New VMAC>, Existing VMAC <Existing VMAC>.

Message Type LOG

Severity WARNING

Probable Cause Indicates virtual router ID (VRID) configuration conflict.

Recommended Check existing VRID configurations.

Action

FVCS-3005

Message Remote VRB_ID update failed. Existing VRID mismatch. VRB_ID <VRB_ID>, SRC_Domain

<SRC_Domain> New VRID <New VRBID>, Existing VRID <Existing VRBID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates virtual router ID (VRID) configuration conflict.

Recommended Check existing VRID configurations.

FVCS-3006

Message Remote VRB_ID update failed. Existing VLAN_ID mismatch. VRB_ID < VRB_ID>,

SRC_Domain <SRC_Domain> New VLAN_ID <New VLAN_ID>, Existing VLAN_ID <Existing

VLAN_ID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates virtual router ID (VRID) configuration conflict.

Recommended Check existing VRID configurations.

Action

FVCS-3007

Message Remote VRB_ID update failed. Existing VMAC mismatch. VRB_ID <VRB_ID>, SRC_Domain

<SRC_Domain>, New VMAC <New VMAC>, Existing VMAC <Existing VMAC>.

Message Type LOG

Severity WARNING

Probable Cause Indicates virtual router ID (VRID) configuration conflict.

Recommended Check existing VRID configurations.

Action

FVCS-3008

Message MAC (L2) database out of sync, Down-level domain <Domain>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current media access control (MAC) count is not supported on the specified downlevel

domain.

Recommended Upgrade the firmware to Network OS v3.0.0 or later.

FVCS-3009

Message Eth_ns buffer capacity exceeded - MAC or MCAST database may be out of sync.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the current media access control (MAC) count exceeds the supported limit.

Recommended Reduce the number of Ethernet devices in the fabric.

FW Messages

FW-1001

Message <label>, value has changed(High=<High value>, Low=<Low value>). Current value is

<Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the internal temperature of the switch has changed.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. To prevent

recurring messages, disable the changed alarm for this threshold. If you receive a temperature-related message, check for an accompanying fan-related message and check fan performance. If all fans are

functioning normally, check the climate control in your lab.

FW-1002

Message <Label>, is below low boundary (High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the internal temperature of the switch has fallen below the low boundary.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Typically,

Action low temperatures means that the fans and airflow of a switch are functioning normally.

Verify that the location temperature is within the operational range of the switch. Refer to the Hardware

Reference Manual for the environmental temperature range of your switch.

FW-1003

Message <Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the internal temperature of the switch has risen above the high boundary to a value that

may damage the switch.

Recommended This message generally appears when a fan fails. If so, a fan-failure message accompanies this

Action message. Replace the fan.

FW-1004

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the internal temperature of the switch has changed from a value outside of the acceptable

range to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. If you

receive a temperature-related message, check for an accompanying fan-related message and check fan

performance. If all fans are functioning normally, check the climate control in your lab.

FW-1005

Message <Label>, value has changed(High=<High value>, Low=<Low value>). Current value is

<Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the speed of the fan has changed. Fan problems typically contribute to temperature

problems.

Recommended No action is required. Respond to this message as is appropriate to the particular policy of the end-user

installation. Consistently abnormal fan speeds generally indicate that the fan is malfunctioning.

FW-1006

Message <Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the speed of the fan has fallen below the low boundary. Fan problems typically contribute

to temperature problems.

Recommended Consistently abnormal fan speeds generally indicate that the fan is failing. Replace the fan.

Message <Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the speed of the fan has risen above the high boundary. Fan problems typically contribute

to temperature problems.

Recommended

Action

Consistently abnormal fan speeds generally indicate that the fan is failing. Replace the fan.

FW-1008

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the speed of the fan has changed from a value outside of the acceptable range to a value

within the acceptable range. Fan problems typically contribute to temperature problems.

Recommended No action is required. Consistently abnormal fan speeds generally indicate that the fan is failing. If this

message occurs repeatedly, replace the fan.

FW-1009

Message <Label>, value has changed(High=<High value>, Low=<Low value>). Current value is

<Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the state of the power supply has changed from faulty to functional or from functional to

faulty.

Recommended If the power supply is functioning correctly, no action is required.

Action If the newer cumply is functioning below the acceptable bour

If the power supply is functioning below the acceptable boundary, verify that it is seated correctly in the chassis. Execute the **show environment power** command to view the status of the power supply. If the

power supply continues to be a problem, replace the faulty power supply.

FW-1010

Message <Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the power supply is faulty. The power supply is not producing enough power.

Recommended Verify that the power supply is installed correctly and that it is correctly seated in the chassis. If the

problem persists, replace the faulty power supply.

FW-1012

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the power supply counter changed from a value outside of the acceptable range to a value

within the acceptable range.

Recommended No action is required. Respond to this message as is appropriate to the particular policy of the end-user

Action installation.

FW-1034

Message <Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the temperature of the small form-factor pluggable (SFP) transceiver has fallen below the

low boundary.

Recommended No action is required. Respond to this message as is appropriate to the particular policy of the end-user

Action installation.

Message <Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the temperature of the small form-factor pluggable (SFP) transceiver has risen above the

high boundary.

Recommended Frequent fluctuations in temperature may indicate a deteriorating SFP transceiver. Replace the SFP

Action transceiver.

FW-1036

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the temperature of the small form-factor pluggable (SFP) transceiver has changed from a

value outside of the acceptable range to a value within the acceptable range.

Recommended No action is required.

Action

FW-1038

Message <Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the receive power value of the small form-factor pluggable (SFP) transceiver has fallen

below the low boundary. The receive performance area measures the amount of incoming laser to help you determine if the SFP transceiver is in good working condition or not. If the counter often exceeds the

threshold, the SFP transceiver is deteriorating.

Recommended Verify that the optical components are clean and functioning properly. Replace deteriorating cables or

Action SFP transceivers. Check for damage from heat or age.

FW-1039

Message

<Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value
is <Value> <Unit>.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the receive power value of the small form-factor pluggable (SFP) transceiver has risen above the high boundary. The receive performance area measures the amount of incoming laser to help you determine if the SFP transceiver is in good working condition or not. If the counter often exceeds the threshold, the SFP transceiver is deteriorating.

Recommended Action

Replace the SFP transceiver before it deteriorates.

FW-1040

Message

<Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).
Current value is <Value> <Unit>.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that the receive power value of the small form-factor pluggable (SFP) transceiver has changed from a value outside of the acceptable range to a value within the acceptable range. The receive performance area measures the amount of incoming laser to help you determine if the SFP transceiver is in good working condition or not. If the counter often exceeds the threshold, the SFP transceiver is deteriorating.

Recommended

Action

No action is required. Respond to this message as is appropriate to the particular policy of the end-user installation.

FW-1042

Message

Severity

<Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value
is <Value> <Unit>.

Message Type

.

LOG

WARNING

Probable Cause

Indicates that the transmit power value of the small form-factor pluggable (SFP) transceiver has fallen below the low boundary. The transmit performance area measures the amount of outgoing laser to help you determine if the SFP transceiver is in good working condition or not. If the counter often exceeds the

threshold, the SFP transceiver is deteriorating.

Recommended

Verify that the optical components are clean and functioning properly. Replace deteriorating cables or SFP transceivers. Check for damage from heat or age.

Message <Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the transmit power value of the small form-factor pluggable (SFP) transceiver has risen

above the high boundary. The transmit performance area measures the amount of outgoing laser to help you determine if the SFP transceiver is in good working condition or not. If the counter often exceeds the

threshold, the SFP transceiver is deteriorating.

Recommended

Action

Replace the SFP transceiver.

FW-1044

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the transmit power value of the small form-factor pluggable (SFP) transceiver has changed

from a value outside of the acceptable range to a value within the acceptable range. The transmit performance area measures the amount of outgoing laser to help you determine if the SFP transceiver is in good working condition or not. If the counter often exceeds the threshold, the SFP transceiver is

deteriorating.

Recommended

Action

No action is required. Respond to this message as is appropriate to the particular policy of the end-user

installation.

FW-1046

Message <Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the value of the small form-factor pluggable (SFP) transceiver voltage has fallen below the

low boundary.

Recommended Verify that your optical components are clean and functioning properly. Replace deteriorating cables or

Action SFP transceivers. Check for damage from heat or age.

FW-1047

Message <Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the value of the small form-factor pluggable (SFP) transceiver voltage has risen above the

high boundary.

Recommended The supplied current of the SFP transceiver is outside of the normal range, indicating possible hardware

failure. If the current rises above the high boundary, replace the SFP transceiver.

FW-1048

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the value of the small form-factor pluggable (SFP) transceiver voltage has changed from a

value outside of the acceptable range to a value within the acceptable range.

Recommended No action is required. Respond to this message as is appropriate to the particular policy of the end-user

Action installation.

FW-1050

Message <Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the value of the small form-factor pluggable (SFP) transceiver voltage has fallen below the

low boundary.

Recommended Configure the low threshold to 1 so that the threshold triggers an alarm when the value falls to 0

Action (Out_of_Range). If continuous or repeated alarms occur, replace the SFP transceiver before it

deteriorates.

Message <Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the value of the small form-factor pluggable (SFP) transceiver voltage has risen above the

high boundary. High voltages indicate possible hardware failures.

Recommended Frequent voltage fluctuations are an indication that the SFP transceiver is deteriorating. Replace the SFP

Action transceiver.

FW-1052

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the value of the small form-factor pluggable (SFP) transceiver voltage has changed from a

value outside of the acceptable range to a value within the acceptable range.

Recommended No action is required. Respond to this message as is appropriate to the particular policy of the end-user

Action installation.

FW-1297

Message <Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the number of Telnet violations has fallen below the low boundary. Telnet violations indicate

that a Telnet connection request has been received from an unauthorized IP address. The

TELNET POLICY contains a list of IP addresses that are authorized to establish Telnet connections to

switches in the fabric.

Recommended

No action is required.

FW-1298

Message

<Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value
is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause

Indicates that the number of Telnet violations has risen above the high boundary. Telnet violations indicate that a Telnet connection request has been received from an unauthorized IP address. The TELNET_POLICY contains a list of IP addresses that are authorized to establish Telnet connections to switches in the fabric.

Recommended

Execute the show logging raslog command to determine the IP address that sent the request.
 Action
 Responses to security-class messages depend on user policies. Consult your security administrator for

response strategies and policies.

FW-1299

Message

<Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).
Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the number of Telnet violations has changed from a value outside of the acceptable range to a value within the acceptable range. Telnet violations indicate that a Telnet connection request has been received from an unauthorized IP address. The TELNET_POLICY contains a list of IP addresses that are authorized to establish Telnet connections to switches in the fabric.

Recommended

Action

No action is required.

FW-1341

Message

<Label>, is below low boundary(High=<High value>, Low=<Low value>). Current value
is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the number of login violations has fallen below the low boundary. Login violations indicate that a login failure has been detected.

Recommended

Action

No action is required.

Message <Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the number of login violations has risen above the high boundary. Login violations indicate

that a login failure has been detected.

Recommended Execute the **show logging raslog** command to determine the IP address of the log in attempt.

Action Responses to security-class messages depend on user policies. Consult your security administrator for

response strategies and policies.

FW-1343

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the number of login violations has changed from a value outside of the acceptable range to

a value within the acceptable range. Login violations indicate that a login failure has been detected.

Recommended No action is required.

Action

FW-1403

Message <Label>,is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the CPU or memory usage is between the boundary limits.

Recommended No action is required.

FW-1404

Message <Label>,is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the CPU or memory usage is above the configured threshold. If this message pertains to

memory usage, then the usage is above middle memory threshold.

Recommended No action is required.

Action

FW-1405

Message <Label>,is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the memory usage is above low threshold.

Recommended No action is required.

Action

FW-1406

Message <Label>, is above high boundary(High=<High value>, Low=<Low value>). Current value

is <Value> <Unit>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the memory usage is above the configured high threshold for memory usage.

Recommended No action is required.

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the memory usage is between the configured high and medium thresholds for memory

usage.

Recommended No action is required.

Action

FW-1408

Message <Label>, is between high and low boundaries(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the memory usage is between the configured low and medium thresholds for memory

usage.

Recommended No action is required.

Action

FW-1424

Message Switch status changed from <Previous state> to <Current state>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because of a policy violation.

Recommended Execute the **show system monitor** command to determine the policy violation.

FW-1425

Message Switch status changed from <Bad state> to HEALTHY.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch status has changed to a healthy state. This state change occurred because a

policy is no longer violated.

Recommended

Action

No action is required.

FW-1426

Message Switch status change contributing factor Power supply: <Number Bad> bad, <Number

Missing> absent.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of faulty or missing

power supplies is greater than or equal to the policy set by the system-monitor command.

Recommended Replace the faulty or missing power supplies.

Action

FW-1427

Message Switch status change contributing factor Power supply: <Number Bad> bad.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of faulty power

supplies is greater than or equal to the policy set by the **system-monitor** command.

Recommended

Action

Replace the faulty power supplies.

Message Switch status change contributing factor Power supply: <Number Missing> absent.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of missing power

supplies is greater than or equal to the policy set by the **system-monitor** command.

Recommended Replace the missing power supplies.

Action

FW-1429

Message Switch status change contributing factor: Power supplies are not redundant.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the power supplies are not in the

correct slots for redundancy.

Recommended Rearrange the power supplies so that one is in an odd slot and another in an even slot to make them

Action redundant.

FW-1430

Message Switch status change contributing factor <string>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of faulty

temperature sensors is greater than or equal to the policy set by the system-monitor command. A

temperature sensor is faulty when the sensor value is not in the acceptable range.

Recommended

Action

Replace the field-replaceable unit (FRU) with the faulty temperature sensor.

FW-1431

Message Switch status change contributing factor Fan: <Number Bad> bad.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of faulty fans is

greater than or equal to the policy set by the system-monitor command. A fan is faulty when sensor

value is not in the acceptable range.

Recommended

Action

Replace the faulty or deteriorating fans.

FW-1432

Message Switch status change contributing factor Cid-Card: <Number Bad> bad.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of faulty Chassis ID

(CID) cards is greater than or equal to the policy set by the **system-monitor** command.

Recommended Replace the faulty CID card.

Action

FW-1433

Message Switch status change contributing factor MM: MM non-redundant (<CP Number>)

faulty.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of faulty

management modules is greater than or equal to the policy set by the system-monitor command. The

management modules are non-redundant.

Recommended

Action

Execute the **show firmware** command to verify if both the management modules have compatible firmware levels. Execute the **firmware download** command to install the same level of firmware to both

management modules. Replace any faulty management modules.

If you reset the micro-switch (the latch on the management module) on the active management module before the heartbeat was up on a power cycle, and the management modules came up non-redundant,

reload the management modules again to clear the problem.

Message Switch status change contributing factor LC: <Number Bad> LC failures (<LC

Numbers>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of line card (LC)

failures is greater than or equal to the policy set by the system-monitor command.

Recommended Replace the faulty LC.

Action

FW-1435

Message Switch status change contributing factor Flash: usage out of range.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the flash usage is out of range.

The policy was set using the **system-monitor** command.

Recommended Execute the **clear support** command to clear the kernel flash.

Action

FW-1439

Message Switch status change contributing factor Switch offline.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the switch is offline.

Recommended Execute the **chassis enable** command to bring the switch online.

FW-1440

Message <FRU label> state has changed to <FRU state>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the state of the specified field-replaceable unit (FRU) has changed to "absent".

Recommended Verify if the event was planned. If the event was planned, no action is required. If the event was not

Action planned, check with your system administrator on the hardware state change.

FW-1441

Message <FRU label> state has changed to <FRU state>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the state of the specified field-replaceable unit (FRU) has changed to "inserted". This

means that an FRU is inserted but not powered on.

Recommended Verify if the event was planned. If the event was planned, no action is required. If the event was not

planned, check with your system administrator on the hardware state change.

FW-1442

Message <FRU label> state has changed to <FRU state>.

Message Type LOG

Action

Action

Severity INFO

Probable Cause Indicates that the state of the specified field-replaceable unit (FRU) has changed to "on".

Recommended Verify if the event was planned. If the event was planned, no action is required. If the event was not

planned, check with your system administrator on the hardware state change.

FW-1443

Message <FRU label> state has changed to <FRU state>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the state of the specified field-replaceable unit (FRU) has changed to "off".

Recommended

Verify if the event was planned. If the event was planned, no action is required. If the event was not

planned, check with your system administrator on the hardware state change.

FW-1444

Message <FRU label> state has changed to <FRU state>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the state of the specified field-replaceable unit (FRU) has changed to "faulty".

Recommended Replace the FRU.

Action

FW-1447

Message Switch status change contributing factor SFM: <Number Bad> SFM failures (<Switch

State>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is not in a healthy state. This occurred because the number of switch fabric

module (SFM) failures is greater than or equal to the policy set by the **system-monitor** command.

Recommended Replace the faulty SFM.

Action

FW-1500

Message Mail overflow - Alerts being discarded.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a mail alert overflow condition has occurred.

Recommended Resolve or disable the mail alert using the system-monitor-mail fru command.

FW-1501

Message Mail overflow cleared - <Mails discarded> alerts discarded.

Message Type LOG

Severity INFO

Probable Cause Indicates that the mail overflow condition has cleared.

Recommended No action is required.

Action

FW-1510

Message <Area string> threshold exceeded: Port <Port number> disabled.

Message Type LOG

Severity INFO

Probable Cause

Indicates that the specified port is now disabled because the link on this port had multiple link failures that exceed Fabric Watch (FW) threshold on the port. The link failures occurred due to one of following reasons:

- Physical and hardware problems on the switch.
- Loss of synchronization.
- Hardware failures.
- A defective small form-factor pluggable (SFP) transceiver or faulty cable.

Protocol errors indicates cyclic redundancy check (CRC) sum disparity. Occasionally, these errors occur due to software glitches. Persistent errors occur due to hardware problems.

Recommended

Action

Check for concurrent loss of synchronization errors. Check the SFP transceiver and the cable and enable the port using the **no shutdown** command.

FW-3101

Message <Port Name>, <Label>, is below low boundary(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the number of invalid cyclic redundancy checks (CRCs) that the port experiences has

fallen below the low boundary.

Recommended

Action

No action is required. Respond to this message as is appropriate to the particular policy of the end-user installation. A low number of invalid CRCs means the switch is functioning normally.

Message <Port Name>, <Label>, is above high boundary(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the number of invalid cyclic redundancy checks (CRCs) that the port experiences has risen

above the high boundary.

Recommended This error generally indicates an deteriorating fabric hardware. Check small form-factor pluggable (SFP)

transceivers, cables, and connections for faulty hardware. Verify that all optical hardware is clean.

FW-3103

Message <Port Name>, <Label>, is between high and low boundaries(High=<High value>,

Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of invalid cyclic redundancy checks (CRCs) that the port experiences has

changed from a value outside of the acceptable range to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Frequent

fluctuations in CRC errors generally indicate an aging fabric. Check the small form-factor pluggable

(SFP) transceivers, cables, and connections for faulty hardware. Verify that all optical hardware is clean.

FW-3104

Message <Port Name>, <Label>, has crossed lower threshold boundary to in

between(High=<High value>, Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of invalid cyclic redundancy checks (CRCs) that the port experiences crossed

lower threshold boundary to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Frequent

fluctuations in CRC errors generally indicate an aging fabric. Check small form-factor pluggable (SFP)

transceivers, cables, and connections for faulty hardware. Verify that all optical hardware is clean.

FW-3105

Message <Port Name>, <Label>, has dropped below upper threshold boundary to in

between(High=<High value>, Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of invalid cyclic redundancy checks (CRCs) that the port experiences has

dropped below upper threshold boundary to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Frequent

fluctuations in CRC errors generally indicate an aging fabric. Check small form-factor pluggable (SFP) transceivers, cables, and connections for faulty hardware. Verify that all optical hardware is clean.

FW-3107

Message <Port Name>, <Label>, is below low boundary(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of Abnormal Frame termination frames that the port experiences has fallen

below the low boundary.

Recommended No action is required. Respond to this message as is appropriate to the particular policy of the end-user

installation. A low number of abnormal frame termination errors means the system is operating normally.

FW-3108

Message <Port Name>, <Label>, is above high boundary(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the number of abnormal frame termination frames that the port experiences has risen

above the high boundary. Flapping interfaces during the traffic flow can generate this error.

Recommended Check all loose connections in the fabric.

Message <Port Name>, <Label>, is between high and low boundaries(High=<High value>,

Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the number of abnormal frame termination frames that the port experiences has changed

from a value outside of the acceptable range to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check all

Action loose connections in the fabric.

FW-3110

Message <Port Name>, <Label>, has crossed lower threshold boundary to in

between(High=<High value>, Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of abnormal frame termination frames that the port experiences crossed lower

threshold boundary to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check all

loose connections in the fabric.

FW-3111

Message <Port Name>, <Label>, has dropped below upper threshold boundary to in

between(High=<High value>, Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the number of abnormal frame termination frames that the port experiences has dropped

below upper threshold boundary to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check all

Action loose connections in the fabric.

FW-3113

Message <Port Name>, <Label>, is below low boundary(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of frames with symbol error that the port experiences has fallen below the low

boundary.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. A low

number of symbol errors means the system is operating normally.

FW-3114

Message <Port Name>, <Label>, is above high boundary(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the number of frames with symbol error that the port experiences has risen above the high

boundary. Flapping interfaces or loose connections can cause this error.

A high number of symbol errors indicate a deteriorated device, cable, or hardware.

Recommended Check your small form-factor pluggables (SFPs), cables, and connections for faulty hardware. Verify that

Action all optical hardware is clean.

FW-3115

Message <Port Name>, <Label>, is between high and low boundaries(High=<High value>,

Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the number of frames with symbol error that the port experiences has changed from a

value outside of the acceptable range to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check all

Action cables and form factors in the system.

Message <Port Name>, <Label>, has crossed lower threshold boundary to in

between(High=<High value>, Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the number of frames with symbol error that the port experiences crossed lower threshold

boundary to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check all

Action cables and form factors in the system.

FW-3117

Message <Port Name>, <Label>, has dropped below upper threshold boundary to in

between(High=<High value>, Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of frames with symbol error that the port experiences has dropped below upper

threshold boundary to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check all

cables and form factors in the system.

FW-3119

Message <Port Name>, <Label>, is below low boundary(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of inter frame gap violation errors that the port experiences has fallen below

the low boundary.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. A low

number of inter frame gap errors means the system is operating normally.

FW-3120

Message <Port Name>, <Label>, is above high boundary(High=<High value>, Low=<Low value>).

Current value is <Value> <Unit>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the number of inter frame gap violation errors that the port experiences has risen above the

high boundary. Flapping interfaces during the traffic flow can generate this error. Congestion or

transmitting multiple frames without an inter frame gap.

Recommended

Action

Check loose connections and congestion in the fabric.

FW-3121

Message <Port Name>, <Label>, is between high and low boundaries(High=<High value>,

Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of inter frame gap violation errors that the port experiences has changed from

a value outside of the acceptable range to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check

loose connections and congestion in the fabric.

FW-3122

Message <Port Name>, <Label>, has crossed lower threshold boundary to in

between(High=<High value>, Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the number of inter frame gap violation errors that the port experiences crossed lower

threshold boundary to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check

Action loose connections and congestion in the fabric.

Message <Port Name>, <Label>, has dropped below upper threshold boundary to in

between(High=<High value>, Low=<Low value>). Current value is <Value> <Unit>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the number of inter frame gap violation errors that the port experiences has dropped below

upper threshold boundary to a value within the acceptable range.

Recommended Respond to this message as is appropriate to the particular policy of the end-user installation. Check

loose connections and congestion in the fabric.

HASM Messages

HASM-1000

Message Component <Component name> terminated. System initiated reload/failover for

recovery.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the software watchdog detected termination of a daemon and the system will reload or

failover to recover.

Recommended After the system reloads, execute the **copy support** command and contact your switch service provider.

Action

HASM-1001

Message Non-restartable component <Component name> terminated. System initiated

reload/failover for recovery.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that the software watchdog detected termination of a daemon and the system will reload or

failover to recover.

Recommended After the system reloads, execute the **copy support** command and contact your switch service provider.

Action

HASM-1002

Message Error happens on service instance <Service type name> <Service instance name>:

<Error message> (Critical).

Message Type LOG

Severity CRITICAL

Probable Cause Indicates software failure.

Recommended Execute the **copy support** command and reload the system manually to recover.

HASM-1003

Message E

Error happened on service instance <Service type name> <Service instance name>: <Error message>.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates software error such as mismatch in the fabric synchronization service (FSS) configuration.

Recommended Action

Execute the \boldsymbol{copy} $\boldsymbol{support}$ command and reload the system manually to recover.

HASM-1004

Message

Processor reloaded - <Reboot Reason>.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that the system has been reloaded either because of a user action or an error. The switch reload can be initiated one of the following commands: **firmware download**, **fastboot**, **ha failover**, and **reload**. Some examples of errors that may initiate this message are hardware errors, software errors, compact flash (CF) errors, or memory errors. The reason for reload can be any of the following:

- Hafailover
- Reset
- Fastboot
- Giveup Master:SYSM
- CP Faulty:SYSM
- FirmwareDownload
- ConfigDownload:MS
- ChangeWWN:EM
- Reboot:WebTool
- Fastboot:WebTool
- Software Fault:Software Watchdog
- Software Fault:Kernel Panic
- Software Fault:ASSERT
- Reboot:SNMP
- Fastboot:SNMP
- Reboot
- Chassis Config
- Reload:API
- Reload:HAM
- EMFault:EM

7 HASM-1013

Recommended

Check the error log on both management modules for additional messages that may indicate the reason

Action for the switch reload.

HASM-1013

Message Restartable daemon (<Component name>) terminated prematurely. System initiated

failover/reload for recovery.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that a restartable daemon terminated before the system has booted up completely.

Recommended After the system reloads, execute the **copy support** command and contact your switch service provider.

Action

HASM-1014

Message Restartable daemon (<Component name>) terminated while the system was booting up.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that a restartable daemon terminated before the system has booted up completely.

Recommended Execute the **copy support** command and reload the system manually to recover.

Action

HASM-1019

Message Firmware operation (<operation code>) was aborted due to disconnection of the peer

node.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the peer node has been reloaded or disconnected due to a software error.

Recommended No action is required. Firmware commit will be started automatically to repair the compact flash (CF)

Action partitions in system.

Message Firmware operation (<operation code>) was aborted due to timeout.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the firmware operation took too long to complete due to CPU overload or other software

errors.

Recommended No action is required. Firmware commit will be started automatically to repair the compact flash (CF)

Action partitions in the system.

HASM-1021

Message Firmware operation (<operation code>) was aborted manually.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified firmware operation was aborted manually.

Recommended No action is required.

Action

HASM-1022

Message Failed to fork firmware child process.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the firmware operation could not be started due to a software error.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

HASM-1023

Message There is no HA connection between the MMs due to firmware incompatibility.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the firmware in the management modules are not compatible.

Recommended

Upgrade the firmware on the standby management module to be the same as the active management

Action module.

HASM-1024

Message Firmware is not available at <Firmware path on MM> on MM.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the firmware for the line card (LC) is not available in the management module compact

flash (CF) card. This event can be due to firmware corruption.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

HASM-1025

Message HA is disconnected between the MMs due to incompatible features.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a feature is enabled and it is not compatible with the firmware running on the standby

management module.

Recommended Upgrade the firmware on the standby management module to be the same as the active management

Action module before enabling the feature.

HASM-1026

Message The last reboot is due to Kernel Panic in <Module name>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the system has reloaded due to kernel panic in the specified module.

Recommended Execute the **copy support** command and contact your switch service provider.

Message HA State is in sync.

Message Type LOG

Severity INFO

Probable Cause Indicates that the high availability (HA) state for the active management module is in synchronization with

the HA state of the standby management module. If the standby management module is healthy, the

failover will be nondisruptive.

Recommended

Action

No action is required.

HASM-1101

Message HA State out of sync.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the high availability (HA) state for the active management module is out of synchronization

with the HA state of the standby management module. If the active management module failover occurs

when the HA state is out of sync, the failover is disruptive.

Recommended If this message was logged as a result of a user-initiated action, no action is required.

Action Execute the **ha dump** command to diagnose the problem.

If the problem persists, execute the copy support command and contact your switch service provider.

HASM-1102

Message Heartbeat misses to <slot/partition> reached threshold.

Message Type LOG

Severity INFO

Probable Cause Indicates that either the active management module Ethernet Media Access Controller (EMAC) or the

indicated interface module is down. The active management module will run a diagnostic test on the

EMAC and will wait for the interface module to reset it if it is down.

Recommended N

Action

No action is required.

HASM-1103

Message Heartbeat to <slot/partition> down.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the active management module has detected that the indicated interface module is down.

This event may happen as a result of one of the following conditions: an operator-initiated action such as **firmware download**, if the interface module is reset or removed, or an error occurred in the interface

module.

Recommended Monitor the interface module for a few minutes. If this message is due to reloading of the interface

module, a message indicating heartbeat up will be displayed after the interface module has reloaded

successfully.

If the interface module does not successfully connect to the active management module after 10

minutes, reload the interface module by ejecting the interface module and reseating it.

HASM-1104

Message Heartbeat to <slot/partition> up.

Message Type LOG

Severity INFO

Probable Cause Indicates that the active management module has detected that the specified interface module is up.

This message indicates that the interface module is ready to start up services and it is typically displayed

when the interface module boots up.

Recommended

Action

No action is required. This message indicates that the interface module is healthy.

HASM-1105

Message Switch bring-up timed out.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the system timed out during a reload or failover sequence, waiting for one or more

programs to register with system services or to fail over to active status.

Recommended

Action

If the switch is in an inconsistent state, reload or power cycle the chassis. Before reloading the chassis, record the firmware version on the switch or management module and execute the **ha dump** command.

If this is a dual-management module switch, gather the output from the management module in which

this log message appeared.

Message Reset the standby management module.

Message Type LOG

Severity INFO

Probable Cause Indicates that the standby management module is being reset due to loss of heartbeat. This message is

typically seen when the standby management module has been reloaded. Note that in certain

circumstances a management module may experience a double reset and reload twice. A management

module can recover automatically even if it has reloaded twice.

Recommended

Action

No action is required.

HASM-1107

Message Take over the active management module.

Message Type LOG

Severity INFO

Probable Cause Indicates that a failover occurred and the standby management module takes over the active

management module.

Recommended

No action is required.

Action

HASM-1108

Message All service instances become active.

Message Type LOG

Severity INFO

Probable Cause Indicates that all service instances became active. Active is an intermediate stage in the boot process.

Recommended No act

Action

No action is required.

HASM-1109

Message The system is ready for configuration replay.

Message Type LOG

Severity INFO

Probable Cause Indicates that all line cards (LCs) are online and the system is ready for configuration replay.

Recommended No action is required.

Action

HASM-1110

Message Configuration replay has completed on the system.

Message Type LOG

Severity INFO

Probable Cause Indicates that configuration replay has completed.

Recommended No action is required.

Action

HASM-1111

Message Configuration replay has completed on <slot/partition>.

Message Type LOG

Severity INFO

Probable Cause Indicates that configuration replay has completed on the specified slot or partition.

Recommended No action is required.

Action

HASM-1120

Message Current version <firwmare version string>.

Message Type LOG

Severity INFO

Probable Cause Indicates the current firmware version string.

Recommended

No action is required.

Action

HASM-1121

Message New version <firmware version string>.

Message Type LOG

Severity INFO

Probable Cause Indicates the new firmware version string after firmware download.

Recommended No a

Action

No action is required.

HASM-1130

Message The Ethernet PHY for slot <slot/partition> was reset successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that there was no Ethernet connection between the active management module and the

specified line card (LC). Subsequently, the PHY in the LC was reset automatically and the connection

has been recovered.

Recommended

No action is required.

Action

HASM-1131

Message Failed to reset the Ethernet PHY for slot <slot/partition>.

Message Type LOG

Severity INFO

Probable Cause Indicates that there was no Ethernet connection between the active management module and the

specified line card (LC). The active management module attempted to recover the connection by

resetting the PHY in the LC but failed.

Recommended

Execute the copy support command and contact your switch service provider.

HASM-1200

Message Detected termination of process <Software component>:<Software component Process

ID>.

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that a process on the switch has ended unexpectedly.

Recommended Action

Copy the warning message along with any core file information and contact your switch service provider.

HASM-1201

Message <Software component>:<Software component Process ID> failed to refresh (<Current

time>:<Refresh time>).

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that one of the daemons is found to be unresponsive. An abort signal is sent.

Recommended Copy the warning message along with any core file information and contact your switch service provider.

HAWK Messages

HAWK-1002

Message Port <port number> chip faulted due to internal error.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates an internal error. All the ports on the interface module or switch will be disrupted.

Recommended For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface

Action module

For a compact switch, reload or power cycle the switch.

HIL Messages

HIL-1202

Message Blower

Splower number> faulted, speed (<measured speed> RPM) below threshold.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified fan speed (in RPMs) has fallen below the minimum threshold.

Recommended Replace the fan field-replaceable unit (FRU). Refer to the *Hardware Reference Manual* of your switch for

Action instructions to replace the fan FRU.

HIL-1301

Message A blower failed or missing. Replace failed or missing blower assembly immediately.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that a fan field-replaceable unit (FRU) has failed or has been removed. This message is often

preceded by a low speed error message. This problem may overheat the switch.

Recommended Replace the affected fan FRU immediately. Refer to the Hardware Reference Manual of your switch for

instructions to replace the fan FRU.

HIL-1302

Message <count> blowers failed or missing. Replace failed or missing blower assemblies

immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that multiple fan field-replaceable units (FRUs) have failed or are missing on the switch. This

message is often preceded by a low fan speed message.

Recommended Replace the affected fan FRUs immediately. Refer to the *Hardware Reference Manual* of your switch for

Action instructions to replace the fan FRU.

HIL-1404

Message <count> fan FRUs missing. Install fan FRUs immediately.

Message Type LOG

Severity WARNING

Probable Cause Indicates that one or more fan field-replaceable units (FRUs) have been removed.

Recommended Install the missing fan FRUs immediately.

Action

HIL-1505

Message High temperature (<measured temperature> C), fan speed increasing per

environmental specifications.

Message Type LOG

Severity INFO

Probable Cause Indicates that temperature in the system has risen above the warning threshold and the fan speed has

been increased to prevent overheating of the system.

Recommended Execute the **show environment fan** command to verify that all fans are working properly.

Action

Make sure that the area is well ventilated and the room temperature is within operational range of your switch. Refer to the *Hardware Reference Manual* of your switch for the operational temperature range.

HIL-1506

Message High temperature (<measured temperature> C) exceeds system temperature limit.

System will shut down within 2 minutes.

Message Type FFDC | LOG

Action

Severity CRITICAL

Probable Cause Indicates that temperature in the system has risen above the critical threshold.

Recommended Execute the **show environment fan** command to verify that all fans are working properly. Replace any

deteriorating fan field-replaceable units (FRUs).

Make sure that the area is well ventilated and the room temperature is within operational range of your switch. Refer to the *Hardware Reference Manual* of your switch for the operational temperature range.

HIL-1510

Message Current temperature (<measured temperature> C) is below shutdown threshold. System

shut down cancelled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that temperature in the system has dropped below the critical threshold; the system will

continue operation.

Recommended To help prevent future problems, execute the show environment fan command to verify all fans are

Action working properly.

Make sure that the area is well ventilated and the room temperature is within operational range of your

switch. Refer to the *Hardware Reference Manual* of your switch for the operational temperature range.

HIL-1511

Message MISMATCH in Fan airflow direction. Replace FRU with fan airflow in same direction.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the airflow of the fan is in the reverse direction. This may heat up the system.

Recommended Replace the fan field-replaceable units (FRUs) in such a manner that the air flows in the same direction

as the remaining fans. Refer to the Hardware Reference Manual of your switch for instructions to replace

the fan FRUs.

HIL-1512

Message MISMATCH in PSU-Fan FRUs airflow direction. Replace PSU with fan airflow in same

direction.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the airflow of the power supply unit (PSU) fan is in the reverse direction. This may heat up

the system.

Recommended Replace the PSU fan field-replaceable unit (FRU) in such a manner that the air flows in the same

direction as the remaining fans. Refer to the Hardware Reference Manual of your switch for instructions

to replace the PSU fan FRU.

HIL-1521

Message <Slot Identifier>, high temperature (<measured temperature>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the temperature of the specified interface module has risen above the warning threshold.

Recommended Execute the **show environment fan** command to verify that all fans are working properly.

Action Make sure that the area is well ventilated and that the room temperature is within operational range of

your switch. Refer to the *Hardware Reference Manual* of your switch for the operational temperature

range.

HIL-1522

Message <Slot Identifier>, high temperature (<measured temperature>). Unit will be shut

down in 2 minutes if temperature remains high.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the temperature of the specified interface module has risen above the critical threshold.

This usually follows a high temperature message.

Recommended Execute the **show environment fan** command to verify that all fans are working properly.

Action

Make sure that the area is well ventilated and the room temperature is within operational range of your switch. Refer to the *Hardware Reference Manual* of your switch for the operational temperature range.

If the message persists, replace the interface module.

HIL-1523

Message <Slot Identifier>, unit shutting down.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the temperature of the specified interface module was above the maximum threshold for at

least two minutes and therefore it has been shut down to prevent damage. This message usually follows

a high temperature warning message.

Recommended Execute the **show environment fan** command to verify that all fans are working properly.

Action Make sure that the area is well ventilated and the room temperature is within the operational range of

your switch. Refer to the Hardware Reference Manual of your switch for the operational temperature

range.

If the message persists, replace the faulty interface module.

HIL-1605

Message High temperature (<measured temperature> C), fan speed increasing per

environmental specifications.

Message Type LOG

Severity INFO

Probable Cause Indicates that temperature in the system has risen above the threshold and therefore the fan speed has

been increased to prevent overheating of the system.

Recommended

Action

No action required.

HLO Messages

HLO-1001

Message Incompatible Inactivity timeout <dead timeout> from port <port number>, correct

value <value>.

LOG | FFDC Message Type

> Severity **ERROR**

Probable Cause Indicates that the hello (HLO) message was incompatible with the value specified in the fabric shortest

path first (FSPF) protocol. The Brocade switch will not accept FSPF frames from the remote switch.

In the Network OS, the HLO dead timeout value is not configurable, so this error can only occur when the

Brocade switch is connected to a switch from another manufacturer.

Recommended The dead timeout value of the remote switch must be compatible with the value specified in the FSPF

protocol. Refer to the documentation for the other manufacturer's switch to change this value.

HLO-1002

Action

Message Incompatible Hello timeout <HLO timeout> from port <port number>, correct value

<correct value>.

Message Type LOG | FFDC

> **ERROR** Severity

Probable Cause Indicates that the hello (HLO) message was incompatible with the value specified in the fabric shortest

path first (FSPF) protocol. The Brocade switch will not accept FSPF frames from the remote switch.

In the Network OS, the HLO timeout value is not configurable, so this error can only occur when the

Brocade switch is connected to a switch from another manufacturer.

Recommended The HLO timeout value of the remote switch must be compatible with the value specified in the FSPF

Action

protocol. Refer to the documentation for the other manufacturer's switch to change this value.

HLO-1003

Message Invalid Hello received from port <port number>, RBridge = <rBridge ID>, Remote

Port = <remote port ID>.

Message Type LOG

> Severity **ERROR**

Probable Cause Indicates that the hello (HLO) message received was invalid and the frame was dropped. The Brocade

switch will not accept fabric shortest path first (FSPF) frames from the remote switch.

The switch has received an invalid HLO because either the RBridge or port number in the HLO message has an invalid value. This error can only occur when the Brocade switch is connected to a switch from

another manufacturer.

Recommended Action The HLO message of the remote switch must be compatible with the value specified in the FSPF

protocol. Refer to the documentation for the other manufacturer's switch to change this value.

HSL Messages

HSL-1000

Message HSL initialization failed.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates a hardware subsystem layer (HSL) initialization failure. This error is caused by other system

errors

Recommended

Action

Execute the copy support command and contact your switch service provider.

HSL-1001

Message Failed to acquire the system MAC address pool.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates the failure to acquire the system address. This error is caused by other system errors.

Recommended Execute the **show logging raslog** command to view the error log for other system errors and correct the

Action errors.

HSL-1004

Message Incompatible SFP transceiver for interface <InterfaceName> is detected.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an incompatible small form-factor pluggable (SFP) transceiver for the interface has been

inserted.

Recommended

Action

Disable the interface using the **shutdown** command and insert an SFP transceiver that is supported on

the interface. After the SFP transceiver is inserted, re-enable the interface using the ${f no}$ shutdown

command.

HSL-1006

Message Failed to get the kernel page size <PageSize> bytes for the Memory Map (MMap).

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that there is not enough contiguous kernel memory.

Recommended Execute the show logging raslog command to view the error log for other system errors and correct the

Action errors.

HSL-1009

Message Failed to create Brocade trunk interface <InterfaceName>.

Message Type LOG

Severity ERROR

Probable Cause Indicates failure to create Brocade trunk because the hardware resources are exhausted.

Recommended Do not exceed the maximum trunk configuration allowed by the system.

IGMP Messages

IGMP-1001

Message MsgQ enqueue failed (rc: <rc>).

Message Type DCE

Severity ERROR

Probable Cause Indicates an internal inter-process communication (IPC) failure due to the scalability scenario.

Recommended Reduce the number of groups and MRouter ports.

Action

IGMP-1002

Message IPC with McastSS failed (message-id: <message-id>, rc: <rc>).

Message Type DCE

Severity ERROR

Probable Cause Indicates an internal inter-process communication (IPC) failure due to the scalability scenario.

Recommended Reduce the number of groups and MRouter ports.

Action

IGMP-1003

Message MRouter eNS update from a VCS RBridge (ID:<rbid>) running lower firmware version.

Message Type DCE

Severity ERROR

Probable Cause Indicates an older message update.

Recommended Upgrade the VCS RBridge firmware to the latest build.

IGMP-1004

Message IGMP maximum VLANs enabled. Cannot enable IGMP on <vlan>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the number of VLANs on which internet group multicast protocol (IGMP) can be enabled

has reached the maximum limit. Therefore, IGMP cannot be enabled on the specified VLAN.

Recommended

Action

No action is required.

IPAD Messages

IPAD-1000

Message IP Config change: Entity:<Type of managed entity>/<Instance number of managed

entity> Interface:<Type of network interface>/<Instance number of network
interface> Adresss family:<Protocol address family> Source of change:<Source of
address change> Address:<Value of address and prefix> DHCP:<DHCP enabled or not>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the local IP address has been changed manually or it was reconfigured automatically by

the Dynamic Host Configuration Protocol (DHCP) server.

Recommended No action is required.

Action

IPAD-1001

Message <Type of managed entity>/<Instance number of managed entity> <Protocol address

family> <Source of address change> <Value of address> DHCP <DHCP enabled or not>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the gateway IP address has been changed manually or it was reconfigured automatically

by the Dynamic Host Configuration Protocol (DHCP) server.

Recommended No action is required.

Action

IPAD-1002

Message Switch name has been successfully changed to <Switch name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch name has been changed.

Recommended No action is required.

IPAD-1003

Message libipadm: <error message> <error message specific code>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the IP admin library has encountered an unexpected error.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

IPAD-1004

Message Unable to set the host name due to /etc/hosts file corruption.

Message Type LOG

Severity INFO

Probable Cause Indicates that the /etc/hosts file was inconsistent and it could not be recovered.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

IPAD-1005

Message The /etc/hosts file was inconsistent but has been recovered successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that the /etc/hosts file was inconsistent but it was recovered.

Recommended No action is required.

KTRC Messages

KTRC-1001

Message Dump memory size exceeds dump file size.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the dump memory size has exceeded the dump file size.

Recommended Execute the copy support command and reload the switch. If the problem persists, contact your switch

Action service provider.

KTRC-1002

Message Concurrent trace dumping.

Message Type LOG

Severity INFO

Probable Cause Indicates that the initial background dump has not completed.

Recommended No action is required.

Action

KTRC-1003

Message Cannot open ATA dump device.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the advanced technology attachment (ATA) dump driver is not initialized properly.

Recommended Execute the copy support command and reload the switch. If the problem persists, contact your switch

Action service provider.

KTRC-1004

Message Cannot write to ATA dump device.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the write boundary in the advanced technology attachment (ATA) dump device has

exceeded.

Recommended Execute the copy support command and reload the switch. If the problem persists, contact your switch

Action service provider.

KTRC-1005

Message Trace initialization failed. <Reason initialization failed>. <Internal error

code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that trace was unable to initialize.

Recommended Execute the copy support command and reload the switch. If the problem persists, contact your switch

Action service provider.

L2AG Messages

L2AG-1001

Message Linux socket error - error reason: <reason>, socket name: <sockname>, error name

<errorname>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that an error has occurred in the Linux socket.

Recommended Reload or power cycle the switch.

Action

L2AG-1002

Message Initialization error : <reason>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Layer 2 Agent (L2AGT) has encountered an error during initialization.

Recommended Reload or power cycle the switch.

Action

L2AG-1003

Message Message Queue Error : Message queue create failed.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Layer 2 Agent (L2AGT) has encountered system service manager (SSM) message

queue errors.

Recommended Reload or power cycle the switch.

L2AG-1004

Message FDB error: Error in creating AVL tree.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Layer 2 Agent (L2AGT) has encountered an error while initializing the AVL tree.

Recommended Reload or power cycle the switch.

Action

L2AG-1005

Message MAC-address-table hash failed even after two attempts for slot <slot> chip <chip>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the media access control (MAC) address table hash failed even after two hash changes on

the specified chip.

Recommended Reload or power cycle the switch.

Action

L2AG-1006

Message MAC-address-table on slot <Slot_id> chip <Chip_id> is 95 percent full.

Message Type DCE

Severity INFO

Probable Cause Indicates that the media access control (MAC) address table on the chip is 95 percent full.

Recommended Clear some of the entries using the clear mac-address-table dynamic command or wait until the old

Action entries age out.

L2AG-1007

Message MAC-address-table on slot <Slot_id> chip <Chip_id> is less than 90 percent full.

Message Type DCE

Severity INFO

Probable Cause Indicates that the media access control (MAC) address table is less than 90 percent full.

Recommended Action

No action is required. The Layer 2 Agent (L2AGT) will start learning the entries.

L2SS Messages

L2SS-1001

Message Linux socket error - error reason: <reason>, socket name: <sockname>, error name

<errorname>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that an error has occurred in the Linux socket.

Recommended Reload or power cycle the switch.

Action

L2SS-1002

Message Initialization error: <reason>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Layer 2 system (L2SYS) has encountered an error during initialization.

Recommended Reload or power cycle the switch.

Action

L2SS-1003

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Layer 2 system (L2SYS) has encountered system service manager (SSM) message

queue errors.

Recommended Reload or power cycle the switch.

L2SS-1004

Message FDB error: Error in creating the AVL tree.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Layer 2 system (L2SYS) has encountered an error while initializing the AVL tree.

Recommended Reload or power cycle the switch.

Action

L2SS-1005

Message MAC-address-table hash failed even after two attempts for slot <slot> chip <chip>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the media access control (MAC) address table hash failed even after two hash changes on

the specified chip.

Recommended Reload or power cycle the switch.

Action

L2SS-1006

Message MAC-address-table is 95 percent full.

Message Type DCE

Severity INFO

Probable Cause Indicates that the media access control (MAC) address table on the chip is 95 percent full.

Recommended Clear some of the entries using the clear mac-address-table dynamic command or wait until the old

Action entries age out.

L2SS-1007

Message MAC-address-table on slot <Slot_id> chip <Chip_id> is less than 90 percent full.

Message Type DCE

Severity INFO

Probable Cause Indicates that the media access control (MAC) address table on the specified chip is less than 90 percent

full

Recommended No action is required. The Layer 2 system (L2SYS) will start learning the entries.

Action

L2SS-1008

Message Adding Internal MAC <mac1>:<mac3>:<mac4>:<mac5>:<mac6> VID <Vid> as a

static MAC.

Message Type DCE

Severity INFO

Probable Cause Indicates that a static media access control (MAC) is overriding an internal MAC entry (VRRP/SVI).

Recommended No action is required.

Action

L2SS-1009

Message Fabric-wide Layer 2 flush command issued.

Message Type DCE

Severity INFO

Probable Cause Indicates that a fabric-wide Layer 2 flush command is issued and the entire Layer 2 forwarding table will

be cleared.

Recommended No action is required.

L2SS-1010

Message Fabric-wide 12 flush completed, status - <command status>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the entire Layer 2 forwarding table has been cleared.

Recommended No action is required.

LOG Messages

LOG-1000

Message Previous message has repeated <repeat count> times.

Message Type LOG

Severity INFO

Probable Cause Indicates that the previous message was repeated the specified number of times.

Recommended No action is required.

Action

LOG-1001

Message A log message was dropped.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates that a log message was dropped. A trace dump file has been created.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

LOG-1002

Message A log message was not recorded.

Message Type FFDC | LOG

Severity WARNING

Probable Cause Indicates that a log message was not recorded by the error logging system. A trace dump file has been

created. The message may still be visible through Simple Network Management Protocol (SNMP) or

other management tools.

Recommended Action

Execute the copy support command and contact your switch service provider.

LOG-1003

Message SYSTEM error log has been cleared.

Message Type LOG

Severity INFO

Probable Cause Indicates that the persistent system error log has been cleared.

Recommended No action is required.

Action

LOG-1004

Message Log message <Log message that has been blocked.> flooding detected and blocked.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified message has been flooding and was blocked.

Recommended Reload the switch. If the message persists, execute the copy support command and contact your switch

Action service provider.

LOG-1005

Message Log message <Log message that has been disabled. > has been disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified message has been disabled from logging.

Recommended No action is required.

Action

LOG-1006

Message Log message Log message that has been enabled.> has been enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified message has been enabled for logging.

7 LOG-1007

Recommended

No action is required.

Action

LOG-1007

Message DCE error log has been cleared.

Message Type DCE

Severity INFO

Probable Cause Indicates that the persistent DCE error log has been cleared.

Recommended No action is required.

LSDB Messages

LSDB-1001

Message Link State ID < link state ID > out of range.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified link state database ID is out of the acceptable range. The valid link state ID is

the same as the valid RBridge ID, whose range is from 1 through 239. The switch will discard the record

because it is not supported.

Recommended

No action is required.

Action

LSDB-1002

Message Local Link State Record reached max incarnation.

Message Type LOG

Severity INFO

Probable Cause Indicates the local link state database reached the maximum incarnations.

An "incarnation" is a progressive number that identifies the most recent version of the link state record (LSR). The switch generates its local link state record when first enabled. The incarnation number will

begin again at 0x80000001 after reaching 0x7FFFFFF.

Recommended

Action

No action is required.

LSDB-1003

Message No database entry for local Link State Record, RBridge < local RBridge>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that there is no local link state record (LSR) entry in the link state database. The switch should

always generate its own local entry when starting up.

An "incarnation" is a progressive number that identifies the most recent version of LSR. The switch generates its local LSR when first enabled. By disabling and enabling the switch, a new local link state

record is generated.

7 LSDB-1004

Recommended

Execute the chassis disable and chassis enable commands. A new local link state record is generated

Action during the switch enable.

LSDB-1004

Message No Link State Record for RBridge <local RBridge>.

Message Type LOG

> Severity WARNING

Probable Cause Indicates there is no link state record (LSR) for the specified local RBridge.

Recommended No action is required. The other switch will pass the LSR after the fabric is stable.

MCAST_SS Messages

MCAST_SS-1001

Message Type DCE

Severity ERROR

Probable Cause Indicates that an error has occurred in the Linux socket.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1002

Message Socket Error: <op> sock name <sock> Error <error> type <type> seq <seq> pid <pid>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the specified error has occurred while processing the hardware abstraction layer (HAL)

message.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1003

Message Learning error: <op> (<reason>) - VLAN <vid> MAC/group <address>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered an error while learning the media

access control (MAC) addresses.

Recommended Reload or power cycle the switch.

MCAST_SS-1004

Message NSM error: <op> (<reason>) for VLAN <vid> port <port>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered an error during a network service

module (NSM) event.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1005

Message Message error: Invalid message type <type> expecting <value1> or <value2> or

<value3>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the type of the message received from the driver is invalid.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1006

Message Message error: <op> (<reason>)Invalid message length <length> expecting

<length1>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the length of the message received from the driver is invalid.

Recommended Reload or power cycle the switch.

MCAST_SS-1007

Message Initialization error: <op> (<reason>).

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered an error during initialization.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1008

Message HAL error: <op> (<reason>) - VLAN <vid> MAC/group <address>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered the hardware abstraction layer

(HAL) errors.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1009

Message L2SS error: <op> (<reason>) VLAN <vid> MAC <mac address>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered the Layer 2 subsystem (L2SS)

related errors.

Recommended Reload or power cycle the switch.

MCAST_SS-1010

Message Queue error: <op> (<reason>).

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered the message queue errors.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1011

Message IDB error: <op> (<reason>) port index <port-index> not found for VLAN ID

<vlan-id>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the specified port index is invalid.

Recommended If there is an impact on the data path, reload or power cycle the switch. Refer to the Network OS

Action Administrator's Guide for instructions to verify the data path.

MCAST_SS-1012

Message IDB error: <op> (<reason>) VLAN ID <vid> not found.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the specified VLAN ID (VID) is invalid.

Recommended If there is an impact on the data path, reload or power cycle the switch. Refer to the Network OS

Action Administrator's Guide for instructions to verify the data path.

MCAST_SS-1013

Message Snooping DB error: <op> (<reason>) Group not found - VLAN <vid>> group <group

address>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the group address lookup for the specified VLAN has failed.

Recommended

Reload or power cycle the switch.

Action

MCAST_SS-1014

Message Snooping DB error: <op> (<reason>) MAC not found - VLAN <vid> MAC-addr <MAC

address>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the media access control (MAC) address lookup for the specified VLAN has failed.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1015

Message HSL error: <op> (<reason>) failed for message <message> VLAN <vid> MAC <MAC

address> mgid <mgid> CPU <cpu>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the specified hardware subsystem layer (HSL) related operation has failed.

Recommended Reload or power cycle the switch.

MCAST_SS-1016

Message Message error: <op> (<reason>) <length> (<length1>).

Message Type DCE

Severity ERROR

Probable Cause Indicates that the length of the message received from the driver is invalid.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1017

Message Learning error: <op> (<reason>) Invalid number <port> for ifindex <ifindex>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered an error while learning the media

access control (MAC) addresses.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1018

Message Memory Alloc Error: <op> (<reason>) type <memtype>/<memsize>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered an error during the memory

allocation.

Recommended Relo

Reload or power cycle the switch.

MCAST_SS-1019

Message Ptree Error: <op> (<reason>) VLAN <vid> MAC/group <address>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered an error during the Ptree operation.

Recommended Reload or power cycle the switch.

Action

MCAST_SS-1020

Message List Error: <pp> (<reason>) VLAN <vid> MAC <mac address> group <group address>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the multicast subsystem (mcast_ss) has encountered an error during the List operation.

Recommended Reload or power cycle the switch.

MPTH Messages

MPTH-1001

Message Null parent, lsId = <number>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that a null parent was reported. The minimum cost path (MPATH) uses a tree structure in which

the parent is used to connect to the root of the tree.

Recommended No action is required.

Action

MPTH-1002

Message Null lsrP, lsId = <ls ID number>.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates that the link state record (LSR) is null.

Recommended No action is required.

Action

MPTH-1003

Message No minimum cost path in candidate list.

Message Type LOG

Severity WARNING

Probable Cause Indicates the fabric shortest path first (FSPF) module has determined that there is no minimum cost path

(MPATH) available in the candidate list.

Recommended No action is required.

MS Messages

MS-1021

Message MS WARMBOOT failure (FSS_MS_WARMINIT failed. Reason=<failure reason>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that fabric synchronization service (FSS) warm recovery failed during the warm initialization

phase of the switch reload.

Recommended If the message persists, execute the **copy support** command and contact your switch service provider.

MSTP Messages

MSTP-1001

Message <message>: <message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the system has failed to allocate memory.

Recommended Check the memory usage on the switch using the **show process memory** command.

Action Reload or power cycle the switch.

MSTP-1002

Message <message>: <message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the system has failed to initialize.

Recommended Reload or power cycle the switch.

Action

MSTP-1003

Message <message>: <message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates a connection, transfer, or receiving error in the socket.

Recommended If this is a modular switch, execute the ha failover command. If the problem persists or if this is a

Action compact switch, download a new firmware version using the firmware download command.

MSTP-1004

Message <message>: <message>.

Message Type DCE

Action

Severity ERROR

Probable Cause Indicates that a port on which PortFast is enabled has received a bridge protocol data unit (BPDU). The

port has been disabled.

Recommended Disable the PortFast feature on the port using one of the following commands:

• For rapid spanning tree protocol (RSTP), execute the no spanning-tree edgeport command.

For spanning tree protocol (STP), execute the **no spanning-tree portfast** command.

After disabling the PortFast feature, execute the no shutdown command to re-enable the port.

MSTP-2001

Message <message>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the multiple spanning tree protocol (MSTP) bridge mode has changed.

Recommended No action is required.

Action

MSTP-2002

Message <Bridge mode information>. My Bridge ID: <Bridge ID> Old Root: <Old Root ID> New

Root: <New Root ID>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the multiple spanning tree protocol (MSTP) bridge or bridge instance root has been

changed.

Recommended No action is required.

MSTP-2003

Message MSTP instance <instance > is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified multiple spanning tree protocol (MSTP) instance has been created.

Recommended No action is required.

Action

MSTP-2004

Message MSTP instance <instance> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified multiple spanning tree protocol (MSTP) instance has been deleted.

Recommended No action is required.

Action

MSTP-2005

Message VLAN <vlan_ids> is <action> on MSTP instance <instance>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified multiple spanning tree protocol (MSTP) instance has been modified.

Recommended No action is required.

Action

MSTP-2006

Message MSTP instance <instance> brigde priority is changed from <pri>priority_old> to

<priority_new>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified multiple spanning tree protocol (MSTP) instance priority has been modified.

Recommended Action

No action is required.

NBFS Messages

NBFS-1001

Message

Duplicate E_Port SCN from port <portnumber> in state <state change name> (<state change number>).

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that a duplicate E_Port state change number was reported. The neighbor finite state machine (NBFSM) states are as follows:

- NB_ST_DOWN The neighbor is down.
- NB_ST_INIT The neighbor is initializing.
- NB_ST_DB_EX The neighbor and the switch are exchanging data from their link state record (LSR) databases.
- NB_ST_DB_ACK_WT The neighbor is waiting for the switch to acknowledge the LSR database.
- NB_ST_DB_WT The LSR database is in waiting state; synchronization is in process.
- NB_ST_FULL The neighbor is in the finishing state.

Recommended Action

No action is required.

NBFS-1002

Message

Wrong input: <state name> to neighbor FSM, state <current state name>, port <portnumber>.

Message Type

FFDC | LOG

Severity

ERROR

Probable Cause

Indicates that a wrong input was sent to the neighbor finite state machine (NBFSM). NBFSM states are as follows:

- NB ST DOWN The neighbor is down.
- NB_ST_INIT The neighbor is initializing.
- NB_ST_DB_EX The neighbor and the switch are exchanging data from their link state record (LSR) databases.
- NB_ST_DB_ACK_WT The neighbor is waiting for the switch to acknowledge the LSR database.
- NB_ST_DB_WT The LSR database is in waiting state; synchronization is in process.
- NB_ST_FULL The neighbor is in the finishing state.

If this error occurs repeatedly, then there is a problem in the protocol implementation between two switches.

Recommended Action

Execute the **show fabric route neighbor-state** command to check the neighbor state of the port listed in the message. If the neighbor state is NB_ST_FULL, then this message can safely be ignored. Otherwise, execute the **shutdown** and **no shutdown** commands to reset the port.

NBFS-1003

Message

DB_XMIT_SET flag not set in state <current state name>, input <state name>, port <portnumber>.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that the database transmit set flag was not set for the specified input state on the specified port. Neighbor finite state machine (NBFSM) states are as follows:

- NB_ST_DOWN The neighbor is down.
- NB_ST_INIT The neighbor is initializing.
- NB_ST_DB_EX The neighbor and the switch are exchanging data from their link state record (LSR) databases.
- NB_ST_DB_ACK_WT The neighbor is waiting for the switch to acknowledge the LSR database.
- NB_ST_DB_WT The LSR database is in waiting state; synchronization is in process.
- NB_ST_FULL The neighbor is in the finishing state.

Recommended Action

No action is required. The Network OS automatically recovers from this problem.

NS Messages

NS-1006

Message Duplicated WWN was detected with PID 0x<existing device PID> and 0x<new device

PID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that an existing device has the same World Wide Name (WWN) as a new device that has come

online.

Recommended The switch will process the new process ID (PID) and leave the existing PID intact. Subsequent switch

Action operations will clean up the obsolete PID. However, administrators can check and remove devices with a

duplicated WWN.

NS-1009

Message NS has detected a device with node WWN as zero, PID 0x<device PID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a port has logged in with node World Wide Name (WWN) as zero, Brocade Network

Advisor (BNA) will not show the port connectivity.

Recommended Check the device that logged in. The device could be misbehaving.

Action

NS-1012

Message Detected duplicate WWPN [<WWPN>] - devices removed with PID 0x<existing device

PID> and 0x<new device PID>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the devices with the same World Wide Port Name (WWPN) have been removed from the

Name Server database.

Recommended Administrators should verify the reported devices with a duplicated WWPN.

NSM Messages

NSM-1001

Message Interface <InterfaceName> is online.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified interface has come online after the protocol dependencies are resolved.

Recommended No action is required.

Action

NSM-1002

Message Interface <InterfaceName> is protocol down.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified interface has gone offline because one of the protocol dependency is

unresolved.

Recommended

Action

Check for the reason codes using the **show interface** command and resolve the protocol dependencies.

NSM-1003

Message Interface <InterfaceName> is link down.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified interface has gone offline because the link was down.

Recommended Check whether the connectivity is proper and the remote link is up.

NSM-1004

Message Interface <InterfaceName> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified logical interface has been created.

Recommended No action is required.

Action

NSM-1007

Message Chassis is <status>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the chassis has been enabled or disabled.

Recommended No action is required.

Action

NSM-1009

Message Interface <InterfaceName> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified logical interface has been deleted.

Recommended No action is required.

Action

NSM-1010

Message InterfaceMode changed from <Mode_old> to <Mode_new> for interface

<InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the interface mode has been changed.

Recommended

No action is required.

Action

NSM-1011

Message OperationalEndpointMode changed from <Mode_old> to <Mode_new> for interface

<InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the interface operational endpoint mode has been changed.

Recommended No action is required.

Action

NSM-1012

Message VLAN classifier group <group_id> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified VLAN classifier group has been created.

Recommended No action is required.

Action

NSM-1013

Message VLAN classifier group <group_id> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified VLAN classifier group has been deleted.

Recommended No action is required.

NSM-1014

Message VLAN classifier rule <rule_id> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified VLAN classifier rule has been created.

Recommended No action is required.

Action

NSM-1015

Message VLAN classifier rule <rule_id> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified VLAN classifier rule has been deleted.

Recommended No action is required.

Action

NSM-1016

Message VLAN classifier rule <rule_id> is <action> on VLAN classifier group <group_id>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified VLAN classifier group has been modified.

Recommended No action is required.

Action

NSM-1017

Message Interface <InterfaceName> is <action> on interface <Logical_InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified logical interface member list has been changed.

Recommended

No action is required.

Action

NSM-1018

Message <count> VLANs <except> will be allowed on interface <Logical_InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the VLAN membership has been changed for the specified interface.

Recommended No action is required.

Action

NSM-1019

Message Interface <InterfaceName> is administratively up.

Message Type DCE

Severity INFO

Probable Cause Indicates that the interface administrative status has changed to up.

Recommended No action is required.

Action

NSM-1020

Message Interface <InterfaceName> is administratively down.

Message Type DCE

Severity INFO

Probable Cause Indicates that the interface administrative status has changed to down.

Recommended No action is required.

NSM-1021

Message Interface IP overlap with management IP <ipAddr> ifname:<ifname>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the IP address configured on the interface overlaps with the management IP address.

Recommended Change the interface IP address using the **ip address** command.

Action

NSM-1022

Message FCoE configuration has been <Option> on interface <InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the Fibre Channel over Ethernet (FCoE) configuration has been enabled or disabled on the

specified interface.

Recommended No action is required.

Action

NSM-1023

Message RBridge ID <RBridgeId> has joined Port-channel <PortChannelKey>. Port-channel is a

vLAG with RBridge IDs <RBridgeList>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified RBridge has joined the virtual link aggregation group (vLAG).

Recommended No action is required.

Message RBridge ID <RBridgeId> has left Port-channel <PortChannelKey>. Port-channel is a

vLAG with RBridge IDs <RBridgeList>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified RBridge has left the virtual link aggregation group (vLAG).

Recommended No action is required.

Action

NSM-1025

Message RBridge ID <RBridgeId> has left Port-channel <PortChannelKey>. Port-channel has

only RBridge ID <RbridgeList> and is no longer a vLAG.

Message Type DCE

Severity INFO

Probable Cause Indicates that the virtual link aggregation group (vLAG) no longer exists.

Recommended No action is required.

Action

NSM-1026

Message SFP transceiver for interface <InterfaceName> is inserted.

Message Type DCE

Severity INFO

Probable Cause Indicates that a small form-factor pluggable (SFP) transceiver has been inserted in the specified

interface.

Recommended No action is required.

NSM-1027

Message SFP transceiver for interface <InterfaceName> is removed.

Message Type DCE

Severity INFO

Probable Cause Indicates that a small form-factor pluggable (SFP) transceiver has been removed from the specified

interface.

Recommended No action is required.

Action

NSM-1028

Message Incompatible SFP transceiver for interface <InterfaceName> is detected.

Message Type DCE

Severity ERROR

Probable Cause Indicates that an incompatible small form-factor pluggable (SFP) transceiver for the interface has been

inserted.

Recommended Disable the interface using the **shutdown** command and insert an SFP transceiver that is supported on

the interface. After the SFP transceiver is inserted, re-enable the interface using the no shutdown

command.

NSM-1029

Message Failed to read SFP transceiver for interface <InterfaceName>.

Message Type DCE

Action

Severity ERROR

Probable Cause Indicates failure to read the small form-factor pluggable (SFP) transceiver for the specified interface.

Recommended Disable the interface using the **shutdown** command and re-insert the SFP transceiver. After the SFP

Action transceiver is inserted, re-enable the interface using the no shutdown command. If the problem persists,

contact your switch service provider.

Message Interface <InterfaceName> is administratively down due to speed mismatch in

port-channel.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified interface has gone down due to mismatching speed in the port-channel.

Recommended Set the correct speed for the interface using the **speed** command.

Action

NSM-1031

Message Session <SessionNumber> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified session has been created.

Recommended No action is required.

Action

NSM-1032

Message Session <SessionNumber> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified session has been deleted.

Recommended No action is required.

Action

NSM-1033

Message Session <SessionNumber> configuration is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified session configuration has been deleted.

Recommended

No action is required.

Action

NSM-1034

Message Session <SessionNumber> configuration is added.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified session configuration has been added.

Recommended No action is required.

Action

NSM-1035

Message Description for Session <SessionNumber> is added.

Message Type DCE

Severity INFO

Probable Cause Indicates that the session description has been added.

Recommended No action is required.

Action

NSM-1036

Message Description for Session <SessionNumber> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the session description has been deleted.

Recommended No action is required.

Message Interface <InterfaceName> is administratively down due to 1Gbps link configured on

Brocade Trunk.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified interface has gone down because a 1 Gbps link has been configured on the

Brocade trunk.

Recommended Remove the 1 Gbps link from the Brocade trunk or change the 1 Gbps small form-factor pluggable (SFP)

Action transceiver.

NSM-1038

Message Unsupported Brocade-branded SFP transceiver for interface <InterfaceName> is

detected.

Message Type DCE

Severity ERROR

Probable Cause Indicates that an unsupported Brocade-branded small form-factor pluggable (SFP) transceiver for the

interface has been inserted.

Recommended Use a Brocade-branded SFP transceiver for the interface because the digital diagnostics will not be

Action supported.

NSM-2000

Message Port-profile <ProfileName> activation succeeded.

Message Type DCE

Severity INFO

Probable Cause Indicates that the profile activation was successful.

Recommended No action is required.

NSM-2001

Message Port-profile <ProfileName> activation failed, reason <Reason>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the profile activation was unsuccessful.

Recommended Check the configuration and port-profile status using the show port-profile status command. Execute

Action the copy support command and contact your switch service provider.

NSM-2002

Message Port-profile <ProfileName> deactivation succeeded.

Message Type DCE

Severity INFO

Probable Cause Indicates that the profile deactivation was successful.

Recommended No action is required.

Action

NSM-2003

Message Port-profile <ProfileName> deactivation failed, reason <Reason>

Message Type DCE

Severity ERROR

Probable Cause Indicates that the profile deactivation was unsuccessful.

Recommended Check the configuration and port-profile status using the show port-profile status command. Execute

Action the copy support command and contact your switch service provider.

NSM-2004

Message Port-profile <ProfileName> application succeeded on <InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the profile application was successful.

Recommended

No action is required.

Action

NSM-2005

Message Port-profile <ProfileName> application failed on <InterfaceName>, reason

<Reason>, removing any applied configuration.

Message Type DCE

Action

Severity ERROR

Probable Cause Indicates that the profile application on the specified interface was unsuccessful.

Recommended Check the configuration and port-profile status using the show port-profile status command. Execute

the **copy support** command and contact your switch service provider.

NSM-2006

Message Port-profile <ProfileName> removed successfully on <InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified port-profile has been removed successfully.

Recommended No action is required.

Action

NSM-2007

Message Interface <InterfaceName> became port-profile-port.

Message Type DCE

Severity INFO

Probable Cause Indicates that the port-profile configuration mode has been enabled on the specified interface using the

port-profile-port command.

Recommended No action is required.

NSM-2008

Message Interface <InterfaceName> became non-port-profile-port.

Message Type DCE

Severity INFO

Probable Cause Indicates that the port-profile configuration mode has been disabled on the specified interface using the

no port-profile-port command.

Recommended No action is required.

Action

NSM-2010

Message Interface <InterfaceName> could not become non-port-profile-port.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the port-profile configuration mode could not be disabled on the specified interface using

the no port-profile-port command.

Recommended Check the configuration and port-profile status using the show port-profile status command. Execute

the copy support command and contact your switch service provider.

NSM-2011

Message Port-profile <ProfileName> removal failed on <InterfaceName>.

Message Type DCE

Action

Severity ERROR

Probable Cause Indicates that the specified port-profile could not be removed.

Recommended Execute the **copy support** command and contact your switch service provider.

Message MAC <ProfileMac> is associated to port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates successful association of the virtual machine (VM) media access control (MAC) address with

the specified port-profile.

Recommended

Action

No action is required.

NSM-2013

Message MAC <ProfileMac> is disassociated from port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates successful disassociation of the virtual machine (VM) media access control (MAC) address

from the specified port-profile.

Recommended

No action is required.

Action

NSM-2014

Message VLAN sub-profile for port-profile <ProfileName> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the VLAN sub-profile has been created successfully.

Recommended

No action is required.

NSM-2015

Message Access VLAN <VlanId> is configured for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the untagged VLAN has been configured for the specified port-profile.

Recommended No action is required.

Action

NSM-2016

Message Access VLAN is deleted from port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the untagged VLAN has been removed from the specified port-profile.

Recommended No action is required.

Action

NSM-2017

Message Port-profile <ProfileName> is configured for switching properties.

Message Type DCE

Severity INFO

Probable Cause Indicates that the switching properties have been configured on the specified port-profile using the

switchport command.

Recommended No

Action

No action is required.

Message Switching properties are removed for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the switching properties have been removed from the specified port-profile using the no

switchport command.

Recommended No action is required.

Action

NSM-2019

Message The <ModeName> mode is configured for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified mode has been configured for the port-profile using the switchport mode

command.

Recommended No action is required.

Action

NSM-2020

Message The <ModeName> mode is de-configured for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified mode has been removed for the port-profile using the switchport mode

command.

Recommended No action is required.

NSM-2021

Message The tagged VLANs <TaggedVlanStr> are configured for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified tagged VLANs are configured in the VLAN sub-profile.

Recommended No action is required.

Action

NSM-2022

Message The tagged VLANs <TaggedVlanStr> are removed for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified tagged VLANs have been removed from the VLAN sub-profile.

Recommended No action is required.

Action

NSM-2023

Message The tagged VLANs except <TaggedVlanStr> are configured for port-profile

<ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that except the specified tagged VLANs, all other tagged VLANs are configured in the VLAN

sub-profile.

Recommended No action is required.

Message All VLANs are configured as tagged VLANs for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that all the available tagged VLANs are configured in the specified VLAN sub-profile.

Recommended No action is required.

Action

NSM-2025

Message All tagged VLANs are removed for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that all the available tagged VLANs have been from the specified VLAN sub-profile.

Recommended No action is required.

Action

NSM-2026

Message Native VLAN <VlanId> is configured to port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the native VLAN has been configured for the specified port-profile.

Recommended No action is required.

Action

NSM-2027

Message Native VLAN is deleted from port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the native VLAN has been removed from the specified port-profile.

Recommended

No action is required.

Action

NSM-2028

Message FCoE sub-profile for port-profile <ProfileName> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the Fibre Channel over Ethernet (FCoE) sub-profile has been created for the specified

port-profile.

Recommended N

Action

No action is required.

NSM-2029

Message FCoE port is configured successfully for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the Fibre Channel over Ethernet (FCoE) port has been configured for the specified

port-profile.

Recommended

Action

No action is required.

NSM-2030

Message FCoE port is removed successfully for port-profile <ProfileName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the Fibre Channel over Ethernet (FCoE) port has been removed from the specified

port-profile.

Recommended No action is required.

NSM-2031

Message Port-profile <ProfileName> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified port-profile has been created successfully.

Recommended No action is required.

Action

NSM-2032

Message Port-profile <ProfileName> is removed.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified port-profile has been removed successfully.

Recommended No action is required.

Action

NSM-2033

Message VLAN sub-profile for port-profile <ProfileName> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the VLAN sub-profile has been deleted successfully.

Recommended No action is required.

Action

NSM-2034

Message FCoE sub-profile for port-profile <ProfileName> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the Fibre Channel over Ethernet (FCoE) sub-profile has been deleted successfully.

7 NSM-2035

Recommended

No action is required.

Action

NSM-2035

Message Non-profiled-macs on profiled ports will be <allowflag>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the non-profiled media access control (MAC) entries on the profiled port will be allowed or

dropped.

Recommended

Action

No action is required.

NSM-2036

Message Association of MAC address: <MAC> failed. Reason: <Reason>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that an error occurred during port-profile to media access control (MAC) association.

Recommended Check the configuration and port-profile status using the show port-profile status command. Execute

Action the copy support command and contact your switch service provider.

ONMD Messages

ONMD-1000

Message LLDP is enabled.

Message Type DCE

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) is enabled globally.

Recommended No action is required.

Action

ONMD-1001

Message LLDP is disabled.

Message Type DCE

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) is disabled globally.

Recommended No action is required.

Action

ONMD-1002

Message LLDP global configuration is changed.

Message Type DCE

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) global configuration has been changed.

Recommended No action is required.

ONMD-1003

Message LLDP is enabled on interface <InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) is enabled on the specified interface.

Recommended No action is required.

Action

ONMD-1004

Message LLDP is disabled on interface <InterfaceName>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the link layer discovery protocol (LLDP) is disabled on the specified interface.

Recommended No action is required.

Action

ONMD-1005

Message Feature Mismatch: <Feature>, will re-negotiate.

Message Type DCE

Severity INFO

Probable Cause Indicates that the content of the specified feature does not match with the link partner.

Recommended Change the feature setting at both ends of the link to match.

OSPF Messages

OSPF-1001

Message <error message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates a configuration error.

Recommended Make sure to input or pass the right parameter through CLI or other daemon.

Action

OSPF-1002

Message <message>.

Message Type DCE

Severity INFO

Probable Cause Indicates an open shortest path first (OSPF) interface state change or external link-state database

(LSDB) overflow notification.

Recommended No action is required.

Action

OSPF-1003

Message <error message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the length, format, or content of the received packet is incorrect.

Recommended Check configuration at the local or remote node.

PDM Messages

PDM-1001

Message Failed to parse the pdm config.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the parity data manager (PDM) process could not parse the configuration file. This may be

caused due to a missing configuration file during the installation.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1003

Message pdm [-d] -S <service> -s <instance>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a syntax error occurred when trying to launch the parity data manager (PDM) process.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1004

Message PDM memory shortage.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the parity data manager (PDM) process ran out of memory.

Recommended Restart or power cycle the switch.

PDM-1006

Message Too many files in sync.conf.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the configuration file sync.conf contains too many entries.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1007

Message File not created: <file name>. errno=<errno>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the parity data manager (PDM) process failed to create the specified file.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1009

Message Cannot update Port Config Data.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the parity data manager (PDM) system call for setting port configuration (setCfg) failed.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1010

Message File open failed: <file name>, errno=<errno>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the parity data manager (PDM) process could not open the specified file.

7 PDM-1011

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1011

Message File read failed: <file name>, Length (read=<Number of character read>,

expected=<Number of characters expected>), errno=<errno returned by read>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the parity data manager (PDM) process could not read data from the specified file.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1012

Message File write failed: <file name>. Length (read=<Number of character read>,

write=<Number of characters written>), errno=<errno returned by write>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the parity data manager (PDM) process could not write data to the specified file.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1013

Message File empty: <File Name>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch configuration file /etc/fabos/fabos.[0]1].conf is empty.

Recommended Execute the **firmware download** command to reinstall the firmware.

PDM-1014

Message Access sysmod failed.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a system call to sysMod failed.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1017

Message System (<Error Code>): <Command>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the specified system call failed.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1019

Message File path or trigger is too long.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a line in the *pdm.conf* file is too long.

Recommended Execute the **firmware download** command to reinstall the firmware.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

PDM-1021

Message Failed to download area port map.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a system call failed.

PDM-1021

Recommended Action

Execute the firmware download command to reinstall the firmware.

PHP Messages

PHP-1001

Message <PHP Script message>.

Message Type LOG

Severity INFO

Probable Cause Indicates a user-defined informative message.

Recommended No action is required.

Action

PHP-1002

Message <PHP Script message>.

Message Type LOG

Severity WARNING

Probable Cause Indicates a user-defined warning message.

Recommended No action is required.

Action

PHP-1003

Message <PHP Script message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates a user-defined error message.

Recommended No action is required.

PHP-1004

Message <PHP Script message>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates a user-defined critical message.

Recommended No action is required.

PLAT Messages

PLAT-1000

Message <Function name> <Error string>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that nonrecoverable peripheral component interconnect (PCI) errors have been detected.

Recommended The system will be faulted and may reload automatically.

Action If the system does not reload, execute the **reload** command.

Execute the copy support command and contact your switch service provider.

PLAT-1001

Message MM<Identifies which MM (1 or 2) is doing the reset> resetting other MM (double

reset may occur).

Message Type LOG

Severity INFO

Probable Cause Indicates that the other management module is being reset. This message is typically generated by a

management module that is in the process of becoming the active management module. Note that in certain circumstances a management module may experience a double reset and reload twice. A

management module can recover automatically even if it has reloaded twice.

Recommended No action is required.

Action

PLAT-1002

Message MM<Identifies which MM (1 or 2) is generating the message>: <Error message>

hk_fence 0x<MM Housekeeping Fence register. Contents are platform-specific> mm_ha

0x<MM HA register. Contents are platform-specific> mm_status 0x<MM Status

register. Contents are platform-specific>.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that one of the management modules cannot access the inter-integrated circuit (I2C)

subsystem because of an error condition or being isolated from the I2C bus.

Recommended Reload the management module if it does not reload automatically. Reseat the management module if

Action reloading does not solve the problem. If the problem persists, replace the management module.

PLAT-1004

Message Turning off Fan <Fan Number> because of airflow direction mismatch.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates that the specified fan field-replaceable unit (FRU) has been turned off because it is

incompatible with the system airflow direction policy.

Recommended Replace the fan FRU. Refer to the Hardware Reference Manual of your switch for instructions to replace

Action the fan FRU.

PLAT-1005

Message Unable to read EEPROM for Global airflow direction. Setting to default Port side

intake.

Message Type LOG | FFDC

Severity CRITICAL

Probable Cause Indicates a failure to read the electrically erasable programmable read-only memory (EEPROM) to

determine the airflow direction of the fans. Therefore, setting the airflow direction to be from the port side

of the system.

Recommended Exe

Action

Execute the **copy support** command and contact your switch service provider.

PLAT-1006

Message Unable to read EEPROM for Global airflow direction. Shutting off Fans now.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates a failure to read the electrically erasable programmable read-only memory (EEPROM) to

determine the airflow direction of the fans. The fans will be shut down.

Recommended Execute the **copy support** command and contact your switch service provider.

PLAT-1007

Message Turning off Fan <Fan Number> because of airflow direction <Global airflow

direction>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the specified fan is turned off because of an incorrect airflow direction.

Recommended Replace the fan field-replaceable units (FRUs) in such a manner that the air flows in the same direction,

that is, towards the port side or away from the port side of the system. Refer to the Hardware Reference

Manual of your switch for instructions to replace the fan FRU.

PLAT-1008

Message Unable to read EEPROM for Global airflow direction.

Message Type LOG

Severity ERROR

Probable Cause Indicates a failure to read the electrically erasable programmable read-only memory (EEPROM) and

therefore unable to determine the global airflow direction of the fans.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

PLAT-1009

Message Unable to read EEPROM Valid Signature for Global airflow direction.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the content read from electrically erasable programmable read-only memory (EEPROM) is

invalid and therefore unable to determine the global airflow direction of the fans.

Recommended Execute the **copy support** command and contact your switch service provider.

PORT Messages

PORT-1003

Message Port <port number> Faulted because of many Link Failures.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified port is disabled because of multiple link failures on the port that have

exceeded the threshold internally set on the port. This problem is related to the hardware.

Action • The small form-factor pluggable (SFP)

The cable (fiber-optic or copper inter-switch link (ISL))

The attached devices

After checking the hardware, execute the no shutdown command to re-enable the port.

Check and replace (if necessary) the hardware attached to both the ends of the specified port, including:

PORT-1004

Recommended

Message Port <port number> (0x<port number (hex)>) could not be enabled because it is

disabled due to long distance.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified port cannot be enabled because other ports in the same group have used the

buffers of this port group. This happens when other ports are configured to be long distance.

Recommended To enable the specified port, perform one of the following actions:

Action • Reconfigure the other E_Ports so that they are not long distance.

Change the other E_Ports so that they are not E_Ports.

This will free some buffers and allow the port to be enabled.

PORT-1011

Message An SFP transceiver for interface Fibre Channel <rbridge-id number>/<slot

number>/<port number> is removed.

Message Type LOG

Severity INFO

Probable Cause Indicates that a small form-factor pluggable (SFP) transceiver has been removed from the specified port.

Recommended

No action is required.

Action

PORT-1012

Message An SFP transceiver for interface Fibre Channel <rbr/>bridge-id number>/<slot

number>/<port number> is inserted.

Message Type LOG

Severity INFO

Probable Cause Indicates that a small form-factor pluggable (SFP) transceiver has been inserted into the specified port.

Recommended No action is required.

Action

PORT-1013

Message An incompatible SFP transceiver for interface Fibre Channel <rbr/>bridge-id

number>/<slot number>/<port number> is inserted.

Message Type LOG

Severity INFO

Probable Cause Indicates that an incompatible small form-factor pluggable (SFP) transceiver has been inserted into the

specified port.

Recommended No action is required.

RAS Messages

RAS-1001

Message First failure data capture (FFDC) event occurred.

Message Type LOG

Severity INFO

Probable Cause Indicates that a first failure data capture (FFDC) event occurred and the failure data has been captured.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

RAS-1002

Message First failure data capture (FFDC) reached maximum storage size (<log size limit>

MB).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the storage size for first failure data capture (FFDC) has reached the maximum.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

RAS-1004

Message Software 'verify' error detected.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates an internal software error.

Recommended Execute the **copy support** command and contact your switch service provider.

RAS-1005

Message Software 'assert' error detected.

Message Type LOG | FFDC

Severity WARNING

Probable Cause Indicates an internal software error.

Recommended Execute the copy support comman

Action

RAS-1006

Message Support data file (<Uploaded file name>) automatically transferred to remote

Execute the copy support command and contact your switch service provider.

address ' <Remote target designated by user> '.

Message Type LOG

Severity INFO

Probable Cause Indicates that the support data was automatically transferred from the switch to the configured remote

server.

Recommended No action is required.

Action

RAS-1007

Message System is about to reload.

Message Type LOG

Severity INFO

Probable Cause Indicates that the system reload was initiated.

Recommended No action is required.

RAS-2001

Message Audit message log is enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the audit message log has been enabled.

Recommended No action is required.

Action

RAS-2002

Message Audit message log is disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the audit message log has been disabled.

Recommended No action is required.

Action

RAS-2003

Message Audit message class configuration has been changed to <New audit class

configuration>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the audit event class configuration has been changed.

Recommended No action is required.

Action

RAS-3001

Message USB storage device plug-in detected.

Message Type LOG

Severity INFO

Probable Cause Indicates that the USB storage device plug-in has been detected.

Recommended

No action is required.

Action

RAS-3002

Message USB storage device enabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the USB storage device has been enabled.

Recommended No action is required.

Action

RAS-3003

Message USB storage device was unplugged before it was disabled.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the USB storage device was unplugged before it was disabled.

Recommended No action is required. It is recommended to disable the USB storage device using the **usb off** command

Action before unplugged it from the system.

RAS-3004

Message USB storage device disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the USB storage device has been disabled.

Recommended No action is required.

RAS-3005

Message File <filename/directory> removed from USB storage.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified file or directory has been removed from the USB storage.

Recommended No action is required.

RCS Messages

RCS-1003

Message Failed to allocate memory: (<function name>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified reliable commit service (RCS) function has failed to allocate memory.

Recommended This message is usually transitory. Wait for a few minutes and retry the command.

Action

Check memory usage on the switch using the **show process memory** command.

Reload or power cycle the switch.

RCS-1005

Message Phase <RCS phase>, <Application Name> Application returned <Reject reason>,

0x<Reject code>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a receiving switch is rejecting the specified reliable commit service (RCS) phase.

Recommended If the reject is in acquire change authorization (ACA) phase, wait for several minutes and retry the operation from the sender switch.

If the reject is in the stage fabric configuration (SFC) phase, check if the application license exists for the local RBridge and if the application data is compatible.

RCS-1006

Message State <RCS phase>, Application Application Name> AD Administrative RBridge>, RCS

CM. RBridge <RBridge ID that sent the reject> returned 0x<Reject code>. App

Response Code < Application Response Code > .

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified RBridge rejected the reliable commit service (RCS) phase initiated by an application on the local switch.

- If the reject phase is acquire change authorization (ACA), the remote RBridge may be busy and could not process the new request.
- If the reject phase is stage fabric configuration (SFC), the data sent by the application may not be compatible or the RBridge does not have the license to support the specified application.

7 RCS-1007

Recommended

If the reject is in ACA phase, wait for several minutes and then retry operation.

Action If the reject is in the SFC phase, check if the application license exists for the RBridge and if the application data is compatible.

RCS-1007

Message Zone DB size and propagation overhead exceeds RBridge <RBridge number>'s maximum

supported Zone DB size <max zone DB size>. Retry after reducing Zone DB size.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the specified RBridge cannot handle the zone database being committed.

Recommended Reduce the zone database size by deleting some zones. Refer to the Network OS Administrator's Guide

for instructions to delete a zone.

RCS-1008

Message RBridge <RBridge number> Lowest Max Zone DB size.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified RBridge has the lowest memory available for the zone database in the fabric.

The zone database must be smaller than the memory available on this RBridge.

Recommended Reduce the zone database size by deleting some zones. Refer to the Network OS Administrator's Guide

Action for instructions to delete a zone.

RCS-1010

Message RBridge <RBridge number> is RCS incapable. Disabled <Number of E_ports disabled>

E_port(s) connected to this RBridge.

Message Type LOG

Severity ERROR

Probable Cause Indicates inability to retrieve RCS-capable information for the specified RBridge due to some potential

routing issues.

Recommended Investigate for routing issue or check the cabling, and re-enable the disabled E_ports to attempt another

Action exchange of RCS-capable information.

RCS-1011

Message Remote RBridge <RBridge number> is RCS incapable. Configure this RBridge as RCS

capable.

Message Type LOG

Severity ERROR

Probable Cause Indicates inability to retrieve RCS-capable information for the specified RBridge due to some potential

routing issues.

Recommended Investigate for routing issue or check the cabling, and re-enable the disabled E_ports to attempt another

Action exchange of RCS-capable information.

RTM Messages

RTM-1001

Message Initialization error: <messsage>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the route management (RTM) has encountered an error during initialization.

Recommended Reload or power cycle the switch.

Action

RTM-1002

Message Max capacity reached: <messsage>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the route management (RTM) has reached its maximum capacity.

Recommended Reduce the number of routes or next hops using the **clear ip route** command.

Action

RTM-1003

Message Static Route Update error: <messsage>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that an error has occurred in the route management (RTM) during the static route update.

Recommended Check the static route configuration using the **show ip static route** command.

RTM-1005

Message Protocol Route update error: <messsage>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that an error has occurred in the route management (RTM) during the protocol route update.

Recommended Check the protocol statistics and configuration.

Action

RTM-1021

Message Static route update success: <messsage>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the static route update was successful.

Recommended No action is required.

Action

RTM-1022

Message Clear Route success: <messsage>.

Message Type DCE

Severity INFO

Probable Cause Indicates that IP routes are cleared by the route management (RTM).

Recommended No action is required.

Action

RTM-1023

Message <messsage>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that a route pointing to the management interface is not redistributed to other protocols.

7 RTM-1023

Recommended No action

No action is required.

RTWR Messages

RTWR-1001

Message

RTWR <routine: error message> 0x<detail 1>, 0x<detail 2>, 0x<detail 3>, 0x<detail 4>, 0x<detail 5>.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that an error occurred in Reliable Transport Write and Read (RTWR) due to one of the following reasons:

- The system ran out of memory.
- The domain may be unreachable.
- The frame transmission failed.
- An internal error or failure occurred.

The message contains the name of the routine that has an error and other error-specific information. Refer to values in details 1 through 5 for more information.

Recommended Action

Execute the **reload** command to restart the switch.

RTWR-1002

Message

RTWR <error message: Maximum retries exhausted> 0x<port>, 0x<RBridge>, 0x<retry count>, 0x<status>, 0x<process ID>.

Message Type

LOG

Severity

WARNING

Probable Cause

Indicates that Reliable Transport Write and Read (RTWR) has exhausted the maximum number of retries for sending data to the specified RBridge.

Recommended Action

Execute the **show fabric all** command to verify that the specified RBridge ID is online.

If the switch with the specified RBridge ID is offline, enable the switch using the **chassis enable** command.

RTWR-1003

Message <module name>: RTWR retry <number of times retried> to RBridge <RBridge ID>,

iu_data <first word of iu_data>.

Message Type LOG

Severity INFO

Probable Cause Indicates the number of times Reliable Transport Write and Read (RTWR) has failed to get a response

and retried.

Recommended Execute the **show fabric all** command to verify that the specified RBridge ID is reachable.

Action

SCN Messages

SCN-1001

Message SCN queue overflow for process <daemon name>.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause

Indicates that an attempt to write a state change notification (SCN) message to a specific queue has failed because the SCN queue for the specified daemon is full. This may be caused by the daemon hanging or the system being busy.

The following are some valid values for the daemon name:

- fabricd
- asd
- evmd
- fcpd
- webd
- msd
- nsd
- psd
- snmpd
- zoned
- fspfd
- tsd

Recommended Action

If this message is caused by the system being busy, the condition is temporary.

If this message is caused by a hung daemon, the software watchdog will cause the daemon to dump the core and reload the switch. In this case, execute the **copy support ftp** command to send the core files using FTP to a secure server location.

SEC Messages

SEC-1033

Message Invalid character used in member parameter to add switch to SCC policy; command

terminated.

LOG Message Type

> **ERROR** Severity

Probable Cause Indicates that a member parameter in the secpolicy defined-policy command is invalid (for example, it

> may include an invalid character, such as an asterisk). A valid switch identifier (WWN, RBridge ID, or switch name) must be provided as a member parameter in the secpolicy defined-policy command.

Recommended Execute the secpolicy defined-policy command using a valid switch identifier (WWN, RBridge ID, or Action

switch name) to add specific switches to the switch connection control (SCC) policy.

SEC-1034

Message Invalid member <policy member>.

Message Type LOG

> **ERROR** Severity

Probable Cause Indicates that the input list has an invalid member.

Recommended Verify the member names and input the correct information.

Action

SEC-1036

Message Device name <device name > is invalid due to a missing colon.

LOG Message Type

> Severity **ERROR**

Probable Cause Indicates that one or more device names mentioned in the secpolicy defined-policy command does not

have the colon character (:).

Recommended Execute the secpolicy defined-policy command with a properly formatted device name parameter.

SEC-1037

Message Invalid WWN format <invalid WWN>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the World Wide Name (WWN) entered in the policy member list had an invalid format.

Recommended Execute the command again using the standard WWN format, that is, 16 hexadecimal digits grouped as

Action eight colon separated pairs. For example: 50:06:04:81:D6:F3:45:42.

SEC-1038

Message Invalid domain <RBridge ID>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that an invalid RBridge ID was entered.

Recommended Verify that the RBridge ID is correct. If RBridge ID is not correct, execute the command again using the

Action correct RBridge ID.

SEC-1044

Message Duplicate member <member ID> in (<List>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified member is a duplicate in the input list. The list can be a policy list or a switch

member lis

Recommended Do not specify any duplicate members.

Action

SEC-1071

Message No new security policy data to apply.

Message Type LOG

Severity ERROR

Probable Cause Indicates that there are no changes in the defined security policy database to be activated.

7 SEC-1180

Recommended Action

Verify that the security event was planned. Change some policy definitions and execute the **secpolicy**

activate command to activate the policies.

SEC-1180

Message Added account <user name> with <role name> authorization.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified new account has been created.

Recommended No action is required.

Action

SEC-1181

Message Deleted account <user name>

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified account has been deleted.

Recommended No action is required.

Action

SEC-1184

Message <configuration> configuration change, action <action>, server ID <server>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified action is applied to remote AAA (RADIUS/TACACS+) server configuration.

The possible actions are ADD, REMOVE, CHANGE, and MOVE.

Recommended No action is required.

SEC-1185

Message <action> switch DB.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch database was enabled or disabled as the secondary authentication, accounting,

and authorization (AAA) mechanism when the remote authentication dial-in user service (RADIUS) or

lightweight directory access protocol (LDAP) is the primary AAA mechanism.

Recommended

Action

No action is required.

SEC-1187

Message Security violation: Unauthorized switch <switch WWN> tries to join fabric.

Message Type LOG

Severity INFO

Probable Cause Indicates that a switch connection control (SCC) security violation was reported. The specified

unauthorized switch attempts to join the fabric.

Recommended

Action

Check the switch connection control policy (SCC) policy to verify the switches are allowed in the fabric. If the switch should be allowed in the fabric but it is not included in the SCC policy, add the switch to the policy using the **secpolicy defined-policy scc_policy member-entry** command. If the switch is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take appropriate action as defined by your enterprise security policy.

SEC-1189

Message Security violation: Unauthorized host with IP address <IP address> tries to do

SNMP write operation.

security policy.

Message Type LOG

Severity INFO

Probable Cause Indicates that a Simple Network Management Protocol (SNMP) security violation was reported. The

specified unauthorized host attempted to perform an SNMP write operation.

Recommended

Action

Check the WSNMP policy (read/write SNMP policy) and verify which hosts are allowed access to the fabric through SNMP. If the host is allowed access to the fabric but is not included in the policy, add the host to the policy. If the host is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take appropriate action as defined by your enterprise

SEC-1190

Message Security violation: Unauthorized host with IP address <IP address> tries to do

SNMP read operation.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that a Simple Network Management Protocol (SNMP) security violation was reported. The

specified unauthorized host attempted to perform an SNMP read operation.

Recommended Check the RSNMP policy (read-only SNMP policy) to verify the hosts that are allowed access to the

fabric through SNMP read operations are included in the RSNMP policy. If the host is allowed access but is not included in the RSNMP policy, add the host to the policy. If the host is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to access your fabric. Take

appropriate action as defined by your enterprise security policy.

SEC-1191

Message Security violation: Unauthorized host with IP address < Ip address > tries to

establish HTTP connection.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that a Hypertext Transfer Protocol (HTTP) security violation was reported. The specified

unauthorized host attempted to establish an HTTP connection.

Recommended Determine whether the host IP address specified in the message can be used to manage the fabric

through an HTTP connection. If so, add the host IP address to the HTTP policy of the fabric. If the host is not allowed access to the fabric, this is a valid violation message and an unauthorized entity is trying to

access your fabric. Take appropriate action as defined by your enterprise security policy.

SEC-1192

Message Security violation: Login failure attempt via <connection method>.

Message Type LOG

Severity INFO

Probable Cause Indicates that a serial or modem login security violation was reported. An incorrect password was used

while trying to log in through a serial or modem connection; the log in failed.

Recommended Use the correct password.

Message Security violation: Login failure attempt via <connection method>. IP Addr: <IP

address>

Message Type LOG

Severity INFO

Probable Cause Indicates that a login security violation was reported. The wrong password was used while trying to log in

through the specified connection method; the log in failed. The violating IP address is displayed in the

message.

Recommended Verify that the specified IP address is being used by a valid switch administrator. Use the correct

Action password.

SEC-1197

Message Changed account <user name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified account has changed.

Recommended No action is required.

Action

SEC-1199

Message Security violation: Unauthorized access to serial port of switch <switch

instance>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that a serial connection policy security violation was reported. An attempt was made to access

the serial console on the specified switch instance when it is disabled.

Recommended Check to see if an authorized access attempt was made on the console. If so, add the switch World Wide

Name (WWN) to the serial policy using the **secpolicy defined-policy scc_policy member-entry** command. If the host is not allowed access to the fabric, this is a valid violation message and an

unauthorized entity is trying to access your fabric. Take appropriate action as defined by your enterprise

security policy.

SEC-1203

Message Login information: Login successful via TELNET/SSH/RSH. IP Addr: <IP address>

Message Type LOG

Severity INFO

Probable Cause Indicates that the remote log in of the specified IP address was successful.

Recommended No action is required.

Action

SEC-1307

Message <RADIUS/TACACS+/LDAP server identity> server <server> authenticated user account

'<username>'.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the specified AAA (RADIUS/TACACS+/LDAP) server responded to a switch request after

some servers timed out.

Recommended If the message appears frequently, reconfigure the list of servers so that the responding server is the first

server on the list.

SEC-1308

Message All <RADIUS/TACACS+/LDAP server identity> servers failed to authenticate user

account '<username>'.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that all servers in the remote AAA (RADIUS/TACACS+/LDAP) service configuration have failed

to respond to a switch request within the configured timeout period.

Recommended Verify that the switch has proper network connectivity to the specified AAA (RADIUS/TACACS+/LDAP)

servers and the servers are correctly configured.

Message <Message>.

Message Type LOG

> Severity INFO

Probable Cause Indicates that the password attributes have been changed.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1313

Message The password attributes parameters were set to default values.

Message Type LOG

Action

Severity **INFO**

Probable Cause Indicates that the password attributes were set to default values.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-1325

Message Security enforcement: Switch <switch WWN> connecting to port <Port number> is not

authorized to stay in fabric.

Message Type LOG

Action

ERROR Severity

Probable Cause Indicates that the specified switch is being disabled on the specified port because of a switch connection

control (SCC) policy violation.

Recommended No action is required unless the switch must remain in the fabric. If the switch must remain in the fabric,

add the switch World Wide Name (WWN) to the SCC policy using the secpolicy defined-policy

scc_policy member-entry command, then attempt to join the switch with the fabric.

SEC-1329

Message IPFilter enforcement: Failed to enforce ipfilter policy of <Policy Type> type

because of <Error code>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the IP filter policy enforcement failed because of an internal system failure.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

SEC-1334

Message local security policy <Event name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified event has occurred.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

SEC-1335

Message local security policy <Event name> WWN <Member WWN>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the specified event has occurred.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

SEC-1336

Message Missing file <file name> is replaced with default configuration.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified file is missing and it has been replaced with the default file.

Recommended

No action is required.

Action

SEC-1337

Message Failed to access file <file name> and reverted the configuration.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified file was not accessible.

Recommended No action is required.

Action

ACUO

SEC-3014

Message Event: <Event Name>, Status: success, Info: <Event related info> <Event option>

server <Server Name> for AAA services.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the AAA (RADIUS/TACACS+) server configuration has been changed manually.

Recommended Verify that the RADIUS/TACACS+ configuration was changed intentionally. If the RADIU/TACACS+

Action configuration was changed intentionally, no action is required. If the RADIUS/TACACS+ configuration

was not changed intentionally, take appropriate action as defined by your enterprise security policy.

SEC-3016

Message Event: <Event Name>, Status: success, Info: Attribute [<Attribute Name>] of

<Attribute related info> server <server ID> changed <Attribute related info, if</pre>

any>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified attribute of the remote AAA (RADIUS/TACACS+) server has been changed

manually.

Recommended

Action

Verify that the attribute was changed intentionally. If the attribute was changed intentionally, no action is required. If the attribute was not changed intentionally, take appropriate action as defined by your

enterprise security policy.

SEC-3017

Message Event: <Event Name>, Status: success, Info: <Event Related Info>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the remote authentication dial-in user service (RADIUS) or lightweight directory access

protocol (LDAP) configuration has been changed manually.

Recommended Verify that the RADIUS or LDAP configuration was changed intentionally. If the RADIUS or LDAP

Action configuration was changed intentionally, no action is required. If the RADIUS or LDAP configuration was

not changed intentionally, take appropriate action as defined by your enterprise security policy.

SEC-3018

Message Event: <Event Name>, Status: success, Info: Parameter [<Parameter Name>] changed

from [<Old Value>] to [<New Value>].

Message Type AUDIT

Class SECURITY

Severity INFO

Action

Probable Cause Indicates that the specified password attribute has been changed.

Recommended Verify that the password attribute was changed intentionally. If the password attribute was changed

intentionally, no action is required. If the password attribute was not changed intentionally, take

appropriate action as defined by your enterprise security policy.

SEC-3019

Message Event: <Event Name>, Status: success, Info: Password attributes set to default

values.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the password attributes are set to default values.

Recommended

Action

Verify that the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3020

Message

Event: <Event Name>, Status: success, Info: Successful login attempt via <connection method and IP Address>.

Message Type

AUDIT

Class

SECURITY

Severity

INFO

Probable Cause

Indicates that the log in was successful. An IP address is displayed when the login occurs over a remote

connection.

Recommended

Action

Verify that the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3021

Message

Event: <Event Name>, Status: failed, Info: Failed login attempt through <connection method and IP Address>.

Message Type

Class SECURITY

AUDIT

Severity INFO

Probable Cause

Indicates that the log in attempt has failed.

Recommended

Action

Verify that the security event was planned. If the security event was planned, no action is required. If the security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3022

Message

Event: <Event Name>, Status: success, Info: Successful logout by user [<User>].

Message Type

AUDIT

Class

SECURITY

Severity

INFO

Probable Cause

Indicates that the specified user has successfully logged out.

Recommended

No action is required.

SEC-3023

Message Event: <Event Name>, Status: failed, Info: Account [<User>] locked, failed

password attempts exceeded.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the number of failed log in attempts due to incorrect password has exceeded the allowed

limit; the account has been locked.

Recommended The administrator can manually unlock the account.

Action

SEC-3024

Message Event: <Event Name>, Status: success, Info: User account [<User Name>], password

changed.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the password was changed for the specified user.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3025

Message Event: <Event Name>, Status: success, Info: User account [<User Name>] added.

 $\verb|Role: [<| Role Type>]|, Password [<| Password Expired or not>]|, Home Context [<| Home Password Expired or not>]|, Home Context [<| Home Password Expired or not>]|, Home Password Oxide or not>]|, Home Password Oxide or not>]|, Home Password Oxide or not>]|, Ho$

AD>], AD/VF list [<AD membership List>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that a new user account was created.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

Message Event: <Event Name>, Status: success, Info: User account [<User Name>], role

changed from [<Old Role Type>] to [<New Role Type>].

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the user account role has been changed.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3027

Message Event: <Event Name>, Status: success, Info: User account [<User Name>] [<Changed

Attributes>].

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates that the user account properties were changed.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3028

Message Event: <Event Name>, Status: success, Info: User account [<User Name>] deleted.

Message Type AUDIT

Action

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified user account has been deleted.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

Message Event: <Event Name>, Status: success, Info: <Event Specific Info>.

Message Type **AUDIT**

> Class **SECURITY**

Severity **INFO**

Probable Cause Indicates that the certificate authority (CA) certificate was imported successfully using the certutil import

Idapca command.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3034

Message Event: AAA Authentication Login Mode Configuration, Status: success, Info:

Authentication configuration changed from <Previous Mode> to <Current Mode>.

Message Type **AUDIT**

> Class **SECURITY**

Severity INFO

Action

Probable Cause Indicates that the authentication configuration has been changed.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3035

Message Event: ipfilter, Status: success, Info: <IP Filter Policy> ipfilter policy(ies)

saved.

Message Type AUDIT | LOG

> **SECURITY** Class

INFO Severity

Probable Cause Indicates that the specified IP filter policies have been saved.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy. Action

Message Event: ipfilter, Status: failed, Info: Failed to save changes for <IP Filter

Policy> ipfilter policy(s).

Message Type AUDIT | LOG

> Class **SECURITY**

INFO Severity

Action

Probable Cause Indicates that the specified IP filter policies have not been saved.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3037

Message Event: ipfilter, Status: success, Info: <IP Filter Policy> ipfilter policy

activated.

Message Type AUDIT | LOG

> Class **SECURITY**

INFO Severity

Action

Probable Cause Indicates that the specified IP filter policy has been activated.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3038

Message Event: ipfilter, Status: failed, Info: Failed to activate <IP Filter Policy>

ipfilter policy.

AUDIT | LOG Message Type

> **SECURITY** Class

Severity INFO

Probable Cause Indicates that the specified IP filter policy failed to activate.

Recommended Verify that the security event was planned. If the security event was planned, no action is required. If the Action

security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3039

Message Event: Security Violation , Status: failed, Info: Unauthorized host with IP address

<IP address of the violating host> tries to establish connection using <Protocol</pre>

Connection Type>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that a security violation was reported. The IP address of the unauthorized host is displayed in

the message.

Recommended Check for unauthorized access to the switch through the specified protocol connection.

Action

SEC-3045

Message Zeroization has been executed on the system.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the system has been zeroized.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

SEC-3046

Message The FIPS Self Tests mode has been set to <Self Test Mode>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that there was a change in the Federal Information Protection Standard (FIPS) self test mode.

Recommended Verify the security event was planned. If the security event was planned, no action is required. If the

Action security event was not planned, take appropriate action as defined by your enterprise security policy.

Message Status of bootprom access is changed using prom-access disable CLI: <Access

Status>.

Message Type AUDIT

Class SECURITY

Severity INFO

Probable Cause Indicates that the status of Boot PROM has changed using prom-access disable command. By default,

the Boot PROM is accessible.

Recommended

No action is required.

Action

SEC-3051

Message The license key <Key> is <Action>.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified license key has been added or removed.

Recommended

Action

No action is required.

SEC-3061

Message Role '<Role Name>' is created.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified role has been created.

Recommended No action is required.

SEC-3062

Message Role '<Role Name>' is deleted.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that the specified role has been deleted.

Recommended No action is required.

Action

SEC-3501

Message Role '<Role Name>' is changed.

Message Type AUDIT | LOG

Class SECURITY

Severity INFO

Probable Cause Indicates that attributes of the specified role have been changed.

Recommended No action is required.

SFLO Messages

SFLO-1001

Message sFlow is <state> globally.

Message Type DCE

Severity INFO

Probable Cause Indicates that sFlow is enabled or disabled globally.

Recommended No action is required.

Action

SFLO-1002

Message sFlow is <state> for port <name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that sFlow is enabled or disabled on the specified port.

Recommended No action is required.

Action

SFLO-1003

Message Global sFlow sampling rate is changed to <sample_rate>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the global sFlow sampling rate has been changed to the specified value.

Recommended No action is required.

SFLO-1004

Message Global sFlow polling interval is changed to <polling_intvl>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the global counter sampling interval has been changed to the specified value.

Recommended No action is required.

Action

SFLO-1005

Message sflow sampling rate on port <name> is changed to <sample_rate>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the sFlow sampling rate has been changed on the specified port.

Recommended No action is required.

Action

SFLO-1006

Message Type DCE

Severity INFO

Probable Cause Indicates that the sFlow polling interval has been changed on the specified port.

Recommended No action is required.

Action

SFLO-1007

Message <name> is <state> as sFlow collector.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified sFlow collector is either configured or not configured.

Recommended

No action is required.

Action

SFLO-1008

Message All the sFlow collectors are not configured.

Message Type DCE

Severity INFO

Probable Cause Indicates that none of the sFlow collectors are configured.

Recommended No action is required.

Action

SFLO-1009

Message Socket Operation Failed while connecting with the collector address.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the connection to the sFlow collector server failed.

Recommended Reconfigure the sFlow collector using the **sflow collector** command.

SLCD Messages

SLCD-1001

Message CF life percentage used up is between 90 - 95 on card No. <CF Card number in

integer>, Actual percentage <life span of CF used up in percentage>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the compact flash (CF) life span left over is a little more than 5 percent as reported by the

CF wear levelling statistics.

Recommended The CF card must be replaced as soon as possible. Contact your switch service provider for the CF card

Action replacement.

SLCD-1002

Message CF life span percentage is between 95 - 99 on card No. <CF Card number in

integer>, Actual percentage <Life span used up on CF in percentage>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the compact flash (CF) life span left over is between 1 and 5 percent as reported by the CF

wear levelling statistics.

Recommended The CF card must be replaced immediately for proper functioning. Contact your switch service provider

Action for the CF card replacement.

SLCD-1003

Message CF life span percentage left is less than 1 on card No. <CF Card number in

integer>, Actual percentage <Life span used up on CF card in percentage>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the compact flash (CF) life span left over is less than 1 percent as reported by the CF wear

levelling statistics.

Recommended A new CF card is required for proper functioning of the chassis. Contact your switch service provider for

Action the CF card replacement.

SLCD-1004

 $\textbf{Message} \qquad \text{CF life span percentage left on Card No < CF Card number in integer> is - < \!\!\!\!\text{Life}$

span left on CF card in percentage>.

Message Type LOG

Severity INFO

Probable Cause Indicates the available life span of the compact flash (CF) as reported by the CF wear levelling statistics.

Recommended No action is required.

Action

SLCD-1005

Message Spare Blocks percentage left on Card No. <CF Card number in integer> is between

5-10, Actual percentage is - <Spare Blocks left in percentage>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the spare blocks left on the compact flash (CF) card is between 5 and 10 percent as

reported by the CF wear levelling statistics.

Recommended The CF card must be replaced as soon as possible. Contact your switch service provider for the CF card

Action replacement.

SLCD-1006

Message Spare Blocks percentage left on CF Card No. <CF Card number in integer> is between

1-5, Actual percentage is - <Spare Blocks left in percentage>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the spare blocks left on the compact flash (CF) card is between 1 and 5 percent as

reported by the CF wear levelling statistics.

Recommended The CF card must be replaced immediately for proper functioning. Contact your switch service provider

Action for the CF card replacement.

SLCD-1007

Message Spare Blocks percentage left on CF Card No. < CF Card number in integer> are less

than 1, Actual percentage is - <Spare Blocks left in percentage>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the spare blocks left on the compact flash (CF) card is less than 1 percent as reported by

the CF wear levelling statistics.

Recommended A new CF card is required for proper functioning of the chassis. Contact your switch service provider for

Action the CF card replacement.

SLCD-1008

Message Spare Blocks percentage left on CF Card No. < CF Card number in integer > are -

<Spare Blocks left in percentage>.

Message Type LOG

Severity INFO

Probable Cause Indicates the percentage of the spare blocks left on the compact flash (CF) card as reported by the CF

wear levelling statistics.

Recommended No action is required.

Action

SLCD-1009

Message Unable to get Wear leveling stats for CF card No. < CF Card number in integer >.

Message Type LOG

Severity ERROR

Probable Cause Indicates that wear leveling data cannot be retrieved from the attached compact flash (CF) card.

Recommended Check the availability and healthiness of the CF card immediately for proper functioning.

SLCD-1010

Message CF wear leveling daemon Failed to find any western digital (WD) CF cards attached.

Message Type LOG

Severity ERROR

Probable Cause Indicates an error in enumerating the attached compact flash (CF) cards.

Recommended Check the availability and connection to the CF cards immediately for proper functioning.

Action

SLCD-1011

Message CF life percentage used for card No. <CF Card number in integer> is es span of

CF used up in percentage>.

Message Type LOG

Severity INFO

Probable Cause Indicates the used life span of the compact flash (CF) card as reported by the CF wear levelling statistics.

Recommended No action is required.

SNMP Messages

SNMP-1001

Message SNMP service is not available <Reason>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Simple Network Management Protocol (SNMP) service could not be started because of

the specified reason. You will not be able to query the switch through SNMP.

Recommended Verify that the IP address for the Ethernet and Fibre Channel interface is set correctly using the **show**

interface management command. If the specified reason is an initialization failure, reload the switch.

SNMP-1002

Message SNMP <Error Details> initialization failed.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the initialization of the Simple Network Management Protocol (SNMP) service failed and

you will not be able to query the switch through SNMP.

Recommended Reload or power cycle the switch. This will automatically initialize SNMP.

Action

SNMP-1003

Message Distribution of Community Strings to Secure Fabric failed.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the changes in the Simple Network Management Protocol (SNMP) community strings

could not be propagated to other switches in the secure fabric.

Recommended Retry changing the SNMP community strings on the primary switch using the snmp-server community

Action command.

SNMP-1004

Message Incorrect SNMP configuration.

Message Type FFDC | LOG

Severity ERROR

Probable Cause Indicates that the Simple Network Management Protocol (SNMP) configuration is incorrect and the

SNMP service will not work correctly.

Recommended Change the SNMP configuration using the **config snmp-server** command.

Action

SNMP-1005

Message SNMP configuration attribute, <Changed attribute>, has changed from <Old Value> to

<New Value>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Simple Network Management Protocol (SNMP) configuration has changed. The

parameter that was modified is displayed along with the old and new values of that parameter.

Recommended E

Action

Execute the **show running-config snmp-server** command to view the new SNMP configuration.

SS Messages

SS-1000

Message copy support has uploaded support information to the host with IP address <host

ip>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the copy support command was used to transfer the support information to a remote

location.

Recommended

Action

No action is required.

SS-1001

Message copy support upload operation to host IP address <host ip> aborted.

Message Type LOG

Severity WARNING

Probable Cause

Indicates that a file copy error occurred during execution of the **copy support** command. Complete error information cannot always be displayed in this message because of possible errors in the subcommands being executed by the **copy support** command.

The file copy error can occur due to one of the following reasons:

- Could not connect to remote host
- Could not connect to remote host timed out
- Transfer failed
- Transfer failed timed out
- Directory change failed
- Directory change failed timed out
- Malformed URL
- Usage error
- Error in login configuration file
- Session initialization failed
- Unknown remote host error

Recommended Action

Check and correct the remote server settings and configuration and then execute the **copy support** command again.

If the problem persists, contact your system administrator.

SS-1002

Message copy support has stored support information to the USB storage device.

Message Type LOG

Severity INFO

Probable Cause Indicates that the copy support command was used to transfer support information to an attached USB

storage device.

Recommended

Action

No action is required.

SS-1003

Message copy support operation to USB storage device aborted.

Message Type LOG

Severity WARNING

Probable Cause Indicates that a USB operation error occurred during execution of the **copy support** command.

Complete error information cannot always be displayed in this message because of possible errors in

subcommands being executed by the **copy support** command.

Recommended Make sure that the attached USB device is enabled.

Action

Execute the **usb on** command to enable an attached USB device. After the USB problem is corrected,

execute the copy support command again.

SS-1004

Message One or more modules timed out during copy support. Retry copy support with timeout

option to collect all modules.

Message Type LOG

Severity WARNING

Probable Cause Indicates timeout in modules during execution of the copy support command.

Recommended Execute the **copy support** command again.

SSMD Messages

SSMD-1001

Message Failed to allocate memory: (<function name>).

Message Type DCE

Severity ERROR

Probable Cause Indicates that the specified function has failed to allocate memory.

Recommended Check the memory usage on the switch using the **show process memory** command.

Action Reload or power cycle the switch.

SSMD-1002

Message Failed to initialize <module> rc = <error>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that initialization of a module within the system services manager (SSM) has failed.

Recommended Download a new firmware version using the **firmware download** command.

Action

SSMD-1003

Message Failed to lock semaphore mutex: (<function name>).

Message Type DCE

Severity ERROR

Probable Cause Indicates that the specified function has failed to lock the mutex (semaphore).

Recommended Reload or power cycle the switch.

SSMD-1004

Message Failed to unlock semaphore mutex: (<function name>).

Message Type DCE

Severity ERROR

Probable Cause Indicates that the specified function has failed to unlock the mutex (semaphore).

Recommended Reload or power cycle the switch.

Action

SSMD-1005

Message SSM startup failed.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected severe error during basic start up and initialization.

Recommended Reload or power cycle the switch.

Action If the problem persists, download a new firmware version using the firmware download command.

SSMD-1006

Message SSM ASIC downland buffer overflow (size <required buffer size> > max <max buffer

size>) in function <function name>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected severe error when fill in the I/O control (IOCTL) structure.

Recommended Reload or power cycle the switch.

Action If the problem persists, download a new firmware version using the **firmware download** command.

SSMD-1007

Message Error:<function name>: <error message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

error

Recommended Reload or power cycle the switch.

Action If the problem persists, download a new firmware version using the **firmware download** command.

SSMD-1200

Message QoS failed programming ASIC <ASIC slot number>/<ASIC chip number> Multicast Rate

Limit.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in the programming dataplane application-specific integrated circuit (ASIC) for

enforcing the multicast rate limit feature.

Recommended Delete and reapply the quality of service (QoS) multicast rate limit policy using the **qos rcv-queue**

Action multicast rate-limit command.

If the problem persists, reload or power cycle the switch.

SSMD-1201

Message QoS failed programming ASIC <ASIC slot number>/<ASIC chip number> Multicast Tail

Drop.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in the programming dataplane application-specific integrated circuit (ASIC) for

enforcing the multicast tail drop feature.

Recommended Delete and reapply the quality of service (QoS) multicast tail drop policy using the qos rcv-queue

Action multicast threshold command.

SSMD-1202

Message QoS failed programming interface 0x<Interface ID> 802.3x Pause flow control.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in the programming dataplane application-specific integrated circuit (ASIC) for

enforcing the interface 802.3x pause flow control feature.

Recommended Delete and reapply the quality of service (QoS) 802.3x pause flow control policy using the **qos**

Action flowcontrol command.

If the problem persists, reload or power cycle the switch.

SSMD-1203

Message QoS failed programming interface 0x<Interface ID> PFC flow control.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) encountered an

unexpected error in the programming dataplane application-specific integrated circuit (ASIC) for

enforcing the interface priority flow control (PFC) feature.

Recommended Delete and reapply the quality of service (QoS) PFC policy using the qos flowcontrol pfc cos

Action command.

If the problem persists, reload or power cycle the switch.

SSMD-1204

Message QoS failed initializing ASIC <ASIC slot number>/<ASIC chip number>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in initializing the dataplane application-specific integrated circuit (ASIC) quality of

service (QoS) infrastructure.

Recommended Reload or power cycle the switch.

SSMD-1205

Message CEE failed programming ETS policy for CEE Map <CEE Map name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming dataplane application-specific integrated circuit (ASIC) for enforcing

the Converged Enhanced Ethernet (CEE) map enhanced transmission selection (ETS) feature.

Recommended Delete and reapply the CEE map ETS policy using the **cee-map default** command.

Action If the problem persists, reload or power cycle the switch.

SSMD-1206

Message CEE failed programming CoS to PGID policy for CEE Map <CEE Map name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for enforcing the Converged Enhanced Ethernet (CEE) map CoS-to-priority group ID (PGID) mapping

feature.

Recommended Delete and reapply the CEE map CoS-to-PGID policy using the **cee-map default** command.

Action If the problem persists, reload or power cycle the switch.

SSMD-1207

Message QoS failed programming interface 0x<Interface ID> Default CoS.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the interface default class of service (CoS) feature.

Recommended Delete and reapply the quality of service (QoS) interface default CoS policy using the **qos cos**

Action command

SSMD-1208

Message QoS failed programming interface 0x<Interface ID> Trust.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the interface trust feature.

Recommended Delete and reapply the quality of service (QoS) interface trust policy using the **qos trust cos** command.

Action If the problem persists, reload or power cycle the switch.

SSMD-1209

Message QoS failed programming interface 0x<Interface ID> CoS Mutation map.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the CoS-mutation mapping feature.

Recommended Delete and reapply the quality of service (QoS) interface CoS-mutation policy using the qos

cos-mutation command.

If the problem persists, reload or power cycle the switch.

SSMD-1210

Message QoS failed programming interface 0x<Interface ID> CoS to Traffic Class map.

Message Type DCE

Action

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the CoS-to-traffic-class mapping feature.

Recommended Delete and reapply the quality of service (QoS) interface CoS-to-traffic-class policy using the **qos**

Action cos-traffic-class command.

7 s

SSMD-1211

Message QoS failed programming ASIC <ASIC slot number>/<ASIC chip number> Scheduler

Control.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the packet scheduler control feature.

Recommended Delete and reapply the quality of service (QoS) packet scheduler control policy using the **qos queue**

Action scheduler command.

If the problem persists, reload or power cycle the switch.

SSMD-1212

Message QoS failed programming ASIC <ASIC slot number>/<ASIC chip number> Multicast

Scheduler Control.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the multicast packet scheduler control feature.

Recommended Delete and reapply the quality of service (QoS) multicast packet scheduler control policy using the qos

Action queue multicast scheduler command.

If the problem persists, reload or power cycle the switch.

SSMD-1213

Message QoS failed programming interface 0x<Interface ID> CoS Tail Drop Threshold.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the interface class of service (CoS) tail drop threshold feature.

Recommended Delete and reapply the quality of service (QoS) CoS tail drop threshold policy using the qos rcv-queue

Action cos-threshold command.

SSMD-1214

Message QoS failed programming interface 0x<Interface ID> CoS Tail Drop Threshold.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the interface class of service (CoS) tail drop threshold feature.

Recommended Delete and reapply the quality of service (QoS) CoS tail drop threshold policy using the qos rcv-queue

Action cos-threshold command.

If the problem persists, reload or power cycle the switch.

SSMD-1215

Message QoS failed programming interface 0x<Interface ID> CoS Tail Drop Threshold.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the interface class of service (CoS) tail drop threshold feature.

Recommended Delete and reapply the quality of service (QoS) CoS tail drop threshold policy using the qos rcv-queue

Action cos-threshold command.

If the problem persists, reload or power cycle the switch.

SSMD-1216

Message QoS failed programming interface 0x<Interface ID> Pause.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the interface pause feature.

Recommended Delete and reapply the quality of service (QoS) pause policy.

SSMD-1217

Message Qos CEE could not comply with FCoE scheduler policy for CEE Map <CEE Map name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) was unable to translate

the Converged Enhanced Ethernet (CEE) Map and Fibre Channel over Ethernet (FCoE) configuration into an Enhanced Transmission Selection (ETS) scheduler policy, which can be implemented by the

dataplane application-specific integrated circuit (ASIC).

Recommended Reconfigure the CEE map and FCoE configuration such that it translates into an ETS scheduler policy

requiring eight or fewer traffic classes.

SSMD-1218

Message QoS failed programming interface 0x<Interface ID> Priority Tag.

Message Type DCE

Action

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the interface priority-tag feature.

Recommended Delete and reapply the QoS interface priority-tag policy using the **priority-tag** command.

Action If the problem persists, reload or power cycle the switch.

SSMD-1219

Message QoS failed programming interface 0x<Interface ID> CoS7 TCAM.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the Data Center Ethernet (DCE) System Services Manager (SSM) has encountered an

unexpected error in programming the dataplane application-specific integrated circuit (ASIC) for

enforcing the interface CoS7 ternary content addressable memory (TCAM) feature.

Recommended Delete and reapply the interface CoS7 priority-tag policy using the **priority-tag** command.

SSMD-1220

Message QoS failed adding member port 0x<member port> to LAG 0x<LAG port>.

Message Type DCE

Severity WARNING

Probable Cause Indicates conflicting quality of service (QoS) configurations on the member port.

Recommended Delete the Converged Enhanced Ethernet (CEE) or Fibre Channel over Ethernet (FCoE) configuration

Action on the member port.

SSMD-1221

Message QoS configuration rejected due to Long Distance configuration restriction on port

<member port>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the number of inter-switch links (ISLs) supported by the long distance configuration has

reached the maximum.

Recommended Disable the ISL port using the **no fabric isl enable** command.

Action

SSMD-1222

Message Long distance configuration cannot be completed for Chip <ASIC slot number>/<ASIC

chip number> because ports are not shut down. Maximum retry count exceeded.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the network service module (NSM) has failed to disable all the ports after maximum retry

attempts.

Recommended Delete and reconfigure long distance on the link using the **long-distance-isl** command.

SSMD-1223

Message QoS failed applying RED profile <RED profile> to PO member port:0x<Member port>.

Message Type DCE

Severity ERROR

Probable Cause Indicates lack of chip resources for configuring a random early drop (RED) profile on the specified

member port.

Recommended Delete RED configuration on other ports of the chip and re-configure RED on port-channel using the **qos**

Action red-profile command.

SSMD-1224

Message L3 trust cannot be applied on PO member port:0x<Interface ID>, corresponding port

group has already max 4 L3 trust ports.

Message Type DCE

Severity ERROR

Probable Cause Indicates lack of chip resources for configuring L3prio trust on the specified member port.

Recommended Delete some of the Layer 3 trust ports on the chip, to which the member port belong.

Action

SSMD-1225

Message QoS failed applying CEE to member port:0x<Interface ID> as the port group it

belongs to has LD ISL enabled.

Message Type DCE

Action

Severity ERROR

Probable Cause Indicates that Converged Enhanced Ethernet (CEE) could not be applied on the chip, on which long

distance inter-switch link (ISL) is enabled.

Recommended Disable long distance ISL using no long-distance-isl command and then enable CEE on the member

port chip.

Message CEE Map <ceemap> is created with precedence cedence>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified Converged Enhanced Ethernet (CEE) map has been created.

Recommended No action is required.

Action

SSMD-1301

Message CEE Map <ceemap> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified Converged Enhanced Ethernet (CEE) map has been deleted.

Recommended No action is required.

Action

SSMD-1302

Message CEE Map <ceemap> priority table <pg_ids> is <action>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified priority groups (PGs) have been added to or removed from the existing

Converged Enhanced Ethernet (CEE) map.

Recommended No action is required.

SSMD-1303

Message CEE Map <ceemap> priority group <pg_id> with weight <PGID_weight> is created with

PFC <pfc>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified priority group has been created.

Recommended No action is required.

Action

SSMD-1304

Message CEE Map <ceemap> priority group <pg_id> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified priority group has been deleted.

Recommended No action is required.

Action

SSMD-1305

Message CEE Map <ceemap> priority group <pg_id> weight is changed from <PGID_weight_new>

to <PGID_weight_old>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the weighting of the specified priority group has been changed.

Recommended No action is required.

Message CEE Map <ceemap> priority group <pg_id> is PFC <pfc_status>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the priority-based flow control (PFC) status has been changed for the specified priority

aroup

Recommended No action is required.

Action

SSMD-1307

Message <ACL Type> access list <ACL Name> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list has been created.

Recommended No action is required.

Action

SSMD-1308

Message <ACL Type> access list <ACL Name> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list has been deleted.

Recommended No action is required.

Action

SSMD-1309

Message <ACL Type> access list <ACL Name> rule sequence number <rule_sq_no> is <action>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list rules have been added to or removed from an existing policy.

Recommended

No action is required.

Action

SSMD-1312

Message <map_type> <map_name> assigned to interface <Interface Name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that a user profile map has been assigned to the specified interface.

Recommended No action is required.

Action

SSMD-1313

Message <map_type> <map_name> removed from interface <Interface Name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that a user profile map has been removed from the specified interface.

Recommended No action is required.

Action

SSMD-1314

Message CEE Map <ceemap> precedence changed from cprecedence_old> to precedence_new>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified Converged Enhanced Ethernet (CEE) map precedence has been changed.

Recommended No action is required.

Message CEE Map <ceemap> remap <lossless or fabric priority> to priority <remapped value>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the priority cost of service (CoS) value of the specified Converged Enhanced Ethernet

(CEE) map has changed.

Recommended

Action

No action is required.

SSMD-1400

Message <ACL Type> access list <ACL Name> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list has been created.

Recommended No action is required.

Action

SSMD-1401

Message <ACL Type> access list <ACL Name> is recorded.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list type and name has been recorded as a reference for ACL binding

in future.

Recommended

No action is required.

SSMD-1402

Message <ACL Type> access list <ACL Name> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list has been deleted.

Recommended No action is required.

Action

SSMD-1403

Message <ACL Type> access list <ACL Name> record is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the access list name and type recorded for bind forward reference has been deleted.

Recommended No action is required.

Action

SSMD-1404

Message <ACL Type> access list <ACL Name> rule sequence number <rule_sq_no> is <action>

Message Type DCE

Severity INFO

Probable Cause Indicates that the access list rules are added to or removed from an existing policy.

Recommended No action is required.

Action

SSMD-1405

Message <ACL Type> access list <ACL Name> configured on interface <Interface Name> at

<Direction>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list has been configured on the interface.

Recommended

No action is required.

Action

SSMD-1406

Message <ACL Type> access list <ACL Name> is removed from interface <Interface Name> at

<Direction>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list has been removed from the interface.

Recommended No action is required.

Action

SSMD-1407

Message <ACL Type> access list <ACL Name> active on interface <Interface Name> at

<Direction>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access list has been configured on the interface.

Recommended No action is required.

Action

SSMD-1408

Message <Number of ACL Rules> rules added to <ACL Type> access list <ACL Name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified rules are added to the access control list (ACL).

Recommended No action is required.

SSMD-1436

Message <ACL Type> access list <ACL Name> partially active on interface <Interface Name>

at <Direction>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the specified access control list (ACL) was not fully instantiated into the ternary content

addressable memory (TCAM).

Recommended Remove the specified ACL and other unused ACLs that are applied using the ip access-list command,

Action and then instantiate ACL into TCAM again.

SSMD-1437

Message <ACL Type> access list <ACL Name> inactive on interface <Interface Name> at

<Direction>.

Message Type DCE

Severity WARNING

Probable Cause Indicates the specified access control list (ACL) was not instantiated into the ternary content addressable

memory (TCAM).

Recommended Remove the specified ACL and other unused ACLs that are applied using the **ip access-list** command,

Action and then instantiate ACL into TCAM again.

SSMD-1438

Message <ACL Type> access list <ACL Name> configured on interface <Interface Name> at

<Direction> has rule(s) which are not supported on this platform.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the specified access control list (ACL) has rules which are not supported on this platform.

Recommended Remove inactive rules using the **ip access-list** command and add rules which are supported on this

Action platform.

Message Rule with sequence number <ACL Rule Sequence number> of <ACL Type> access list

<ACL Name> configured on interface <Interface Name> at <Direction> is not

supported on this platform.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the specified access control list (ACL) has rules which are not supported on this platform.

Recommended Remove inactive rules using the ip access-list command and add rules which are supported on this

Action platform.

SSMD-1500

Message <Feature Name> TCAM region usage on chip <Slot number>/<Chip Number> is below

<Usage percentage> percent.

Message Type DCE

Severity WARNING

Probable Cause Indicates that ternary content addressable memory (TCAM) usage on the chip is below threshold.

Recommended TCAM is full and therefore clear some of the entries or do not add entries.

Action

SSMD-1536

Message <Feature Name> TCAM region usage on chip <Slot number>/<Chip Number> is above

<Usage percentage> percent.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the access control list (ACL), which is bound to interfaces in consuming ternary content

addressable memory (TCAM) entries in the hardware.

Recommended Remove ACLs which are not required using the **ip access-list** command.

SSMD-1537

Message <Feature Name> TCAM region on chip <Slot number>/<Chip Number> is <Usage

percentage> percent full.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the access control list (ACL), which is bound to interfaces is consuming ternary content

addressable memory (TCAM) entries in the hardware.

Recommended Remove ACLs which are not required using the **ip access-list** command.

Action

SSMD-1571

Message Error <Error code> Creating region Feature: <Logical Device ID> Region: <Region ID>

Chip:0x<Chip Index>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the application-specific integrated circuit (ASIC) driver has returned an error.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

SSMD-1600

Message Policy map <Policy map name> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policy map has been created.

Recommended No action is required.

Message Policy map Policy map name is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policy map has been deleted.

Recommended No action is required.

Action

SSMD-1602

Message Class map <Class map name> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified class map has been created.

Recommended No action is required.

Action

SSMD-1603

Message Class map <class map name> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified class map has been deleted.

Recommended No action is required.

Action

SSMD-1604

Message Police priority map <police priority map name> is created.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified police priority map has been created.

Recommended

No action is required.

Action

SSMD-1605

Message Police priority map <police priority map name> is deleted.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified police priority map has been deleted.

Recommended No action is required.

Action

SSMD-1606

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified class map has been added to the policy map.

Recommended No action is required.

Action

SSMD-1607

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified class map has been removed from the policy map.

Recommended No action is required.

Message Policer attribute <policer attribute type> is <action> to <policer attribute

value> for policy map <policy map name> and class map <class map name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policer attribute (rate limiting value) is set or updated for the policy and class

map.

Recommended

Action

No action is required.

SSMD-1610

Message Policer attribute <policer attribute type> is removed from policy map <policy map

name> and class map <class map name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policer attribute (rate limiting value) has been removed from the policy and

class map.

Recommended No act

Action

No action is required.

SSMD-1611

Message Policer attribute <policer attribute type> is <action> to <Policer attribute

value> for policy map <policy map name> and class map <class map name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policer attribute (marking value) is set or updated for the policy and class

map.

Recommended No action is required.

SSMD-1612

Message Policer attribute <policer attribute type> is removed from policy map <policy map

name> and class map <class map name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policer attribute (marking value) has been removed from the policy and class

map.

Recommended N

Action

No action is required.

SSMD-1613

Message Policer attributes removed from policy map <policy map name > and class map <class

map name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that all policer attributes have been removed from the specified policy and class map.

Recommended No action is required.

Action

SSMD-1614

Message <cos map type> CoS map is <action> to

<cos0>,<cos1>,<cos2>,<cos3>,<cos4>,<cos5>,<cos6>,<cos7> for police priority map

<police priority map name>

Message Type DCE

Severity INFO

Probable Cause Indicates that the conform or exceed cost of service (CoS) map is set or updated for the police priority

map.

Recommended No action is required.

name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the conform or exceed cost of service (CoS) map has been removed from the police

priority map.

Recommended No action is required.

Action

SSMD-1618

Message Policy map <policy map name > is applied on interface <interface name > in

<direction> direction.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policy map has been applied on the interface.

Recommended No action is required.

Action

SSMD-1619

Message Policy map <policy map name> is removed from interface <interface name> in

<direction> direction.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policy map has been removed from the interface.

Recommended No action is required.

SSMD-1620

Message Policer attribute priority map <police priority map name> is added to policy map

<policy map name> and class map <class map name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policer attribute priority map has been added to the policy and class map.

Recommended No action is required.

Action

SSMD-1621

Message Policer attribute priority map is removed from policy map <policy map name> and

class map <class map name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified policer attribute priority map has been removed from the policy and class

map.

Recommended No action is required.

Action

SSMD-1622

Message Operational policer attr CBS value set to <operational cbs> on interface

<interface name> in <direction> direction for policy map <policy map name> and

class map <class map name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the operational committed burst size (CBS) is set on the specified interface for the policy

and class map.

Recommended No action is required.

Message Policer resource limit reached.

Message Type DCE

Severity WARNING

Probable Cause Indicates unavailability of policer resources.

Recommended Remove unnecessary class maps from policy map using the **no class** command.

Action

SSMD-1651

Message Failed to apply policy map <policy map name> on interface <interface name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the specified policy map could not be applied on the interface.

Recommended Apply the policy map on interface again using the **service-policy** command.

Action

SSMD-1652

Message Type DCE

Severity WARNING

Probable Cause Indicates that the specified policy map could not be removed from the interface.

Recommended Remove the policy map on interface again using the **no service-policy** command.

Action

SSMD-1653

Message Failed to retreive police statistics for interface <interface name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that an attempt to retrieve the police statistics for policy map on the specified interface has

failed.

Recommended Action

Retrieve the police statistics for interface again using the **show policymap** command.

SSMD-1654

Message Failed to clear police statistics for interface <interface name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that an attempt to clear the policy map statistics on the specified interface has failed.

Recommended Clear the police statistics again using the clear counters policymap interface tengigabitethernet

Action command.

SSMD-1655

Message Failed to clear all police statistics.

Message Type DCE

Severity WARNING

Probable Cause Indicates that an attempt to clear all policy map statistics has failed.

Recommended Clear the police statistics again using the **clear counters policymap** command.

Action

SSMD-1656

Message Failed to update police priority map ropolice priority map name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that an attempt to update the specified police priority map has failed.

Recommended Update the police priority map again using the **no conform | exceed** command.

Message Failed to remove police priority map <police priority map name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that an attempt to delete the specified police priority map has failed.

Recommended Delete the police priority map again.

Action

SSMD-1658

Message Policy map <policy map name > not found for applying it on interface <interface

name> in <direction> direction.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the specified policy map is not found for binding policy map to the interface.

Recommended Check whether the policy map exists. If the policy map does not exist, add a policy map using the

Action policy-map command.

SSMD-1659

name> for policy map <policy map name> and class map <class map name> on interface

<interface name> in <direction> direction.

Message Type DCE

Severity WARNING

Probable Cause Indicates that a lossy cost of service (CoS) value is remapped to lossless CoS value.

Recommended Remove conflicting CoS values in conform and exceed map and update prio map using the conform |

Action exceed command.

SSMD-1660

Message Policer attribute <policer action> TC is set to lossless TC for policy map <policy

map name> class map <class map name> on interface <interface name> in <direction>

direction.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the conform or exceed traffic class is set to lossless traffic class.

Recommended Modify the conform or exceed traffic class using the **conform | exceed** command.

Action

SSMD-1700

Message Storm control for <BUM_protocol_type> traffic with a rate of <BUM_rate_bps> bps

configured on interface <interface_name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the broadcast, unknown unicast, and multicast (BUM) storm control has been enabled

manually for a given protocol on the specified interface.

Recommended No action is required.

Action

SSMD-1701

Message Storm control for <BUM_protocol_type> traffic successfully instantiated on

interface <interface_name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that broadcast, unknown unicast, and multicast (BUM) configuration has been instantiated into

the hardware.

Recommended No action is required.

Message Storm control instantiation for <BUM_protocol_type> traffic failed interface

<interface_name>. Reason code <failure_code>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that broadcast, unknown unicast, and multicast (BUM) configuration failed to be instantiated

into the hardware.

Recommended

Action

Action varies depending on reason code.

SSMD-1703

Message Storm control for <BUM_protocol_type> traffic removed from interface

<interface_name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the broadcast, unknown unicast, and multicast (BUM) storm control has been disabled

manually for a given protocol on a specific interface.

Recommended No action is required.

Action

SSMD-1704

Message Unable to remove <BUM_protocol_type> storm control from interface

<interface_name>. Reason code <failure_code>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that broadcast, unknown unicast, and multicast (BUM) storm control could not be disabled on

the specified interface.

Recommended No action is required.

SSMD-1705

Message <BUM_protocol_type> traffic rate has been exceeded on interface <interface_name>.

Message Type DCE

Severity WARNING

Probable Cause Indicates that the broadcast, unknown unicast, and multicast (BUM) monitor routine has detected rate

violation.

Recommended No action is required.

Action

SSMD-1706

Message <BUM_protocol_type> traffic rate returned to conforming on interface

<interface_name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that broadcast, unknown unicast, and multicast (BUM) storm control has been disabled

manually for a given protocol on the specified interface.

Recommended No action is required.

Action

SSMD-1707

Message <BUM_protocol_type> traffic rate has been exceeded interface <interface_name>.

Interface will be shut down.

Message Type DCE

Action

Severity WARNING

Probable Cause Indicates that the broadcast, unknown unicast, and multicast (BUM) monitor routine has detected rate

violation. The interface has been shut down.

Recommended Disable BUM storm control on the interface using the no storm-control ingress command; then

re-enable the interface (using the no shutdown command) and BUM storm control (using the

storm-control ingress command).

Message Unable to obtain BUM storm control status for interface <interface_name>. Reason

code <failure_code>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the broadcast, unknown unicast, and multicast (BUM) monitoring routine has failed to

obtain the storm control status from the hardware.

Recommended Execute the **copy support** command and contact your switch service provider.

Action

SSMD-1900

Message Security sub-profile is created for port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that a security sub-profile has been created for the specified port profile.

Recommended No action is required.

Action

SSMD-1901

Message ACL <ACL name> is configured successfully for security sub-profile of port-profile

<Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access control list (ACL) has been configured for security sub-profile.

Recommended No action is required.

SSMD-1902

Message ACL <ACL name> is removed successfully for security sub-profile of port-profile

<Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified access control list (ACL) has been removed for security sub-profile.

Recommended No action is required.

Action

SSMD-1903

Message CoS <Cos value> is configured successfully for QoS sub-profile of port-profile

<Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified cost of service (CoS) has been configured for quality of service (QoS)

sub-profile.

Recommended No action is required.

Action

SSMD-1904

Message Trust is configured successfully for QoS sub-profile of port-profile <Profile

name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that trust has been configured for quality of service (QoS) sub-profile.

Recommended No action is required.

Message Trust is removed successfully for QoS sub-profile of port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that trust has been removed for quality of service (QoS) sub-profile.

Recommended No action is required.

Action

SSMD-1906

Message Flowcontrol Tx <Tx flag> Rx <Rx flag> is configured successfully for QoS

sub-profile of port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that flowcontrol has been configured for quality of service (QoS) sub-profile.

Recommended No action is required.

Action

SSMD-1907

Message CoS-mutation <Map name> is configured successfully for QoS sub-profile of

port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that CoS-mutation has been configured for quality of service (QoS) sub-profile.

Recommended No action is required.

SSMD-1908

Message CoS-mutation is removed successfully for QoS sub-profile of port-profile <Profile

name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the CoS-mutation has been removed for quality of service (QoS) sub-profile.

Recommended No action is required.

Action

SSMD-1909

Message CoS-traffic-class <Map name> is configured successfully for QoS sub-profile of

port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified CoS-to-traffic-class mapping has been configured for quality of service (QoS)

sub-profile.

Recommended No action is required.

Action

SSMD-1910

Message CoS-traffic-class is removed successfully for QoS sub-profile of port-profile

<Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the CoS-to-traffic-class mapping has been removed for quality of service (QoS) sub-profile.

Recommended No action is required.

Message CEE is removed successfully for QoS sub-profile of port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that Converged Enhanced Ethernet (CEE) has been removed for quality of service (QoS)

sub-profile.

Recommended

Action

No action is required.

SSMD-1912

Message CEE <Map name> is configured successfully for QoS sub-profile of port-profile

<Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that Converged Enhanced Ethernet (CEE) has been configured for quality of service (QoS)

sub-profile.

Recommended

Action

No action is required.

SSMD-1913

Message Flowcontrol PFC-CoS <Pfc-Cos value> Tx <Tx flag> Rx <Rx flag> is configured

Message Type DCE

Severity INFO

Probable Cause Indicates that the flowcontrol priority flow control (PFC) has been configured for quality of service (QoS)

sub-profile.

Recommended

Action

No action is required.

7 SSMI

SSMD-1914

SSMD-1914

Message QoS sub-profile is created for port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the quality of service (QoS) sub-profile has been created.

Recommended No action is required.

Action

SSMD-1915

Message Security sub-profile is deleted for port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the security sub-profile has been deleted.

Recommended No action is required.

Action

SSMD-1916

Message QoS sub-profile is deleted for port-profile <Profile name>.

Message Type DCE

Severity INFO

Probable Cause Indicates that the specified quality of service (QoS) sub-profile has been deleted.

Recommended No action is required.

SULB Messages

SULB-1100

Message Firmware <firmware operations: install, swap, reboot, commit, recover> begins on

<slot/partition>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the specified firmware operation has started on the specified slot or partition.

Recommended No action is required.

Action

SULB-1101

Message Firmware <firmware operations: install, swap, reboot, commit, recover> ends on

<slot/partition>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that the specified firmware operation has completed successfully on the specified slot or

partition.

Recommended No action is required.

Action

SULB-1102

Message Firmware <firmware operations: install, swap, reboot, commit, recover> failed on

<slot/partition> with error (<error code>).

Message Type AUDIT | LOG

Class FIRMWARE

Severity WARNING

Probable Cause Indicates that the specified firmware operation has failed on the specified slot or partition. The error code

indicates the reason for the failure.

The following table lists the error codes that provide more details on why the firmware operation failed.

TABLE 9 Error messages and error codes

Error message	Error code
"Upgrade is inconsistent."	0x10
"OSRootPartition is inconsistent."	0x11
"Unable to access the package list file. Check whether the file name is specified properly."	0x12
"Red Hat package manager (RPM) package database is inconsistent. Contact your service provider for recovery."	0x13
"Out of memory."	0x14
"Failed to download RPM package. Check if the firmware image is accessible."	0x15
"Unable to create firmware version file."	0x16
"Unexpected system error."	0x17
"Another firmware download is in progress."	0x18
"Error in releasing lock device."	0x19
"firmware commit failed."	0x1a
"Firmware directory structure is not compatible. Check whether the firmware is supported on this platform."	0x1b
"Failed to load the Linux kernel image. Contact your service provider to assistance."	0x1c
"OSLoader is inconsistent.	0x1d
"New image has not been committed. Execute the firmware commit command or the firmware restore and firmware download commands."	0x1e
"firmware restore is not needed."	0x1f
"Images are not mounted properly."	0x20
"Unable to uninstall old packages. Contact your service provider for assistance."	0x21
"firmware download has timed out."	0x23
"Out of disk space."	0x24
"Primary filesystem is inconsistent. Execute the firmware restore to restore the original firmware, or contact your service provider for recovery."	0x25
"The post-install script failed."	0x26
"Reload (partition) failed."	0x27
"Primary kernel partition is inconsistent. Contact your service provider for recovery."	0x28
"The pre-install script failed."	0x29
"Failed to install RPM package."	0x2b
"Cannot downgrade directly to this version. Downgrade to an intermediate version and then download the desired version."	0x2c
"Failed to validate firmware signature."	0x3e
Talled to Validate III III ware signature.	
"Failed to swap the firmware partitions."	0x40

Recommended Action

Execute the **show firmwaredownloadstatus** command for more information. Restart the firmware operation if needed.

SULB-1103

Message Firmware download completed successfully on <slot/partition>.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that firmware download has completed successfully on the specified slot or partition.

Recommended No action is required.

Action Execute the show firmwaredownloadstatus command for more information. Execute the show

version to verify the firmware version.

SULB-1104

Message Firmware download failed on <slot/partition> with error (<error code>).

Message Type AUDIT | LOG

Class FIRMWARE

Severity CRITICAL

Probable Cause

Indicates that firmware download has failed on the specified slot. The error code indicates the reason for the failure.

The following table lists the error codes that provide more details on why the firmware operation failed.

 TABLE 10
 Error messages and error codes

Error message	Error code
"Upgrade is inconsistent."	0x10
"OSRootPartition is inconsistent."	0x11
"Unable to access the package list file. Check whether the file name is specified properly."	0x12
"Red Hat package manager (RPM) package database is inconsistent. Contact your service provider for recovery."	0x13
"Out of memory."	0x14
"Failed to download RPM package. Check if the firmware image is accessible."	0x15
"Unable to create firmware version file."	0x16
"Unexpected system error."	0x17
"Another firmware download is in progress."	0x18

 TABLE 10
 Error messages and error codes

Error message	Error code
"Error in releasing lock device."	0x19
"firmware commit failed."	0x1a
"Firmware directory structure is not compatible. Check whether the firmware is supported on this platform."	Ox1b
"Failed to load the Linux kernel image. Contact your service provider to assistance."	0x1c
"OSLoader is inconsistent.	0x1d
"New image has not been committed. Execute the firmware commit command or the firmware restore and firmware download commands."	Ox1e
"firmware restore is not needed."	0x1f
"Images are not mounted properly."	0x20
"Unable to uninstall old packages. Contact your service provider for assistance."	0x21
"firmware download has timed out."	0x23
"Out of disk space."	0x24
"Primary filesystem is inconsistent. Execute the firmware restore to restore the original firmware, or contact your service provider for recovery."	0x25
"The post-install script failed."	0x26
"Reload (partition) failed."	0x27
"Primary kernel partition is inconsistent. Contact your service provider for recovery."	0x28
"The pre-install script failed."	0x29
"Failed to install RPM package."	0x2b
"Cannot downgrade directly to this version. Downgrade to an intermediate version and then download the desired version."	0x2c
"Failed to validate firmware signature."	0x3e
"Failed to swap the firmware partitions."	0x40
"Failed to load the PROM image. Contact your service provider for assistance."	0x41

Recommended Action

Execute the **show firmwaredownloadstatus** command for more information. Execute the **power-off** and **power-on** commands on the slot for recovery.

SULB-1105

Message Firmware upgrade session (<session ID>: <session subject>) starts.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that firmware upgrade has started.

Recommended

No action is required.

Action

SULB-1106

Message Firmware upgrade session (<session ID>: <session subject>) completes.

Message Type AUDIT | LOG

Class FIRMWARE

Severity INFO

Probable Cause Indicates that firmware upgrade has completed successfully.

Recommended Execute the **show firmwaredownloadstatus** command for more information.

Action

SULB-1107

Message Firmware upgrade session (<session ID>: <session subject>) failed but recovered.

Message Type LOG

Severity WARNING

Probable Cause Indicates that firmware upgrade has failed but was recovered.

Recommended Execute the **show firmwaredownloadstatus** command for more information. Execute the **firmware**

Action download command again if needed.

SULB-1108

Message Firmware upgrade session (<session ID>: <session subject>) failed.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that firmware upgrade has failed.

Recommended Execute the **show firmwaredownloadstatus** command for more information. Execute the **firmware**

Action download command again if needed.

SULB-1109

Message Firmware upgrade session (<session ID>: <session subject>) aborted.

Message Type LOG

Severity CRITICAL

Probable Cause Indicates that firmware upgrade has been aborted.

Recommended Execute the **firmware download** command again if needed.

SWCH Messages

SWCH-1001

Message Switch is not in ready state - Switch enable failed switch status= 0x<switch

status>, c_flags = 0x<switch control flags>.

Message Type LOG

Severity ERROR

Probable Cause Indicates failure to enable the switch because it is not in ready state.

Recommended If the message persists, execute the **copy support** command and contact your switch service provider.

Action

SWCH-1002

Message Security violation: Unauthorized device < wwn name of device > tries to flogin to

port <port number>.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the specified device is not present in the authorized profile list.

Recommended Verify that the device is authorized to log in to the switch. If the device is authorized, execute the **show**

secpolicy command to verify whether the specified device World Wide Name (WWN) is listed. If it is not

listed, execute the **secpolicy defined-policy** command to add this device to an existing policy.

SWCH-1003

Message Slot ENABLED but Not Ready during recovery, disabling slot = <slot number>(<return

value>).

Message Type LOG

Severity ERROR

Probable Cause Indicates that the slot state has been detected as inconsistent during failover or recovery.

Recommended For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface

Action module

For a compact switch, reload or power cycle the switch.

SWCH-1004

Message Interface module attach failed during recovery, disabling slot = <slot number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified interface module has failed during failover or recovery.

Recommended For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface

Action module

For a compact switch, reload or power cycle the switch.

SWCH-1005

Message Diag attach failed during recovery, disabling slot = <slot number>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the diagnostic interface module attach operation has failed during failover or recovery.

Recommended For a modular switch, execute the power-off and power-on commands to power cycle the interface

Action module.

For a compact switch, reload or power cycle the switch.

SWCH-1007

Message Switch port <port number> disabled due to \"<disable reason>\".

Message Type LOG

Severity WARNING

Probable Cause Indicates that the specified switch port is disabled due to the reason displayed in the message.

Recommended Take corrective action to restore the port based on the disable reason displayed in the message and then

Action execute the **shutdown** and **no shutdown** commands.

SWCH-1021

Message HA state out of sync: Standby MM (ver = <standby SWC version>) does not support

Dynamic area on default switch (Active MM version = <active SWC version>).

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby management module does not support dynamic area on the default switch.

Recommended Load a firmware version in which the standby management module supports dynamic area on the default

Action switch using the firmware download command.

TOAM Messages

TOAM-1000

Message Cannot run this command because VCS is disabled.

Message Type DCE

Severity INFO

Probable Cause Indicates inability to run the TRILL OAM (TOAM) commands because VCS is disabled.

Recommended To run the TOAM commands, enable VCS using the **vcs enable** command.

Action

TOAM-1003

Message Initilization error: <reason>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that TRILL OAM (TOAM) has encountered an error during initialization.

Recommended Reload or power cycle the switch.

TRCE Messages

TRCE-1002

Message

Trace dump<optional slot indicating on which slot the dump occurs> automatically transferred to address ' <FTP target designated by user> '.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that a trace dump has occurred on the switch or the specified slot, and the trace dump files were automatically transferred from the switch to the specified FTP server.

Recommended

Action

No action is required.

TRCE-1003

Message

Trace dumpoptional slot indicating on which slot the dump occurs> was not transferred due to FTP error.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that a trace dump has occurred on the switch or the specified slot, but the trace dump files were not automatically transferred from the switch due to reasons such as an FTP error, wrong FTP address, FTP site is down, and network is down.

Recommended

Action

If the message persists, execute the copy support command and contact your switch service provider.

TRCE-1005

Message

FTP Connectivity Test failed due to error.

Message Type

LOG

Severity

ERROR

Probable Cause

Indicates that the connectivity test to the FTP host failed because of reasons such as a wrong FTP address, FTP site is down, or network is down.

Recommended

Action

Execute the **copy support** command and contact your switch service provider.

TRCE-1006

Message FTP Connectivity Test succeeded to FTP site ' <FTP target configured by users> '.

Message Type LOG

Severity INFO

Probable Cause Indicates that a connectivity test to the FTP host has succeeded.

Recommended No action is required.

Action

TRCE-1007

Message Notification of this MM has failed. Parameters temporarily out of sync with other

 $\ensuremath{\mathsf{MM}}$.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the active management module was unable to alert the standby management module of a

change in the trace status. This message is only applicable to modular switches.

Recommended This message is often transitory. Wait a few minutes and try the command again.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

TRCE-1008

Message Unable to load trace parameters.

Message Type FFDC | LOG

Severity CRITICAL

Probable Cause Indicates that the management module is unable to read the stored trace parameters.

Recommended Reload the switch or the chassis.

Action If the message persists, execute the **copy support** command and contact your switch service provider.

TRCE-1009

Message Unable to alert active MM that a dump has occurred.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the standby management module is unable to communicate trace information to the active

management module. This message is only applicable to modular switches.

Recommended Execute the show ha command to verify that the current management module is standby and the active

Action management module is active.

If the message persists, execute the **copy support** command and contact your switch service provider.

TRCE-1010

Message Traced fails to start.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the trace daemon (traced), which is used for transferring the trace files has failed to start.

The trace capability within the switch is unaffected. The system automatically restarts the traced facility

after a brief delay.

Recommended If the message persists, reload the switch or the chassis.

Action Execute the **copy support** command and contact your switch service provider.

TRCE-1011

Message Trace dump manually transferred to target ' <optional string to indicate which

slot the trace dump is transferred> ': <result>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the trace dump files were transferred manually to the specified slot.

Recommended No action is required.

TRCE-1012

Message The system was unable to retrieve trace information from slot <Slot number of the

interface module on which the attempt was made>.

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates that the system was unable to retrieve trace information from the specified slot because there is

no communication between the main system and the slot.

Recommended Check that the interface module is enabled and retry the command. If the interface module is already

enabled, execute the copy support command and contact your switch service provider.

TS Messages

TS-1002

Message

<Type of clock server used> Clock Server used instead of <Type of clock server
configured>: locl: 0x<Reference ID of LOCL> remote: 0x<Reference ID of external
clock server>.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that the switch time synchronization was sourced from an alternate clock server instead of the configured clock server. The clock server used can be one of the following type:

- LOCL Local switch clock.
- External External Network Time Protocol (NTP) server address configured.

This message may be logged during temporary operational issues such as IP network connection issues to the external clock server. If the message does not recur, it can be ignored.

Recommended

Action

Execute the **show ntp status** command to verify that the switch clock server IP address is configured correctly. Verify if this clock server is accessible to the switch and functional. If it is not accessible or functional, configure an accessible and functional clock server or reset the clock server to local clock server (LOCL).

TS-1008

Message

<New clock server used> Clock Server used instead of <Old server configured>.

Message Type

LOG

Severity

INFO

Probable Cause

Indicates that the source of switch time synchronization was changed to another configured clock server because the Network Time Protocol (NTP) query to the current active external clock server failed.

Recommended

Action

No action is required. New clock server synchronization will adjust the clock time.

UCST Messages

UCST-1003

Message Duplicate Path to RBridge <RBridge ID>, Output Port = <port number>, PDB pointer =

0x<value>.

Message Type LOG

Severity INFO

Probable Cause Indicates that duplicate paths were reported to the specified RBridge from the output port. The *PDB*

pointer value displayed in the message is the address of the path database (PDB) and provides

debugging information.

Recommended

Action

No action is required.

UPTH Messages

UPTH-1001

Message No minimum cost path in candidate list.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the switch is unreachable because no minimum cost path (MPATH) exists in the candidate

list (RBridge ID list).

Recommended No action is required. This error will end the current shortest path first (SPF) computation.

VC Messages

VC-1000

Message vCenter <vCenterName> configuration is added.

Message Type LOG

Severity INFO

Probable Cause Indicates that a new vCenter configuration was added.

Recommended No action is required.

Action

VC-1001

Message vCenter <vCenterName> configuration is changed.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified vCenter configuration has been updated.

Recommended No action is required.

Action

VC-1002

Message vCenter <vCenterName> configuration is deleted.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified vCenter configuration has been deleted.

Recommended No action is required.

VC-1003

Message vCenter <vCenterName> configuration has been activated successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified vCenter configuration has been activated.

Recommended No action is required.

Action

VC-1004

Message vCenter <vCenterName> configuration has been deactivated successfully.

Message Type LOG

Severity INFO

Probable Cause Indicates that the specified vCenter configuration has been deactivated.

Recommended No action is required.

Action

VC-1005

Message Login to vCenter <vCenterName> failed (attempt(s) <failedAttempts>) - check

credentials for user <userName>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the vCenter login failed due to invalid credentials.

Recommended Enter the correct username and password for the vCenter.

7 vc-1006

VC-1006

Message vCenter <vCenterName> periodic discovery interval has been changed to <interval>

minutes.

Message Type LOG

Severity INFO

Probable Cause Indicates that the periodic discovery timer interval has been changed for the specified vCenter.

Recommended No action is required.

VCS Messages

VCS-1001

Message

Event: VCS cluster create, Coordinator IP: <Coordinator's Public IP>, VCS ID: <VCS Id>, Status: <Cluster status>.

Message Type

LOG | VCS

Severity

INFO

Probable Cause

Indicates that the VCS cluster has been created.

Distributed Configuration Manager (DCM): The initial VCS enable and configuration distribute on two or more nodes where a VCS cluster of the same VCS ID did not exist before.

Fabric Distribution Service (FDS): The initial VCS enable on two or more nodes with the same VCS ID where a VCS cluster of the same VCS ID did not exist before.

Recommended

Action

No action is required.

VCS-1002

Message

Event: VCS cluster create, Coordinator IP: <Coordinator's Public IP>, VCS ID: <VCS Id>, Status: VCS cluster failed to be created, Reason: <Error Reason>.

Message Type

LOG | VCS

Severity

ERROR

Probable Cause

Indicates that the VCS cluster failed to be created. Refer to the reason code for the cause of the error.

Recommended

Action

Refer to reason code for possible action.

VCS-1003

Message

Event: VCS node add, Coordinator IP: <Coordinator's Public IP>, VCS ID: <VCS Id>, Status: rBridge ID <RBridge-id of Added Switch> (<IP of Added Switch>) added to VCS cluster.

Message Type

LOG | VCS

Severity

INFO

Probable Cause

Indicates that a node has been added to the VCS cluster. The node was added due to one of the following conditions:

 Distributed Configuration Manager (DCM): VCS is enabled on a node that was not a member of the VCS cluster.

7 VCS-1004

 Fabric Distribution Service (FDS): VCS is enabled on a node that was not a member of the VCS cluster, or the node rejoined the VCS cluster after the **reload** command was issued, or the interswitch link (ISL) was toggled.

Recommended

No action is required.

Action

VCS-1004

Message

Event: VCS node add, Coordinator IP: <Coordinator's Public IP>, VCS ID: <VCS Id>, Status: rBridge ID <RBridge-id of Switch That Failed To Be Added> (<IP of Switch That Failed To Be Added>) failed to be added to VCS cluster, Reason: <Error Reason>.

Message Type

LOG | VCS

Severity

ERROR

Probable Cause

Indicates that a node failed to be added to the VCS cluster. Refer to the reason code for the cause of the error.

Recommended

Action

Refer to reason code for possible action.

VCS-1005

Message

Event: VCS node rejoin, Coordinator IP: <Coordinator's Public IP>, VCS ID: <VCS Id>, Status: rBridge ID <RBridge-id of Rejoined Switch> (<IP of Rejoined Switch>) rejoined VCS cluster.

Message Type

LOG | VCS

Severity

INFO

Probable Cause

Indicates that the Distributed Configuration Manager (DCM) node has gone offline and returned online without any configuration changes.

Recommended

No action is required.

VCS-1006

Message Event: VCS node rejoin, Coordinator IP: <Coordinator's Public IP>, VCS ID: <VCS

Id>, Status: rBridge ID <RBridge-id of Switch That Failed To Rejoin> (<IP of Switch That Failed To Rejoin>) failed to rejoin VCS cluster, Reason: <Error

Reason>.

Message Type LOG | VCS

Severity ERROR

Probable Cause Indicates that the Distributed Configuration Manager (DCM) node has failed to rejoin the existing VCS

cluster. Refer to the reason code for the cause of the error.

Recommended Refer to reason code for possible action.

Action

VCS-1007

Message Event: VCS node remove, Coordinator IP: <Coordinator's Public IP>, VCS ID: <VCS

Id>, Status: rBridge ID <RBridge-id of Removed Switch> (<IP of Removed Switch>)

removed from VCS cluster.

Message Type LOG | VCS

Severity INFO

Probable Cause Indicates that VCS is disabled on the node that was part of a VCS cluster.

Recommended No action is required.

Action

VCS-1008

Message Event: VCS node remove, Coordinator IP: <Coordinator's Public IP>, VCS ID: <VCS

Id>, Status: rBridge ID <RBridge-id of Switch That Failed To Be Removed> (<IP of Switch That Failed To Be Removed>) failed removal from VCS cluster, Reason: <Error

Reason>.

Message Type LOG | VCS

Severity ERROR

Probable Cause Indicates that a Distributed Configuration Manager (DCM) node failed to be removed from the VCS

cluster. Refer to the reason code for the cause of the error.

Recommended Refer to reason code for possible action.

VCS-1009

Message Event: VCS node disconnect, Coordinator IP: <Coordinator's Public IP>, VCS ID:

<VCS Id>, Status: rBridge ID <RBridge-id of Switch That Disconnected> (<IP of

Switch That Disconnected >) disconnected from VCS cluster.

Message Type LOG | VCS

Severity INFO

Action

Probable Cause Indicates that the heartbeat loss to a secondary node occurred because the node was reloaded or all

interswitch links (ISLs) to the secondary node are down.

Recommended If you had issued the reload command, no action is required. If for another reason, check the state of the

disconnected node and the ISLs to the disconnected node.

VRRP Messages

VRRP-1001

Message <message>: <message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the system has failed to allocate memory.

Recommended Check the memory usage on the switch using the **show process memory** command.

Action Reload or power cycle the switch.

VRRP-1501

Message <message>: <message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates that the system has failed to initialize.

Recommended Reload or power cycle the switch.

Action

VRRP-2001

Message <message>: <message>.

Message Type DCE

Severity ERROR

Probable Cause Indicates a connection, transfer, or receiving error in the socket.

Recommended If this is a modular switch, execute the ha failover command. If the problem persists or if this is a

Action compact switch, download a new firmware version using the **firmware download** command.

WLV Messages

WLV-1001

Message Port <port number> port fault. Change the SFP transceiver or check cable.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates a deteriorated small form-factor pluggable (SFP) transceiver, an incompatible SFP transceiver

pair, or a faulty cable between the peer ports.

Recommended Verify that compatible SFP transceivers are used on the peer ports, the SFP transceivers have not

deteriorated, and the Fibre Channel cable is not faulty. Replace the SFP transceivers or the cable, if

necessary.

WLV-1002

Message Port <port number> chip faulted due to internal error.

Message Type LOG | FFDC

Severity ERROR

Probable Cause Indicates an internal error. All the ports on the interface module or switch will be disrupted.

Recommended For a modular switch, execute the **power-off** and **power-on** commands to power cycle the interface

Action module.

For a compact switch, reload or power cycle the switch.

WLV-1003

Message Port <port number> faulted due to excessive link flapping. Check the SFP

transceiver/cable and issue shutdown/no shutdown commands to recover.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates a deteriorated small form-factor pluggable (SFP) transceiver, an incompatible SFP transceiver

pair, or a faulty cable between the peer ports.

Recommended Verify that compatible SFP transceivers are used on the peer ports, the SFP transceivers have not

deteriorated, and the cable is not faulty. Replace the SFP transceivers or the cable, if necessary. Execute

the **shutdown** and **no shutdown** commands to restart the link up process.

ZONE Messages

ZONE-1010

Message Duplicate entries in zone (<zone name>) specification.

Message Type LOG

Severity WARNING

Probable Cause Indicates that there are duplicate entries in a zone object. A zone object member is specified twice in a

given zone object. This message occurs only when enabling a zone configuration.

Recommended Check the members of the zone and delete the duplicate member using the no member-zone

Action command.

ZONE-1014

Message Missing required license - cense name>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the required zoning license is missing.

Recommended Install the zoning license using the license add command. Contact your switch supplier to obtain a

Action zoning license if you do not have one.

ZONE-1015

Message Type LOG

Severity WARNING

Probable Cause Indicates that a zoning change operation was not allowed because the zoning transaction was opened

by another task. Indicates concurrent modification of the zone database by multiple administrators.

Recommended Wait until the previous transaction is completed. Verify that only one administrator is working with the

Action zone database at a time.

ZONE-1019

Message Transaction Commit failed. Reason code <reason code> (<Application reason>) -

\"<reason string>\".

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the reliable commit service (RCS) had a transmit error. RCS is a protocol used to transmit

changes to the configuration database within a fabric.

Recommended Often this message indicates a transitory problem. Wait a few minutes and retry the command.

Make sure your changes to the zone database are not overwriting the work of another administrator.

Execute the show zoning operation-info command to know if there is any outstanding transaction

running on the local switches.

If the message persists, execute the copy support command and contact your switch service provider.

ZONE-1022

Message The effective configuration has changed to <Effective configuration name>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the effective zone configuration has changed to the specified configuration name.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-1023

Message Switch connected to port (<port number>) is busy. Retrying zone merge.

Message Type LOG

Severity INFO

Probable Cause Indicates that the switch is retrying the zone merge operation. This usually occurs if the switch on the

other side of the port is busy.

Recommended If the message persists, execute the **copy support** command and contact your switch service provider.

Message <Information message>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the zoning enabled-configuration cfg-action cfg-save command was executed

successfully.

Recommended No action is required.

Action

ZONE-1027

Message Zoning transaction aborted <error reason>.

Message Type LOG

Severity INFO

Probable Cause Indicates that the zoning transaction was aborted because of one of the following conditions:

- Zone Merge Received: The fabric is in the process of merging two zone databases.
- Zone Config update Received: The fabric is in the process of updating the zone database.
- Bad Zone Config: The new configuration is not viable.
- Zoning Operation failed: A zoning operation failed.
- Shell exited: The command shell has exited.
- Unknown: An error was received for an unknown reason.
- User Command: A user aborted the current zoning transaction.
- Switch Shutting Down: The switch is currently shutting down.

Most of these error conditions are transitory.

Recommended Action

Try again after sometime. Verify that only one administrator is modifying the zone database at a time.

ZONE-1028

Message Commit zone DB larger than supported - <zone db size> greater than <max zone db

size>.

Message Type LOG

Severity WARNING

Probable Cause Indicates that the zone database size is greater than the limit allowed by the fabric. The limit of the zone

database size depends on the lowest level switch in the fabric. Older switches have less memory and

force a smaller zone database for the entire fabric.

Recommended Action

Edit the zone database to keep it within the allowable limit for the specific switches in your fabric. You can

view the zone database size information using the **show zoning operation-info** command.

ZONE-1029

Message Restoring zone cfg from flash failed - bad config saved to <config file name>

[<return code>].

Message Type LOG

Severity WARNING

Probable Cause Indicates that the zone configuration restored from the flash was faulty. This error will save the faulty

zone configuration in the zoned core file directory.

Recommended If the message persists, execute the **copy support** command and contact your switch service provider.

Action

ZONE-1032

Message RBridge <RBridge number> Max Zone DB size <max zone db size>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the specified RBridge does not have enough memory for the zone database being

committed.

Recommended Reduce the size of the zone database by deleting some zones and retry the operation. Refer to the

Network OS Administrator's Guide for instructions to delete a zone.

ZONE-1033

Message RBridge <RBridge number> Lowest Max Zone DB size.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the specified RBridge has the lowest memory available for the zone database in the fabric.

The zone database must be smaller than the memory available on this RBridge.

Recommended Reduce the size of the zone database by deleting some zones and retry the operation. Refer to the

Action Network OS Administrator's Guide for instructions to delete a zone.

Message A new zone database file is created.

Message Type LOG

Severity INFO

Probable Cause Indicates that a new zone database file has been created.

Recommended No action is required.

Action

ZONE-1035

Message Unable to rename <Old config file name> to <New config file name>: error message

<System Error Message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Network OS cannot rename the zone configuration file. Typically, the zone

configuration is too large for the memory available on the switch.

Recommended Reduce the size of the zone database by deleting some zones and retry the operation. Refer to the

Network OS Administrator's Guide for instructions to delete a zone.

ZONE-1036

Message Unable to create <config file name>: error message <System Error Message>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the Network OS cannot create the zone configuration file. Typically, the zone configuration

is too large for the memory available on the switch.

Recommended Reduce the size of the zone database by deleting some zones and retry the operation. Refer to the

Action Network OS Administrator's Guide for instructions to delete a zone.

ZONE-1037

Message Unable to examine <config file name>: error message <System Error Message>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the Network OS cannot examine the zone configuration file. Typically, the zone

configuration is too large for the memory available on the switch.

Recommended Reduce the size of the zone database by deleting some zones and retry the operation. Refer to the

Network OS Administrator's Guide for instructions to delete a zone.

ZONE-1038

Message Unable to allocate memory for <config file name>: error message <System Error

Message>.

Message Type LOG

Action

Severity ERROR

Probable Cause Indicates that the Network OS cannot allocate enough memory for the zone configuration file. Typically,

the zone configuration is too large for the memory available on the switch.

Recommended Reduce the size of the zone database by deleting some zones and retry the operation. Refer to the

Network OS Administrator's Guide for instructions to delete a zone.

ZONE-1039

Message Unable to read contents of <config file name>: error message <System Error

Message>.

Message Type LOG

Severity ERROR

Probable Cause Indicates that the Network OS cannot read the zone configuration file. Typically, the zone configuration is

too large for the memory available on the switch.

Recommended Reduce the size of the zone database by deleting some zones and retry the operation. Refer to the

Action Network OS Administrator's Guide for instructions to delete a zone.

Message Merged zone database exceeds limit.

Message Type LOG

Severity INFO

Probable Cause Indicates that the Network OS cannot read the merged zone configuration file. Typically, the zone

configuration is too large for the memory available on the switch.

Recommended Reduce the size of the zone database by deleting some zones and retry the operation. Refer to the

Network OS Administrator's Guide for instructions to delete a zone.

ZONE-1041

Message Unstable link detected during merge at port (<Port number>).

Message Type LOG

Action

Severity WARNING

Probable Cause Indicates a possible unstable link or a faulty cable.

Recommended Verify that the small form-factor pluggable (SFP) transceiver and cable at the specified port are not faulty.

Action Replace the SFP transceiver and cable if necessary.

ZONE-1042

Message The effective configuration has been disabled.

Message Type LOG

Severity INFO

Probable Cause Indicates that the effective zone configuration has been disabled.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-1043

Message The Default Zone access mode is set to No Access.

Message Type LOG

Severity INFO

Probable Cause Indicates that the default zone access mode is set to No Access.

Recommended

Verify that the event was planned. If the event was planned, no action is required. If the event was not

planned, take appropriate action as defined by your enterprise security policy.

ZONE-1044

Message The Default Zone access mode is set to All Access.

Message Type LOG

Action

Severity INFO

Probable Cause Indicates that the default zone access mode is set to All Access.

Recommended Verify that the event was planned. If the event was planned, no action is required. If the event was not

Action planned, take appropriate action as defined by your enterprise security policy.

ZONE-1045

Message The Default Zone access mode is already set to No Access.

Message Type LOG

Severity INFO

Probable Cause Indicates that the default zone access mode is already set to No Access.

Recommended No action is required.

Action

ZONE-1046

Message The Default Zone access mode is already set to All Access.

Message Type LOG

Severity INFO

Probable Cause Indicates that the default zone access mode is already set to All Access.

Recommended No action is required.